

aruna@modiproperties.com

From: "Soham Modi" <sohammodi@modiproperties.com>
Date: 28-06-2019 10:37 AM
To: "Aruna" <aruna@modiproperties.com>
Attach: C block sump.jpg
Subject: Fw: Fwd: "C" & "A" block sump mud water issue

Print

Regards,
 Soham Modi

From: paramount.avenue@gmail.com
Sent: 28 June 2019 9:46 AM
To: shirish@modiproperties.com
Cc: sohammodi@modiproperties.com
Subject: Fwd: "C" & "A" block sump mud water issue

Dear Sir,

Please go through the forwarded email received from Mr. Ramesh Patel, Flat No: 721. We request you to please do the needful.

Thanks & Regards,

PAOA EC-Members

----- Forwarded message -----

From: **Ramesh Patel** <patelmfinance@gmail.com>
Date: Fri, Jun 28, 2019 at 7:59 AM
Subject: "C" & "A" block sump mud water issue
To: Paramount Avenue <paramount.avenue@gmail.com>

Dear ECM

we are facing issue with muddy water during raining this is because A & C block sump is located inside the planted trees when rain comes all the muddy water goes inside the sump and it is getting pumped in the over head tanks. with this water is getting wasted because it can't be used, the height of the sump should be increased to arrest this problem. It is affecting our children's health already my son is facing itching problem. here attached with some snapshot of the sump how muddy water is going inside the sump when it is raining. Please try to resolve the issue as soon as possible.



Ramesh Kumar Patel
 Hyderabad

Cell No: 9848217320

28-06-2019

