Remarks from site on the 'Requisition by Site Report of purchase division

Company:		VISTA HOMES				Date:			18.07.20			
Site:		VISTA HOMES				Prepar	Prepared by:			CH.Sneha Priya		
Report From / To 11.			07.20 (Saturday) to 18.07.20 (turday)			_	ved by:			T.MADHU		
Report Date		18.07.	4/									
List of requis	sitions nu	110000000000000000000000000000000000000		n the ren	ort*-9967	99716						
List of requis	sitions w	here PC)/WO not	nrenared	3 worki	ng days	after rea	nicition:				
Req No.	Req Date											
99576	21.05.20				Item Description 82.5 KVA generator			Reason for not preparing PO/WO				
99646	18.06.20				Door closer Door locks			Estimate with MD approval Po Not made				
99647	18.06.20								Po Not made			
99671	26.06.20				MS Round plates Cue Sticks		CS	Po Not made Po Not made				
99687	30.06.20		10		Coconut oil							
99706	02.07.20		1&4		UPS			Partially material PO Not made				
99717	10.07.20		1604		GIUcl	amne		Partially material PO Not made				
99718	10.07.20				GI rour	The state of the s			Po Not made Po Not made			
			/WO is n	repared a			hoon wo	PO NO	i made		1.1	
Req No.	Req No. Req Date		Serial no of item in Req.		Iten	Item Description		Details of discussion with supplier				
99622	06.06.20		9		GI wire			Material Ready with Supplier				
99680	29.06.	20	1 to 40		PVC &	CPVC I	External	Partial	ly Rec	eived by	SSLIP	
99681	29.06.	20	1&2		SS Sink Waste couplin			Partially Received by SSLLP Material Ready with SSLLP				
99682	29.06.20		2 & 3		Wooden Screws & Fishers			Material Ready with Supplier				
99696	01.07.	01.07.20		12		GI Pipe			Material Ready with Supplier			
99697	01.07.20		9		GI Pipe				Material Ready with Supplier			
99698	01.07.20		6		GI Pipe			Material Ready with Supplier				
99701	01.07.20		2		Loft Tank			Material Ready with SSLLP				
99702	01.07.20		3 & 4		Door Beading			Material Ready with SSLLP				
99706	02.07.20		1 to 4		UPS			Partially Received by SSLLP				
99710	07.07.20		To the	Armour		Cable		Material Ready with Supplier				
99713	09.07.20				Split A			Material Ready with Supplier Material Ready with Supplier				
9715	10.07.20		1 to 10		Cleaning Material			Partially Received by SSLLP				
9721	10.07.20		2		Wipro Granet light		Partially Received by SSLLP					
9722	13.07.20		1 to 6		MS Square Pipe		-	Material Ready with SSLLP				
9723	14.07.20		1		MCCB L&T		Material Ready with Supplier					
9725	14.07.20		1 to 6		Sliding Windows		Material Ready with Supplier Material Ready with SSLLP					
9726		14.07.20		1 to 7		Grills			Material Ready with SSLLP			
No. of gate passes issued this wee					02 From No.			1615 To No. 1616				
Delivery van site visit on:					14.07.20	0,17.07.	.20		TO NO.	1 1010		
nward report	(MRN/o	ther) &	stock rep	ort emai	led in pdf	format t	o purcha	ase?		Ye	S	
OC register Sl. No. during the week From								To No.				
tems not orde						Le la la			2"-1			
tems sent to I rump 2 HP se	IO /vend	lor that	are pendi	ng for re	pair:-1.(1	0599)Au	to Curte	r Motor S	Sent to	Satish.2.(1	0643) Mud	
Other correction	ons & re	marks:							150			
Details			Project Manager			Admin Officer/M		Manager	Admin Audit			
Sign			Hault	aneliap		_ 1	Tie	Admin Addit				
1511	ate		I LAAA			Or M	1/10 1	Dal . A				

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!