

sohammodi@modiproperties.com

From: Narender Reddy <narender@modiproperties.com>
Sent: 02/02/2018 12:41 PM
To: Soham Modi
Cc: Nilgiri Estates
Subject: Tot lot level check-NE

MD sir,

We have checked the levels at the NE tot lot area. There is difference of 6" down than the FFL given is coming were GSB is laid at east to club L-shape area and swimming pool deck area and 2" down coming at the club house set backs. We are the removing the GSB and filling up with the morrum at the club house east side L-shape area.

with regards

K. Narender Reddy