QC Audit Report

Date		22-08-2018		Prepared by P.Sai Kum			
Project		NILGIRI ESTATES					
For month beginning date 22.07.18				Company	NILGIRI ESTATES		
SI No.	Dilling date 21.0					.08.18	
1.	Description Are all plans filed as per Internal memo no. 917/5? Are provision 6					Remarks	
2.	Are provision for curing adequate?					Yes	
3.	Is temporary closed by					£ .	
	Is temporary electrical points for construction provided on each						
4.	is temporary electric nower connection					Yes	
5.	sq mm cable and DBs?					Yes	
6.	Are DBs for temporary electrical power connection locked? Is power connection in 1-1.						
7.	The connection in labour quarters					No	
/.	Is curing being done for 21 days (check procedure and enquire with workers)?					Yes	
3.	workers)? Is proportion 1					No	
	Is proportion box being used (check availability and enquire with					Yes	
).	No. of recron packets consumed during the month?					i es	
0.	Are safety belts and helmets regularly used?					106	
1.	Are CC cubes being sent for testing regularly?					NA	
2.	Any default in proceed:					No	
	Any default in proceeding with work without QC inspection at any stage? Give details					No	
<u></u>	Recommendation for imposition of 5.					. 10	
4.	lo. of co	nsultants visi	ts. Enclose soon	nes as per circular no.	607(a).	-	
omment	s:			nes as per circular no. ned copy of consulta	nts report.	_	
ıggestio:	ns: New	V joined Eng	incore and c	an (Engineer) also ha			
d Forma	its.	- 1- med Bilk	meers and Srav.	an (Engineer) also ha	s to read all OC	Reports	
)mplaint • numb-	s: Curin	g Photos not	Sending Regula	rly by Site-Engineers			
- numbe	r of time	s intimated to	them.	of one-engineers	and Project Ma	nager as	

Notes: 1. Report to be submitted once a month for each site. 2. Sites include PMRII, Vista, MNM. SOB III. GWE, KNM, Mehdi and other new sites. 3. Report must be send by email to M.D. and project manager in PDF format. 4. Confidential comments may be sent to M.D. by separate email. 5. Include photographs whenever necessary.