

Regarding pressure at villa No.117 curing pipe Tuesday, 5 Jun 2018, 12:28 pm

To: Soham Modi <sohammodi@modiproperties.com>
From: Nilgiri Estates <nilgiriestate@modiproperties.com>
Cc: Madhusudhan Eng <madhusudhan@modiproperties.com>

Respected sir,

I have checked the pressure of curing pipe. there is in proper connection at HDPE pipe (loose contact) that purpose there is leakage at pipe joint. problem is rectified and pressure is coming properly.

Regards
M.Madhusudhan