Remarks from site on the 'Requisition by Site Report' of purchase division

Company: N		Modi re	alty Mallapur	Date:		03.10.2020				
			ar residency	Prepared by:		M.Likhitha				
			09.2020 to 03.10.20		Approved by:		Ram Prasad			
			to Saturday)							
Report Date 03.10.2			-	Billia						
List of reau	isition	ns number	rs missing in	the repo	ort*: 68453, 684	454,6	8455 .			
List of requ	uisition	ns where	PO/WO not p	repared	3 working day	s after	requisition:			
Req No.			S.no	Item Description		Reason for not preparing PO/WO*				
68381	28.08.2020		2	UPS		Online Purchase				
68424	17-09-2020		1-3	SS Railing		Delay by purchase assistant.				
68435	21.09.20		7 & 10	GP2 cement & Arment rearm bond.		Delay by purchase assistant.				
68445	28.09.20		8-13	Sanitary		Dela	Delay by purchase assistant.			
68446	28.09.20		1 to 3	Tiles		Dela	Delay by purchase assistant.			
68447	28.09.20		1,2	Spray paints		Dela	Delay by purchase assistant.			
lead time: Req No.		eq Date	Serial no of item in Req.	Item Description		Details of discussion with supplier				
68363	31.0	07.2020	1	Hollow bricks		PO	PO NO – 69346.(pending -500)			
68376		08.2020	1	Cement		PO NO - 69850 . partly receiving no stock at SSLLP				
68383	29.	08.2020	1	False ceiling		PO	PO No - 70032 . contractor started the work .			
68398	03.09.2020		1	False ceiling		PO	PO No - 70032 . contractor started the work .			
68415	16.09.2020		1	PVC pipe		PO	PO No - 70518, Ready with supplier (90% received)			
68422	16-	09-2020	1	Cement Blocks.			No - 70508, partly receiving			
68425		09-2020	1,3&5	Grills		PO	PO No - 70577. Supplier arranging for material.			
68426	18-	09-2020	1	Grass Carpet		PO	PO No - 70566.Supplier arranging for material.			
68429	21-09-2020		2	Vitrified tiles 2'X2'		PO No - 70618. No stock at vista, BNC sites.				
68436	23.	-09-2020	4	Clamshell cards		PO No - 70714, no stock at SSLLP				
68437	24.09.20		2 to 8	Star screws & Araldite .		PO	PO - 70843, 70842. Material in transits.			
	28.09.20			Janata paste		LIGHT	ISIIS			
68442	20	00.20	2,3	11/2/17/05-25/05	Participation of the second of		no - 70897 . SSLLP store is			

				a silv		close	d.		
68443	28.09.20	1,3,5,	6,7	Wires		PO no - 70834 . SSLLP store is closed .			
68448	28.09.20	1 to 4		Flush	doors	PO no - 70875 . SSLLP store is closed .			
No. of gate passes issued this week:				02	From No.		1///		1775
	van site visit o				.20 (Tuesday) rday).	, 01.1	0.20 (Th		y) & 03.10.20
Inward re		ner) & sto	ock rep	ort ema	niled in pdf form	nat to			Yes
				n No.	916	To No.	To No. 928		
Items not	ordered but re	ceived: r	nil			1	3-13-14-13		
Items sen	nt to HO /vendo	or that are	e pendi	ing for 1	repair: 03 motor	s (Dev	vatering pu	imps	2HP)
Other con	rrections & ren	narks:							
Details		Project Manag			ger Admin Officer/Mana		Admir	Admin Audit	
Sign	EN EX LA ME	Ly	0		Samani	4			
Date		03	110/23	0	3 00	100			1 /1.

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report ashaiya@modiproperties.com purchase@modiproperties.com, rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks - For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, 9. Purchase to send reply to Delay by purchase assistant, Supplier arranging for material, this report within one week. 10. Follow up for WO is the responsibility of engineers at site purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up - DO NOT CALL PURCHASE!