

BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59164	Gulmohar Residency	B	205	1660	Sree Srinivasa constructions	Rcc Slab-4	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50dd240efc.pdf	Towards slab workdone for flat no - 205 atB-Block . bill inward nois 125 .
59167	Gulmohar Residency	B	208	1660	Sree Srinivasa constructions	Rcc Slab-4	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50e5b56f6f.pdf	Towards slab work done for flat no - 208 at B-Block . bill inward no is 125 .
59691	Gulmohar Residency	A	202	1360	Surasani Constructions Pvt Ltd	Rcc Slab-4	269.7	366,792	30 Dec 2020		30 Dec 2020	INR	doc_5fec1a222a484.pdf	Towards RCC-slab 4 work done for flat no 202 at A-Block . bill inward no is 188.
59694	Gulmohar Residency	A	205	1360	Surasani Constructions Pvt Ltd	Rcc Slab-4	269.7	366,792	30 Dec 2020		30 Dec 2020	INR	doc_5fec1afa78f8c.pdf	Towards RCC-slab 4 work done for flat no 205 at A-Block . bill inward no is 188.
59697	Gulmohar Residency	A	208	1360	Surasani Constructions Pvt Ltd	Rcc Slab-4	269.7	366,792	30 Dec 2020		30 Dec 2020	INR	doc_5fec1bc10c5d8.pdf	Towards RCC-slab 4 work done for flat no 208 at A-Block . bill inward no is 188.
59162	Gulmohar Residency	B	203	1660	Sree Srinivasa constructions	Rcc Slab-4	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50d5755036.pdf	Towards slab work done for flat no - 203 at B-Block . bill inward no is 125 .
59165	Gulmohar Residency	B	206	1660	Sree Srinivasa constructions	Rcc Slab-4	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50e0087254.pdf	Towards slab work done for flat no - 206 at B-Block . bill inward no is 125 .
59692	Gulmohar Residency	A	203	1360	Surasani Constructions Pvt Ltd	Rcc Slab-4	269.7	366,792	30 Dec 2020		30 Dec 2020	INR	doc_5fec1a6128e0b.pdf	Towards RCC-slab 4 work done for flat no 203 at A-Block . bill inward no is 188.

APPROVED BY
 12 JAN 2021
 M. RAM PRASAD
 PROJECT MANAGER

BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59695	Gulmohar Residency	A	206	1360	Surasani Constructions Pvt Ltd	Rcc Slab-4	269.7	366,792	30 Dec 2020		30 Dec 2020	INR	doc_5fec1b39a98ad.pdf	Towards RCC-slab 4 work done for flat no 206 at A-Block . bill inward no is 188.
59698	Gulmohar Residency	A	209	1360	Surasani Constructions Pvt Ltd	Rcc Slab-4	269.7	366,792	30 Dec 2020		30 Dec 2020	INR	doc_5fec1c214f08d.pdf	Towards RCC-slab 4 work done for flat no 209 at A-Block . bill inward no is 188.
59160	Gulmohar Residency	B	201	1660	Sree Srinivasa constructions	Rcc Slab-4	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50cf55dd02.pdf	Towards slab work done for flat no - 201 at B-Block . bill inward no is 125 .
59163	Gulmohar Residency	B	204	1660	Sree Srinivasa constructions	Rcc Slab-4	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50da7b42c5.pdf	Towards slab work done for flat no - 204 at B-Block . bill inward no is 125 .
59169	Gulmohar Residency	B	304	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50eea4885f.pdf	Towards slab work done for flat no - 304 at B-Block . bill inward no is 125 .
59191	Gulmohar Residency	B	302	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb62957e556.pdf	Towards RCC Slab 5 work done for flat no 302 at B-Block . bill inward no is 133.
59170	Gulmohar Residency	B	305	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50f15f3a8a.pdf	Towards slab work done for flat no - 305 at B-Block . bill inward no is 125 .
59192	Gulmohar Residency	B	307	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb62f47e4cb.pdf	Towards RCC Slab 5 work done for flat no 307 at B-Block . bill inward no is 133.



BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59168	Gulmohar Residency	B	303	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50e9b809d9.pdf	Towards slab workdone for flat no 303 atB-Block . bill inward nois 125 .
59171	Gulmohar Residency	B	306	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	18 Nov 2020		01 Jan 1970	INR	doc_5fb50f4108944.pdf	Towards slab work done for flat no - 306 at B-Block . bill inward no is 125 .
59190	Gulmohar Residency	B	301	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb623fe8b35.pdf	Towards RCC Slab 5 work done for flat no 301 at B-Block . bill inward no is 133.
59193	Gulmohar Residency	B	308	1660	Sree Srinivasa constructions	Rcc Slab-5	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb63302cd39.pdf	Towards RCC Slab 5 work done for flat no 308 at B-Block . bill inward no is 133.
59149	Gulmohar Residency	B	404	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,757	18 Nov 2020		01 Jan 1970	INR	doc_5fb508d3f0af5.pdf	Towards rcc columns work done for flat no - 404 at B-Block . bill inward no is 125 .
59200	Gulmohar Residency	B	407	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb67a8a2d73.pdf	Towards RCC Col 6 work done for flat no 407 at B-Block . bill inward no is 133.
59150	Gulmohar Residency	B	405	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,757	18 Nov 2020		01 Jan 1970	INR	doc_5fb509090a45d.pdf	Towards rcc columns work done for flat no - 405 at B-Block . bill inward no is 125 .
59198	Gulmohar Residency	B	401	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb66d5c5376.pdf	Towards RCC Col 6 work done for flat no 401 at B-Block . bill inward no is 133.

APPROVED BY

12 JAN 2021
 M. RAM PRASAD
 PROJECT MANAGER

BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59201	Gulmohar Residency	B	408	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb67db1da84.pdf	Towards RCC Col 6 work done for flat no 408 at B-Block . bill inward no is 133.
59148	Gulmohar Residency	B	403	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,757	18 Nov 2020		01 Jan 1970	INR	doc_5fb5089daf6c6.pdf	Towards rcc columns work done for flat no - 403 at B-Block . bill inward no is 125 .
59151	Gulmohar Residency	B	406	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,757	18 Nov 2020		01 Jan 1970	INR	doc_5fb509c0830c5.pdf	Towards rcc columns work done for flat no - 406 at B-Block . bill inward no is 125 .
59199	Gulmohar Residency	B	402	1660	Sree Srinivasa constructions	RCC-Col 6	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb67352aed5.pdf	Towards RCC Col 6 work done for flat no 402 at B-Block . bill inward no is 133.
59202	Gulmohar Residency	B	503	1660	Sree Srinivasa constructions	RCC-Col 7	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb685327a12.pdf	Towards RCC Col 7 work done for flat no 503 at B-Block . bill inward no is 133.
59205	Gulmohar Residency	B	506	1660	Sree Srinivasa constructions	RCC-Col 7	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb699107c28.pdf	Towards RCC Col 7 work done for flat no 506 at B-Block . bill inward no is 133.
59514	Gulmohar Residency	B	507	1660	Sree Srinivasa constructions	RCC-Col 7	86.0	142,743	21 Dec 2020		21 Dec 2020	INR	doc_5fe02486a151d.pdf	Towards RCC col7 work done for flat no 507 at B-Block . bill inward no is 170.
59203	Gulmohar Residency	B	504	1660	Sree Srinivasa constructions	RCC-Col 7	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb6916e005d.pdf	Towards RCC Col 7 work done for flat no 504 at B-Block . bill inward no is 133.

APPROVED BY
 12 JAN 2021
 M. RAM PRASAD
 PROJECT MANAGER

BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59512	Gulmohar Residency	B	501	1660	Sree Srinivasa constructions	RCC-Col 7	85.9	142,594	21 Dec 2020		21 Dec 2020	INR	doc_5fe0237dd8043.pdf	Towards RCC col7work done for flat no501 at B-Block . billinward no is 170.
59515	Gulmohar Residency	B	508	1660	Sree Srinivasa constructions	RCC-Col 7	86.0	142,743	21 Dec 2020		21 Dec 2020	INR	doc_5fe024d175e95.pdf	Towards RCC col7 work done for flat no 508 at B-Block . bill inward no is 170.
59204	Gulmohar Residency	B	505	1660	Sree Srinivasa constructions	RCC-Col 7	86.0	142,743	23 Nov 2020		01 Jan 1970	INR	doc_5fbb6947a8cea.pdf	Towards RCC Col 7 work done for flat no 505 at B-Block . bill inward no is 133.
59513	Gulmohar Residency	B	502	1660	Sree Srinivasa constructions	RCC-Col 7	85.9	142,594	21 Dec 2020		21 Dec 2020	INR	doc_5fe023c5acd98.pdf	Towards RCC col7 work done for flat no 502 at B-Block . bill inward no is 170.
59213	Gulmohar Residency	B	402	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbbab5f322a2.pdf	Towards slab 6 work done for flat no 402 at B-Block . bill inward no is 137.
59194	Gulmohar Residency	B	403	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb6379e4886.pdf	Towards RCC Slab 6 work done for flat no 403 at B-Block . bill inward no is 133.
59197	Gulmohar Residency	B	406	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb65f8066a8.pdf	Towards RCC Slab 6 work done for flat no 406 at B-Block . bill inward no is 133.
59214	Gulmohar Residency	B	407	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbbab91595e4.pdf	Towards slab 6 work done for flat no 407 at B-Block . bill inward no is 137.

APPROVED BY

12 JAN 2021

M. RAM PRASAD
PROJECT MANAGER

BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59195	Gulmohar Residency	B	404	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb63a9e4524.pdf	Towards RCC Slab 6 work done for flat no 404 at B-Block . bill inward no is 133.
59212	Gulmohar Residency	B	401	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbbab0399455.pdf	Towards slab 6 work done for flat no 401 at B-Block . bill inward no is 137.
59215	Gulmohar Residency	B	408	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbbabc27fcec.pdf	Towards slab 6 work done for flat no 408 at B-Block . bill inward no is 137.
59196	Gulmohar Residency	B	405	1660	Sree Srinivasa constructions	RCC-Slab 6	258.0	428,252	23 Nov 2020		01 Jan 1970	INR	doc_5fbb640e21056.pdf	Towards RCC Slab 6 work done for flat no 404 at B-Block . bill inward no is 133.
59517	Gulmohar Residency	B	504	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe026161ae56.pdf	Towards RCC slab 7 work done for flat no 504 at B-Block . bill inward no is 170.
59520	Gulmohar Residency	B	501	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe02885cc248.pdf	Towards RCC slab 7 work done for flat no 501 at B-Block . bill inward no is 170.
59523	Gulmohar Residency	B	508	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe02950c160f.pdf	Towards RCC slab 7 work done for flat no 508 at B-Block . bill inward no is 170.
59518	Gulmohar Residency	B	505	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe02664dd35e.pdf	Towards RCC slab 7 work done for flat no 505 at B-Block . bill inward no is 170.

APPROVED BY
12 JAN 2021
M. JAM PRASAD
PROJECT MANAGER

BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59521	Gulmohar Residency	B	502	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe028d37c763.pdf	Towards RCC slab 7 work done for flat no 502 at B-Block . bill inward no is 170.
59516	Gulmohar Residency	B	503	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe025adb7697.pdf	Towards RCC slab 7 work done for flat no 503 at B-Block . bill inward no is 170.
59519	Gulmohar Residency	B	506	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe028441fb60.pdf	Towards RCC slab 7 work done for flat no 506 at B-Block . bill inward no is 170.
59522	Gulmohar Residency	B	507	1660	Sree Srinivasa constructions	RCC-Slab 7	258.0	428,252	21 Dec 2020		21 Dec 2020	INR	doc_5fe0291104b97.pdf	Towards RCC slab 7 work done for flat no 507 at B-Block . bill inward no is 170.
58915	Gulmohar Residency	Misc	Misc	31540	R.anjaiah	Rock Cutting	31.1	979,950	02 Nov 2020		01 Jan 1970	INR	doc_5f9ff42160b4a.pdf	Towards rock rope cutting work done at F-Block . bill inward no is 131 .
58824	Gulmohar Residency	B	104	1660	K.Krishna	Scaffolding	1.7	2,795	21 Oct 2020		01 Jan 1970	INR	doc_5f93ca8932fff.pdf	Towards scaffolding work done at B-104 & B-105 for plastering work . bill inward no is 129 .
59493	Gulmohar Residency	B	106	1660	K.Krishna	Scaffolding	6.0	9,975	15 Dec 2020		01 Jan 1970	INR	doc_5fd8ae6bdf508.pdf	Towards scaffolding work done for B-106 for toilet line water pipe line work purpose . inward no is 169.



BILLID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
58825	Gulmohar Residency	B	105	1660	K.Krishna	Scaffolding	7.5	12,500	21Oct 2020		01 Jan 1970	INR	doc_5f93ca43dd80d.pdf	Towards scaffolding work done forplastering work at Flatno B-105 .inward no is129.
59581	Gulmohar Residency	A	101	1360	K.Krishna	Scaffolding	7.4	10,062	21 Dec 2020		21 Dec 2020	INR	doc_5fe08be85869b.pdf	Towards double scaffolding work done for external plastering work done at A-Block flat no 101 . bill inward no is 174 .
59494	Gulmohar Residency	B	Misc	9040	K.Krishna	Scaffolding	0.6	5,040	15 Dec 2020		01 Jan 1970	INR	doc_5fd8aebae5.pdf	Towards scaffolding work done at B-block duct area for plastering work .in ward no is 169 .
59582	Gulmohar Residency	A	109	1360	K.Krishna	Scaffolding	7.4	10,062	21 Dec 2020		21 Dec 2020	INR	doc_5fe08c3a4aa5f.pdf	Towards double scaffolding work done for external plastering work done at A-Block flat no 109 . bill inward no is 174 .
59492	Gulmohar Residency	B	105	1660	K.Krishna	Scaffolding	9.5	15,750	15 Dec 2020		01 Jan 1970	INR	doc_5fd8ae03d7ad8.pdf	Towards scaffolding work done at B-105 for plastering work . bill inward no is 169.
59226	Gulmohar Residency	A	109	1360	Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	16.9	22,943	25 Nov 2020		01 Jan 1970	INR	doc_5fbdff02ab56b5.pdf	Towards Tiles fixing work done in flat no 109 A-Block . bill inward no is 140 .
59299	Gulmohar Residency	B	104	1660	Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	19.6	32,539	30 Nov 2020		01 Jan 1970	INR	doc_5fe48ee17a16e.pdf	Towards Flooring & bathroom tiles work done in B-104 . bill inward no is 151 enclosed.

BillID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency Code	Bill Document	Remarks
59227	Gulmohar Residency	A	101	1360	Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	19.6	26,609	25 Nov 2020		01 Jan 1970	INR	doc_5fbdff0a6d7347.pdf	Towards Tiles fixing work done in flat no101 A-Block . billinward no is 141 .
59300	Gulmohar Residency	B	105	1660	Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	16.8	27,910	30 Nov 2020		01 Jan 1970	INR	doc_5fc48f670ffeb.pdf	Towards tiles fixing work done at B-105 flat . bill inward no is 150 .
59362	Gulmohar Residency	A	101	1360	Vidya Shankar	Wooden false ceiling	20.7	28,206	03 Dec 2020		01 Jan 1970	INR	doc_5fca274591d49.pdf	Towards false ceiling work done for flat no 101 . bill dated on 02.12.20
59363	Gulmohar Residency	A	109	1360	Vidya Shankar	Wooden false ceiling	23.9	32,472	03 Dec 2020		01 Jan 1970	INR	doc_5fca276f7c7e9.pdf	Towards false ceiling work done for flat no 109 . bill dated on 02.12.20

*** The End ***

