

1st of Bills

Bill ID	Project Name	Block Num	Unit No	Unit Area	Contractor Name	Work Type Name	Rate	Bill Amount	Bill Date	Voucher Num	Voucher Date	Currency	Code	Bill Document	Remarks
59801	Gulmohar Residency	Misc		31540 Sai Venkateswara Borewell	Bore well		1	32,000	12-Jan-21		12-Jan-21 INR			doc_5f6d3a6f7d0ed.pdf	Towards bore well point digging work done in different depths of site. bill inward no is 216.
59802	Gulmohar Residency	Misc		31540 Sai Venkateswara Borewell	Bore well		13.7	432,245	12-Jan-21		12-Jan-21 INR			doc_5f6d3a4193c4.pdf	Towards bore well point digging work done in different depths of site. bill inward no is 220.
60842	Gulmohar Residency	Misc		31540 Sai Venkateswara Borewell	Bore well		0.9	28,540	16-Mar-21		16-Mar-21 INR			doc_60507c10d4a83.pdf	Towards borewell digging work done at GMR site. bill inward no is 246.
60596	Gulmohar Residency	A	102	1360 B Rambabu	Carpentry - Door heading		0.3	360	02-Mar-21		02-Mar-21 INR			doc_603a1354dd66d.pdf	A 102 Bill inward ID 282
60597	Gulmohar Residency	A	104	1360 B Rambabu	Carpentry - Door heading		0.3	360	02-Mar-21		02-Mar-21 INR			doc_603a131d1e760.pdf	A 104 Bill inward ID 282
60598	Gulmohar Residency	A	105	1360 B Rambabu	Carpentry - Door heading		0.3	360	02-Mar-21		02-Mar-21 INR			doc_603a1351d830f.pdf	A 105 Bill inward ID 282
60599	Gulmohar Residency	A	205	1360 B Rambabu	Carpentry - Door heading		0.3	360	02-Mar-21		02-Mar-21 INR			doc_603a1385ba723.pdf	A 205 Bill inward ID 282
59794	Gulmohar Residency	B	206	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4c4e4f9d6.pdf	Towards WPC door frames fixing work done for flat no 206 at B-Block. bill inward no is 206.
59795	Gulmohar Residency	B	207	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4a4a94e16.pdf	Towards WPC door frames fixing work done for flat no 207 at B-Block. bill inward no is 206.
59796	Gulmohar Residency	B	208	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4a7998c4b.pdf	Towards WPC door frames fixing work done for flat no 208 at B-Block. bill inward no is 206.
59797	Gulmohar Residency	B	301	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4d1704823.pdf	Towards WPC door frames fixing work done for flat no 301 at B-Block. bill inward no is 206.
59798	Gulmohar Residency	B	302	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4b3b7f0096.pdf	Towards WPC door frames fixing work done for flat no 302 at B-Block. bill inward no is 206.
59799	Gulmohar Residency	B	303	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e450c4346e.pdf	Towards WPC door frames fixing work done for flat no 303 at B-Block. bill inward no is 206.
59800	Gulmohar Residency	B	304	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4312286f1.pdf	Towards WPC door frames fixing work done for flat no 304 at B-Block. bill inward no is 206.
59801	Gulmohar Residency	B	305	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e41a0b8cee.pdf	Towards WPC door frames fixing work done for flat no 305 at B-Block. bill inward no is 206.
59802	Gulmohar Residency	B	306	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4156d0443.pdf	Towards WPC door frames fixing work done for flat no 306 at B-Block. bill inward no is 206.
59803	Gulmohar Residency	B	307	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4123c7d71.pdf	Towards WPC door frames fixing work done for flat no 307 at B-Block. bill inward no is 206.
59804	Gulmohar Residency	B	308	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e40d0f4d9.pdf	Towards WPC door frames fixing work done for flat no 308 at B-Block. bill inward no is 206.
59805	Gulmohar Residency	B	401	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e40b522e1.pdf	Towards WPC door frames fixing work done for flat no 401 at B-Block. bill inward no is 206.
59806	Gulmohar Residency	B	402	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e4081720d9.pdf	Towards WPC door frames fixing work done for flat no 402 at B-Block. bill inward no is 206.
59807	Gulmohar Residency	B	403	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e405454933.pdf	Towards WPC door frames fixing work done for flat no 403 at B-Block. bill inward no is 206.
59808	Gulmohar Residency	B	404	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e402d255a3.pdf	Towards WPC door frames fixing work done for flat no 404 at B-Block. bill inward no is 206.
59809	Gulmohar Residency	B	405	1660 B Rambabu	Carpentry - Door Frames		1.1	1,760	06-Jan-21		06-Jan-21 INR			doc_5f6e3a58a86.pdf	Towards WPC door frames fixing work done for flat no 405 at B-Block. bill inward no is 206.

15 APR 2021
M. RAM PRASAD
PROJECT MANAGER

59810	Gulimohar Residency	B	406	1660 B.Rambabu	1.760	06-Jan-21	INR	doc_5ff69f562d321.pdf	Towards WPC door frames fixing work done for flat no 406 at B-Block . bill inward no is 206
59811	Gulimohar Residency	B	407	1660 B.Rambabu	1.760	06-Jan-21	INR	doc_5ff69f42610f9.pdf	Towards WPC door frames fixing work done for flat no 407 at B-Block . bill inward no is 206
59812	Gulimohar Residency	B	408	1660 B.Rambabu	1.760	06-Jan-21	INR	doc_5ff69e847ea6f6.pdf	Towards WPC door frames fixing work done for flat no 408 at B-Block . bill inward no is 206
59813	Gulimohar Residency	A	301	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff59e87d4913.pdf	Towards WPC door frames fixing work done for flat no 301 at A-Block . bill inward no is 205
59814	Gulimohar Residency	A	302	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff59ed42638e.pdf	Towards WPC door frames fixing work done for flat no 302 at A-Block . bill inward no is 205
59815	Gulimohar Residency	A	303	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff59fe753b85.pdf	Towards WPC door frames fixing work done for flat no 303 at A-Block . bill inward no is 205
59816	Gulimohar Residency	A	304	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff59fa2936316.pdf	Towards WPC door frames fixing work done for flat no 304 at A-Block . bill inward no is 205
59817	Gulimohar Residency	A	305	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff5a075e7f22.pdf	Towards WPC door frames fixing work done for flat no 305 at A-Block . bill inward no is 205
59818	Gulimohar Residency	A	306	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff5a0a9df02c.pdf	Towards WPC door frames fixing work done for flat no 306 at A-Block . bill inward no is 205
59819	Gulimohar Residency	A	307	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff5a0d9d3ee5.pdf	Towards WPC door frames fixing work done for flat no 307 at A-Block . bill inward no is 205
59820	Gulimohar Residency	A	308	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff5a13d6df42.pdf	Towards WPC door frames fixing work done for flat no 308 at A-Block . bill inward no is 205
59821	Gulimohar Residency	A	309	1360 B.Rambabu	1.711	06-Jan-21	INR	doc_5ff5a1f16107e.pdf	Towards WPC door frames fixing work done for flat no 309 at A-Block . bill inward no is 205
60371	Gulimohar Residency	A	401	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b821b2bec71.pdf	Towards WPC door frames fixing work done for FLAT NO 401A-Block . bill inward no 265
60372	Gulimohar Residency	A	402	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b826b7a62.pdf	Towards WPC door frames fixing work done for FLAT NO 402 A-Block . bill inward no is 265
60373	Gulimohar Residency	A	403	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b82b54c236.pdf	Towards WPC door frames fixing work done for FLAT NO 403 A-Block . bill inward no is 265
60374	Gulimohar Residency	A	404	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b82fa5c983.pdf	Towards WPC door frames fixing work done for FLAT NO 404 A-Block . bill inward no is 265
60375	Gulimohar Residency	A	405	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b83287cf66.pdf	Towards WPC door frames fixing work done for FLAT NO 405 A-Block . bill inward no is 265
60376	Gulimohar Residency	A	406	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b8369c68cf.pdf	Towards WPC door frames fixing work done for FLAT NO 406 A-Block . bill inward no is 265
60377	Gulimohar Residency	A	407	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b83a90a473.pdf	Towards WPC door frames fixing work done for FLAT NO 407 A-Block . bill inward no is 265
60378	Gulimohar Residency	A	408	1360 B.Rambabu	1.540	16-Feb-21	INR	doc_602b83ff6a83b.pdf	Towards WPC door frames fixing work done for FLAT NO 408 A-Block . bill inward no is 265

6039	Gumohar Residency	A	429	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	16-Feb-21	16-Feb-21 INR	doc_60288432600da.pdf	Towards WPC door frames fixing work done for FLAT NO 409 A-Block. bill inward no is 295.
6039	Gumohar Residency	F	101	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	16-Feb-21	16-Feb-21 INR	doc_6028846b803as.pdf	Towards WPC door frames fixing work done for FLAT NO 101 F-Block. bill inward no is 295.
6039	Gumohar Residency	F	106	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	16-Feb-21	16-Feb-21 INR	doc_602884611c342.pdf	Towards WPC door frames fixing work done for FLAT NO 106 F-Block. bill inward no is 295.
6039	Gumohar Residency	F	201	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	16-Feb-21	16-Feb-21 INR	doc_6028846c665b4.pdf	Towards WPC door frames fixing work done for FLAT NO 201 F-Block. bill inward no is 295.
6039	Gumohar Residency	F	206	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	16-Feb-21	16-Feb-21 INR	doc_6028851435006.pdf	Towards WPC door frames fixing work done for FLAT NO 206 F-Block. bill inward no is 295.
6039	Gumohar Residency	A	102	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	08-Mar-21	08-Mar-21 INR	doc_6045b065c672.pdf	Towards door frames fixing work done for flat no 102 at A-Block. bill inward no is 296.
6039	Gumohar Residency	A	103	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	08-Mar-21	08-Mar-21 INR	doc_6045b1cbb52a.pdf	Towards door frames fixing work done for flat no 103 at A-Block. bill inward no is 296.
6039	Gumohar Residency	A	105	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	08-Mar-21	08-Mar-21 INR	doc_6045b21c36cde.pdf	Towards door frames fixing work done for flat no 105 at A-Block. bill inward no is 296.
6039	Gumohar Residency	A	106	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	08-Mar-21	08-Mar-21 INR	doc_6045b26ee642.pdf	Towards door frames fixing work done for flat no 106 at A-Block. bill inward no is 296.
6039	Gumohar Residency	A	107	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	08-Mar-21	08-Mar-21 INR	doc_6045b2a6d854.pdf	Towards door frames fixing work done for flat no 107 at A-Block. bill inward no is 296.
6039	Gumohar Residency	A	108	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	08-Mar-21	08-Mar-21 INR	doc_6045b3027b4e8.pdf	Towards door frames fixing work done for flat no 108 at A-Block. bill inward no is 296.
6039	Gumohar Residency	A	204	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,540	08-Mar-21	08-Mar-21 INR	doc_6045b33b205bd.pdf	Towards door frames fixing work done for flat no 204 at A-Block. bill inward no is 296.
6039	Gumohar Residency	B	101	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6046b4018b78.pdf	Towards door frames fixing work done for flat no 101 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	102	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6046b729d4c09.pdf	Towards door frames fixing work done for flat no 102 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	103	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6046b71d4530.pdf	Towards door frames fixing work done for flat no 103 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	104	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6046b7aee9e35.pdf	Towards door frames fixing work done for flat no 104 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	105	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6046b7ee3949.pdf	Towards door frames fixing work done for flat no 105 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	106	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6046b7fa5260b.pdf	Towards door frames fixing work done for flat no 106 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	107	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6046b7fb4b562.pdf	Towards door frames fixing work done for flat no 107 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	202	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_604703088743.pdf	Towards door frames fixing work done for flat no 202 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	203	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_604703a17b44c.pdf	Towards door frames fixing work done for flat no 203 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	204	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_60470311174d.pdf	Towards door frames fixing work done for flat no 204 B-Block. bill inward no is 297.
6039	Gumohar Residency	B	205	1360 B Ramnabhu	Carpentry - Door Frames	1.1	1,360	09-Mar-21	09-Mar-21 INR	doc_6047031b27584.pdf	Towards door frames fixing work done for flat no 205 B-Block. bill inward no is 297.
6039	Gumohar Residency	A	102	1360 B Ramnabhu	Carpentry - Door Shutters	2	2,700	02-Mar-21	02-Mar-21 INR	doc_603a108211363.pdf	A102. Bill inward ID 281.
6039	Gumohar Residency	A	104	1360 B Ramnabhu	Carpentry - Door Shutters	2	2,700	02-Mar-21	02-Mar-21 INR	doc_603a11155521.pdf	A105. Bill inward ID 281.
6039	Gumohar Residency	A	105	1360 B Ramnabhu	Carpentry - Door Shutters	2	2,700	02-Mar-21	02-Mar-21 INR	doc_603a115d47878.pdf	A105. Bill inward ID 281.
6039	Gumohar Residency	A	205	1360 B Ramnabhu	Carpentry - Door Shutters	2	2,700	02-Mar-21	02-Mar-21 INR	doc_603a115d47878.pdf	A105. Bill inward ID 281.

60116	Gulmohar Residency	A	206	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017dc7029cde.pdf	Towards civil work - brickwork done for flat no 206 at A-Block . bill inward no is 250.
60117	Gulmohar Residency	A	207	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017dcb100573.pdf	Towards civil work - brickwork done for flat no 207 at A-Block . bill inward no is 250.
60118	Gulmohar Residency	A	208	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017dd0d191bb.pdf	Towards civil work - brickwork done for flat no 208 at A-Block . bill inward no is 250.
60119	Gulmohar Residency	A	209	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017de57dcee9.pdf	Towards civil work - brickwork done for flat no 209 at A-Block . bill inward no is 250.
60120	Gulmohar Residency	A	501	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	89.9	122,269	01-Feb-21		01-Feb-21	INR	doc_6017de193e60b.pdf	Towards RCC-col 7 work done for flat no 501 at A-Block . bill inward no is 249.
60124	Gulmohar Residency	A	201	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017df429a662.pdf	Towards civil work - brickwork done for flat no 248 at A-Block . bill inward no is 248.
60125	Gulmohar Residency	A	202	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017df9aafb37.pdf	Towards civil work - brickwork done for flat no 202 at A-Block . bill inward no is 248.
60126	Gulmohar Residency	A	203	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017dfe6820ba.pdf	Towards civil work - brickwork done for flat no 203 at A-Block . bill inward no is 248.
60127	Gulmohar Residency	A	204	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017e0275695b.pdf	Towards civil work - brickwork done for flat no 204 at A-Block . bill inward no is 248.
60128	Gulmohar Residency	A	205	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	128.2	174,409	01-Feb-21		01-Feb-21	INR	doc_6017e0998826a.pdf	Towards civil work - brickwork done for flat no 205 at A-Block . bill inward no is 248.
60140	Gulmohar Residency	B	401	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,615	02-Feb-21		02-Feb-21	INR	doc_601916d1e3e14.pdf	Towards brickwork work done for flat no 401 at B-Block . bill inward no is 252.
60141	Gulmohar Residency	B	404	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,615	02-Feb-21		02-Feb-21	INR	doc_601916f14379c.pdf	Towards brickwork work done for flat no 404 at B-Block . bill inward no is 252.
60142	Gulmohar Residency	B	406	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,615	02-Feb-21		02-Feb-21	INR	doc_6019170c144da.pdf	Towards brickwork work done for flat no 406 at B-Block . bill inward no is 252.
60143	Gulmohar Residency	B	408	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,615	02-Feb-21		02-Feb-21	INR	doc_60191753bd89.pdf	Towards brickwork work done for flat no 408 at B-Block . bill inward no is 252.
60144	Gulmohar Residency	B	304	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	02-Feb-21		02-Feb-21	INR	doc_6019176e828e1.pdf	Towards plastering work done for flat no 304 at B-Block . bill inward no is 251.
60145	Gulmohar Residency	B	306	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	02-Feb-21		02-Feb-21	INR	doc_6019191af3740.pdf	Towards plastering work done for flat no 306 at B-Block . bill inward no is 251.
60146	Gulmohar Residency	B	308	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	02-Feb-21		02-Feb-21	INR	doc_6019195f28a3a.pdf	Towards plastering work done for flat no 308 at B-Block . bill inward no is 251.
60533	Gulmohar Residency	B	405	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,616	20-Feb-21		20-Feb-21	INR	doc_6030fd8515db6.pdf	Towards brick work done for flat no 405 B-Block . bill inward no is 274 .
60535	Gulmohar Residency	B	302	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	20-Feb-21		20-Feb-21	INR	doc_6030fe1348e39.pdf	Towards brick work done for flat no 302 B-Block . bill inward no is 273 .
61090	Gulmohar Residency	A	205	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f2067ab674.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 317 .
61092	Gulmohar Residency	A	206	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f20a060242.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 317 .
61093	Gulmohar Residency	A	207	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f20e875a5e.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 317 .
61094	Gulmohar Residency	A	208	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f2128c12a0.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 317 .
61095	Gulmohar Residency	A	209	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f21592759a.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 317 .
61096	Gulmohar Residency	A	102	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f222020e93.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 318 .
61097	Gulmohar Residency	A	103	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f224b64507.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 318 .
61098	Gulmohar Residency	A	104	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f226fc5d5b.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 318 .
61099	Gulmohar Residency	A	105	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f229a89df2.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 318 .
61100	Gulmohar Residency	A	106	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f22c452205.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 318 .
61101	Gulmohar Residency	A	107	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f22e8d648a.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 318 .
61102	Gulmohar Residency	A	108	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,653	27-Mar-21		27-Mar-21	INR	doc_605f230d1c40a.pdf	Towards internal plaster hg work done at A-Block . bill inward no is 318 .

61104	Gulmohar Residency	B		305	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	29-Mar-21		29-Mar-21	INR	doc_606169aedc939.pdf	Towards Internal plaster hg work done for flats at B-Block. bill inward no is 320.
61105	Gulmohar Residency	B		402	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	29-Mar-21		29-Mar-21	INR	doc_606169d862a93.pdf	Towards Internal plaster hg work done for flats at B-Block. bill inward no is 320.
61106	Gulmohar Residency	B		403	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	29-Mar-21		29-Mar-21	INR	doc_60616a083a100.pdf	Towards Internal plaster hg work done for flats at B-Block. bill inward no is 320.
61107	Gulmohar Residency	B		406	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	29-Mar-21		29-Mar-21	INR	doc_60616a482e0dc.pdf	Towards Internal plaster hg work done for flats at B-Block. bill inward no is 320.
61108	Gulmohar Residency	B		407	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	29-Mar-21		29-Mar-21	INR	doc_60616a72caab9.pdf	Towards Internal plaster hg work done for flats at B-Block. bill inward no is 320.
61109	Gulmohar Residency	B		408	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	95.4	158,364	29-Mar-21		29-Mar-21	INR	doc_60616a9df0eb8.pdf	Towards Internal plaster hg work done for flats at B-Block. bill inward no is 320.
61110	Gulmohar Residency	B		402	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,615	29-Mar-21		29-Mar-21	INR	doc_60616aee2fe4e.ptcf	Towards brick work done for flats at B-Block. bill inward no is 319.
61111	Gulmohar Residency	B		403	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,615	29-Mar-21		29-Mar-21	INR	doc_60616b5fa03d2.pdf	Towards brick work done for flats at B-Block. bill inward no is 319.
61112	Gulmohar Residency	B		407	1660 Sree Srinivasa constructions	Civil - Brickwork & Plastering	122.7	203,615	29-Mar-21		29-Mar-21	INR	doc_60616ba154a57.pdf	Towards brick work done for flats at B-Block. bill inward no is 319.
61151	Gulmohar Residency	A		301	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a7255f6c4.pdf	Towards Internal Plaster hg at A-block Flat no-301. Bill inward ID 324
61152	Gulmohar Residency	A		302	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a7d18ff53.pdf	Towards Internal Plaster hg at A-block Flat no-302. Bill inward ID 324
61153	Gulmohar Residency	A		303	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a817eec51.pdf	Towards Internal Plaster hg at A-block Flat no-303. Bill inward ID 324
61154	Gulmohar Residency	A		304	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a853ec58e.pdf	Towards Internal Plaster hg at A-block Flat no-304. Bill inward ID 324
61155	Gulmohar Residency	A		305	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a8f5730bf.pdf	Towards Internal Plaster hg at A-block Flat no-305. Bill inward ID 325.
61156	Gulmohar Residency	A		306	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a9366b8b1.pdf	Towards Internal Plaster hg at A-block Flat no-306. Bill inward ID 325.
61157	Gulmohar Residency	A		307	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a96785c7e.pdf	Towards Internal Plaster hg at A-block Flat no-307. Bill inward ID 325.
61158	Gulmohar Residency	A		308	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a9a0c13df.pdf	Towards Internal Plaster hg at A-block Flat no-308. Bill inward ID 325.
61159	Gulmohar Residency	A		309	1360 Surasani Constructions Pvt Ltd	Civil - Brickwork & Plastering	99.7	135,646	29-Mar-21		29-Mar-21	INR	doc_6061a9dd62104.pdf	Towards Internal Plaster hg at A-block Flat no-309. Bill inward ID 325.
60534	Gulmohar Residency	B		301	1660 Sree Srinivasa constructions	Civil Work - Brickwork & Plastering	95.4	158,364	20-Feb-21		20-Feb-21	INR	doc_6030fde450ca4.pdf	Towards brick work done for flat no 301 B-Block. bill inward no is 273.
60536	Gulmohar Residency	B		303	1660 Sree Srinivasa constructions	Civil Work - Brickwork & Plastering	95.4	158,364	20-Feb-21		20-Feb-21	INR	doc_6030fe7559c13.pdf	Towards brick work done for flat no 303 B-Block. bill inward no is 273.
60537	Gulmohar Residency	B		307	1660 Sree Srinivasa constructions	Civil Work - Brickwork & Plastering	95.4	158,364	20-Feb-21		20-Feb-21	INR	doc_6030fec6d79b.ptcf	Towards brick work done for flat no 307 B-Block. bill inward no is 273.
60525	Gulmohar Residency	A		201	1360 Surasani Constructions Pvt Ltd	Civil Work - Brickwork & Plastering	99.7	135,653	05-Mar-21		05-Mar-21	INR	doc_6041ecaedc037.pdf	A - Block 201. Bill inward ID 295.
60526	Gulmohar Residency	A		202	1360 Surasani Constructions Pvt Ltd	Civil Work - Brickwork & Plastering	99.7	135,653	05-Mar-21		05-Mar-21	INR	doc_6041ed07bb8e5.pdf	A - Block 202. Bill inward ID 295.
60527	Gulmohar Residency	A		203	1360 Surasani Constructions Pvt Ltd	Civil Work - Brickwork & Plastering	99.7	135,653	05-Mar-21		05-Mar-21	INR	doc_6041ee161b1bf.pdf	A - Block 203. Bill inward ID 295.
60528	Gulmohar Residency	A		204	1360 Surasani Constructions Pvt Ltd	Civil Work - Brickwork & Plastering	99.7	135,653	05-Mar-21		05-Mar-21	INR	doc_6041eea6abdb90.pdf	A - Block 204. Bill inward ID 295.
60370	Gulmohar Residency	Misc	Misc		31540 Kamles Varma - Earth work	Civil Work - Misc.	0.1	3,960	16-Feb-21		16-Feb-21	INR	doc_602b815b26c13.pdf	towards brick work done for creche room. Bill inward no 267
59891	Gulmohar Residency	A		102	1360 V.Balakrishna - Core Cutting	Core cutting	3.6	4,950	12-Jan-21		12-Jan-21	INR	doc_5ffd2ca31b78a.pdf	Towards core cutting work done at A-101. Bill inward no is 215.
59892	Gulmohar Residency	A		103	1360 V.Balakrishna - Core Cutting	Core cutting	3.6	4,950	12-Jan-21		12-Jan-21	INR	doc_5ffd30679c9a9.pdf	Towards core cutting work done at A-102. Bill inward no is 215.
59893	Gulmohar Residency	A		104	1360 V.Balakrishna - Core Cutting	Core cutting	3.6	4,950	12-Jan-21		12-Jan-21	INR	doc_5ffd30d1f04f3.pdf	Towards core cutting work done at A-104. Bill inward no is 215.
59894	Gulmohar Residency	A		107	1360 V.Balakrishna - Core Cutting	Core cutting	2.5	3,375	12-Jan-21		12-Jan-21	INR	doc_5ffd3134c6194.pdf	Towards core cutting work done at A-107. Bill inward no is 215.
59895	Gulmohar Residency	A		108	1360 V.Balakrishna - Core Cutting	Core cutting	2.5	3,375	12-Jan-21		12-Jan-21	INR	doc_5ffd31b3c2849.pdf	Towards core cutting work done at A-108. Bill inward no is 215.
59896	Gulmohar Residency	B		101	1660 V.Balakrishna - Core Cutting	Core cutting	2.7	4,556	12-Jan-21		12-Jan-21	INR	doc_5ffd3271589cf.pdf	Towards core cutting work done at B-101. Bill inward no is 215.
59897	Gulmohar Residency	B		102	1660 V.Balakrishna - Core Cutting	Core cutting	2.7	4,556	12-Jan-21		12-Jan-21	INR	doc_5ffd32ab99646.pdf	Towards core cutting work done at B-102. Bill inward no is 215.

60879	Gulmohar Residency	B		404	1660 V.Balakrishna - Core Cutting	Core cutting	2.7	4,425	18-Mar-21		18-Mar-21	INR	doc_6052dd29b5b5.pdf	Towards core cutting work done at B-Block . bill Inward no is 305.
60880	Gulmohar Residency	B		405	1660 V.Balakrishna - Core Cutting	Core cutting	2.7	4,425	18-Mar-21		18-Mar-21	INR	doc_6052dd8a89261.pdf	Towards core cutting work done at B-Block . bill Inward no is 305.
60881	Gulmohar Residency	B		406	1660 V.Balakrishna - Core Cutting	Core cutting	2.7	4,425	18-Mar-21		18-Mar-21	INR	doc_6052ddd73aaa3.pdf	Towards core cutting work done at B-Block . bill Inward no is 305.
60882	Gulmohar Residency	B		407	1660 V.Balakrishna - Core Cutting	Core cutting	2.7	4,425	18-Mar-21		18-Mar-21	INR	doc_6052de21ad294.pdf	Towards core cutting work done at B-Block . bill Inward no is 305.
60883	Gulmohar Residency	B		408	1660 V.Balakrishna - Core Cutting	Core cutting	2.7	4,425	18-Mar-21		18-Mar-21	INR	doc_6052de566a43d.pdf	Towards core cutting work done at B-Block . bill Inward no is 305.
59755	Gulmohar Residency	Misc	Misc		31540 B. Nareish - Earth work	Earth Work - LS	7.9	250,000	05-Jan-21		05-Jan-21	INR	doc_5ff4273fb08bc.pdf	Towards morrum filling work done at C-Block . bill Inward no is 203.
59837	Gulmohar Residency	Misc	Misc		31540 Varikuppala Raju - Earth Work - Misc.	Earth Work - LS	24.1	760,000	07-Jan-21		07-Jan-21	INR	doc_5ff6c988d3ee9.pdf	Towards boulders shifting work done at D & F blocks . bill Inward no is 214 .
59754	Gulmohar Residency	Misc	Misc		31540 varikuppala Lakshmi - Earthwork	Earth Work - Misc.	0.8	25,000	05-Jan-21		05-Jan-21	INR	doc_5ff43324d169b.pdf	Dowel holes drilling in C,F , G-blocks. bill Inward no is 204.
59833	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	07-Jan-21		07-Jan-21	INR	doc_600bf545e0aef.pdf	Towards upper basement flat no 9 work done at A-Block . bill Inward no is 240 .
59834	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	07-Jan-21		07-Jan-21	INR	doc_600bf59496a07.pdf	Towards upper basement flat no - 8 work done at A-Block . bill Inward no is 239 .
59841	Gulmohar Residency	H		101	1360 Manyem - Earthwork	Earth Work - Misc.	84.6	115,000	15-Jan-21		15-Jan-21	INR	doc_60013e208da11.pdf	G,H-E-Blocks Boulders shifting work.
60013	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	23-Jan-21		23-Jan-21	INR	doc_600bf6724e362.pdf	Towards upper basement flat no 7 work done at A-Block . bill Inward no is 238.
60014	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	23-Jan-21		23-Jan-21	INR	doc_600bf75b09ac2.pdf	Towards upper basement flat no 6 work done at A-Block . bill Inward no is 237.
60015	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	23-Jan-21		23-Jan-21	INR	doc_600bf87e44c09.pdf	Towards upper basement flat no 5 work done at A-Block . bill Inward no is 236.
60016	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	23-Jan-21		23-Jan-21	INR	doc_600bf8fb95f30.pdf	Towards upper basement flat no 4 work done at A-Block . bill Inward no is 235.
60017	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	23-Jan-21		23-Jan-21	INR	doc_600bf96157c51.pdf	Towards upper basement flat no 3 work done at A-Block . bill Inward no is 234.
60018	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	23-Jan-21		23-Jan-21	INR	doc_600bfa0f29b6b.pdf	Towards upper basement flat no 2 work done at A-Block . bill Inward no is 233.
60019	Gulmohar Residency	A	upper Basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.4	637,613	23-Jan-21		23-Jan-21	INR	doc_600bfa72610d5.pdf	Towards upper basement flat no 1 work done at A-Block . bill Inward no is 232.
60020	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfa0f8f1b0.pdf	Towards lower basement flat no 9 work done at A-Block . bill Inward no is 231.
60021	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfb6a83ee1.pdf	Towards lower basement flat no 8 work done at A-Block . bill Inward no is 230.
60022	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfb645f0b9.pdf	Towards lower basement flat no 4 work done at A-Block . bill Inward no is 229.
60023	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfc30ee71f.pdf	Towards lower basement flat no 7 work done at A-Block . bill Inward no is 228.
60024	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfce2c035.pdf	Towards lower basement flat no 5 work done at A-Block . bill Inward no is 227.
60025	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bf4f08680.pdf	Towards lower basement flat no 5 work done at A-Block . bill Inward no is 226.
60026	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfdbcb7aab.pdf	Towards lower basement flat no 3 work done at A-Block . bill Inward no is 225.
60027	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfe0f0b070.pdf	Towards lower basement flat no 2 work done at A-Block . bill Inward no is 224.
60028	Gulmohar Residency	A	lower basement		12900 Surasani Constructions Pvt Ltd	Earth Work - Misc.	49.5	638,381	23-Jan-21		23-Jan-21	INR	doc_600bfe8466f94.pdf	Towards lower basement flat no 1 work done at A-Block . bill Inward no is 223.
60057	Gulmohar Residency	Misc	Misc		31540 Meeriyala Raju Kumar - Earth Work	Earth Work - Misc.	7.1	225,000	28-Jan-21		28-Jan-21	INR	doc_60129167706e9.pdf	Towards boulders shifting from E-Block . bill Inward no is 245 .
60162	Gulmohar Residency	Misc	Misc		31540 M.Chandrakala	Earth Work - Misc.	2.7	83,948	02-Feb-21		02-Feb-21	INR	doc_60193b9242e1a.pdf	Towards morrum filling work done at clubhouse area. bill Inward no is 254 .
60457	Gulmohar Residency	Misc	Misc		31540 Meeriyala Raju Kumar - Earth Work	Earth Work - Misc.	7.9	250,000	18-Feb-21		18-Feb-21	INR	doc_602e32c10188f.pdf	Towards morrum filling work done at E-Block. bill Inward no is 270.
60463	Gulmohar Residency	A		102	1360 Kamles Varraja - Earth work	Earth Work - Misc.	4	5,440	18-Feb-21		18-Feb-21	INR	doc_602e4292359cb.pdf	Towards Dust filling work for flooring tiles laying work done for flat no 102 A-Block. bill Inward no is 272.

60454	Gulmohar Residency	A	103	1360 Kamles Varma - Earth work	Earth Work - Misc.	4	5,440	18-Feb-21		18-Feb-21	INR	doc_602e42d61374f.pdf	Towards Dust filling work for flooring tiles laying work done for flat no 103 A-Block. bill inward no is 272.
60455	Gulmohar Residency	A	104	1360 Kamles Varma - Earth work	Earth Work - Misc.	4	5,440	18-Feb-21		18-Feb-21	INR	doc_602e433b2c805.pdf	Towards Dust filling work for flooring tiles laying work done for flat no 104 A-Block. bill inward no is 272.
60456	Gulmohar Residency	A	105	1360 Kamles Varma - Earth work	Earth Work - Misc.	4	5,440	18-Feb-21		18-Feb-21	INR	doc_602e436a53056.pdf	Towards Dust filling work for flooring tiles laying work done for flat no 105 A-Block. bill inward no is 272.
60457	Gulmohar Residency	A	106	1360 Kamles Varma - Earth work	Earth Work - Misc.	4	5,440	18-Feb-21		18-Feb-21	INR	doc_602e43eae7b53.pdf	Towards Dust filling work for flooring tiles laying work done for flat no 106 A-Block. bill inward no is 272.
60458	Gulmohar Residency	A	107	1360 Kamles Varma - Earth work	Earth Work - Misc.	4	5,440	18-Feb-21		18-Feb-21	INR	doc_602e444aaa3b1.pdf	Towards Dust filling work for flooring tiles laying work done for flat no 107 A-Block. bill inward no is 272.
60459	Gulmohar Residency	A	108	1360 Kamles Varma - Earth work	Earth Work - Misc.	4	5,440	18-Feb-21		18-Feb-21	INR	doc_602e44907d8db.pdf	Towards Dust filling work for flooring tiles laying work done for flat no 108 A-Block. bill inward no is 272.
61005	Gulmohar Residency	B	101	1660 Kamles Varma - Earth work	Earth Work - Misc.	4	6,640	25-Mar-21		25-Mar-21	INR	doc_605c8160e60ba.pdf	Towards dust filling work done for flooring at B-Block. bill inward no is 291.
61007	Gulmohar Residency	B	102	1660 Kamles Varma - Earth work	Earth Work - Misc.	4	6,640	25-Mar-21		25-Mar-21	INR	doc_605c81a09cd20.pdf	Towards dust filling work done for flooring at B-Block. bill inward no is 291.
61011	Gulmohar Residency	B	108	1660 Kamles Varma - Earth work	Earth Work - Misc.	4	6,640	25-Mar-21		25-Mar-21	INR	doc_605c824960f6c.pdf	Towards dust filling work done for flooring at B-Block. bill inward no is 291.
61014	Gulmohar Residency	B	204	1660 Kamles Varma - Earth work	Earth Work - Misc.	4	6,640	25-Mar-21		25-Mar-21	INR	doc_605c82cfc78c.pdf	Towards dust filling work done for flooring at B-Block. bill inward no is 291.
61016	Gulmohar Residency	B	203	1660 Kamles Varma - Earth work	Earth Work - Misc.	4	6,640	25-Mar-21		25-Mar-21	INR	doc_605c82fba14ab.pdf	Towards dust filling work done for flooring at B-Block. bill inward no is 291.
61017	Gulmohar Residency	B	107	1660 Kamles Varma - Earth work	Earth Work - Misc.	4	6,640	25-Mar-21		25-Mar-21	INR	doc_605c833e435bb.pdf	Towards dust filling work done for flooring at B-Block. bill inward no is 291.
59738	Gulmohar Residency	A	205	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	04-Jan-21		04-Jan-21	INR	doc_5ff6d7be07a9f.pdf	A-205 flats electrical chipping and metal boxes fixing done . bill inward no is 189 .
59743	Gulmohar Residency	A	201	1360 N.Ramakrishna Reddy	Electrical - Inside flat	5.1	7,000	04-Jan-21		04-Jan-21	INR	doc_5ff6e3ee44847.pdf	Inside flats electrical work done for flat no 202 A-Block . bill inward no is 193 .
59745	Gulmohar Residency	B	301	1660 V.Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	04-Jan-21		04-Jan-21	INR	doc_5ff6e6ad7394b.pdf	Inside flats electrical work done for flat no 301 B-Block . bill inward no is 195 .
59748	Gulmohar Residency	B	104	1660 S.Ganesh	Electrical - Inside flat	1.1	1,800	04-Jan-21		04-Jan-21	INR	doc_5ff6ec3737a6e.pdf	Inside flats additional electrical works for flat no 104 B-Block . bill inward no is 198 .
59838	Gulmohar Residency	A	206	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	07-Jan-21		07-Jan-21	INR	doc_5ff6d8340dbb6.pdf	A-206 flats electrical chipping and metal boxes fixing done . bill inward no is 189 .
59847	Gulmohar Residency	A	202	1360 N.Ramakrishna Reddy	Electrical - Inside flat	5.1	7,000	07-Jan-21		07-Jan-21	INR	doc_5ff6e453bc204.pdf	Inside flats electrical work done for flat no 202 A-Block . bill inward no is 193 .
59848	Gulmohar Residency	A	204	1360 N. Ramakrishna Reddy	Electrical - Inside flat	5.1	7,000	07-Jan-21		07-Jan-21	INR	doc_5ff6e49d2f674.pdf	Inside flats electrical work done for flat no 204 A-Block . bill inward no is 193 .
59849	Gulmohar Residency	A	208	1360 N.Ramakrishna Reddy	Electrical - Inside flat	5.1	7,000	07-Jan-21		07-Jan-21	INR	doc_5ff6e4d7b315b.pdf	Inside flats electrical work done for flat no 208 A-Block . bill inward no is 193 .
59850	Gulmohar Residency	B	302	1660 V.Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	07-Jan-21		07-Jan-21	INR	doc_5ff6e868ebbb1.pdf	Inside flats electrical work done for flat no 302 B-Block . bill inward no is 195 .
59851	Gulmohar Residency	B	307	1660 V.Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	07-Jan-21		07-Jan-21	INR	doc_5ff6e8e1706dc.pdf	Inside flats electrical work done for flat no 307 B-Block . bill inward no is 195 .
59852	Gulmohar Residency	B	308	1660 V.Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	07-Jan-21		07-Jan-21	INR	doc_5ff6e9240b8da.pdf	Inside flats electrical work done for flat no 308 B-Block . bill inward no is 195 .
59859	Gulmohar Residency	B	105	1660 S.Ganesh	Electrical - Inside flat	1.1	1,800	07-Jan-21		07-Jan-21	INR	doc_5ff6ec6aa380c.pdf	Inside flats additional electrical works for flat no 105 B-Block . bill inward no is 198 .
59886	Gulmohar Residency	A	203	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	12-Jan-21		12-Jan-21	INR	doc_5ffd26add1a2.pdf	A-203 flats electrical chipping and metal boxes fixing done . bill inward no is 217 .
59886	Gulmohar Residency	A	207	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	12-Jan-21		12-Jan-21	INR	doc_5ffd27091cfd3.pdf	A-207 flats electrical chipping and metal boxes fixing done . bill inward no is 217 .
60055	Gulmohar Residency	B	404	1660 S.Ganesh	Electrical - Inside flat	4.7	7,750	28-Jan-21		28-Jan-21	INR	doc_601290d2ca08b.pdf	Towards inside flats electrical work done for flat no 404 at B-Block. bill inward no is 244 .

60056	Gulmohar Residency	B	406	1660 S.Ganesh	Electrical - Inside flat	4.7	7,750	28-Jan-21	28-Jan-21	INR	doc_6012910458d29.pdf	Towards inside flats electrical work done for flat no 406 at B-Block. bill inward no is 244 .
60147	Gulmohar Residency	A	304	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	02-Feb-21	02-Feb-21	INR	doc_60191aa064c36.pdf	Towards stage 2 electrical works for flat no - 304 at A-Block . bill inward no is 253.
60148	Gulmohar Residency	A	305	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	02-Feb-21	02-Feb-21	INR	doc_60191ad907696.pdf	Towards stage 2 electrical works for flat no - 305 at A-Block . bill inward no is 253.
60261	Gulmohar Residency	A	106	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	10-Feb-21	10-Feb-21	INR	doc_602364f05aea3.pdf	Towards inside flats electrical works done for flat no 106 A-Block. bill Inward no is 256 .
60262	Gulmohar Residency	A	201	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	10-Feb-21	10-Feb-21	INR	doc_6023652c183a0.pdf	Towards inside flats electrical works done for flat no 201 A-Block. bill Inward no is 256 .
60263	Gulmohar Residency	A	204	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	10-Feb-21	10-Feb-21	INR	doc_602365c719b85.pdf	Towards inside flats electrical works done for flat no 204 A-Block. bill Inward no is 256 .
60264	Gulmohar Residency	A	209	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	10-Feb-21	10-Feb-21	INR	doc_6023660a7ff78.pdf	Towards inside flats electrical works done for flat no 209 A-Block. bill Inward no is 256 .
60266	Gulmohar Residency	F	306	1360 N.Nagaraju - Electrical	Electrical - Inside flat	1.8	2,500	10-Feb-21	10-Feb-21	INR	doc_602366a613a59.pdf	Towards slab electrical conducting work done for flat no 306 F-Block. bill Inward no is 256 .
60291	Gulmohar Residency	A	304	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	10-Feb-21	10-Feb-21	INR	doc_6023c5464e277.pdf	Towards inside flats electrical works done for flat no 304 . Bill inward no is 263.
60292	Gulmohar Residency	A	305	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	10-Feb-21	10-Feb-21	INR	doc_6023c589a5091.pdf	Towards inside flats electrical works done for flat no 305 . Bill inward no is 263.
60293	Gulmohar Residency	A	307	1360 K.Ramakrishna	Electrical - Inside flat	5.1	7,000	10-Feb-21	10-Feb-21	INR	doc_6023c5bca6aed.pdf	Towards inside flats electrical works done for flat no 307 . Bill inward no is 263.
60367	Gulmohar Residency	B	305	1660 S.Ganesh	Electrical - Inside flat	4.7	7,750	16-Feb-21	16-Feb-21	INR	doc_602b7fa756c9f.pdf	towards electrical work done inside flats for 305 B-block. Bill inward no is 264
60368	Gulmohar Residency	B	403	1660 S.Ganesh	Electrical - Inside flat	4.7	7,750	16-Feb-21	16-Feb-21	INR	doc_602b801c6d88e.pdf	towards electrical work done inside flats for 403 B-block. Bill inward no is 264
60369	Gulmohar Residency	B	405	1660 S.Ganesh	Electrical - Inside flat	4.7	7,750	16-Feb-21	16-Feb-21	INR	doc_602b8071eff04.pdf	towards electrical work done inside flats for 405 B-block. Bill inward no is 264
60558	Gulmohar Residency	F	106	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	22-Feb-21	22-Feb-21	INR	doc_6033b1ed66cbf.pdf	Towards inside flats electrical work done for flat no 106 F-Block. bill inward no is 278.
60559	Gulmohar Residency	A	309	1360 Srikanth jena	Electrical - Inside flat	3.1	4,200	23-Feb-21	23-Feb-21	INR	doc_6034f5a339ebe.pdf	Towards inside flats plumbing work done for flat no 309 A-Block. bill inward no is 279.
60560	Gulmohar Residency	A	404	1360 Srikanth jena	Electrical - Inside flat	3.1	4,200	23-Feb-21	23-Feb-21	INR	doc_6034f6224d11d.pdf	Towards inside flats plumbing work done for flat no 404 A-Block. bill inward no is 279.
60561	Gulmohar Residency	A	405	1360 Srikanth jena	Electrical - Inside flat	3.1	4,200	23-Feb-21	23-Feb-21	INR	doc_6034f67522e30.pdf	Towards inside flats plumbing work done for flat no 405 A-Block. bill inward no is 279.
60606	Gulmohar Residency	A	301	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	05-Mar-21	05-Mar-21	INR	doc_6041d4f95580f.pdf	A-301.Bill Inward ID 286.
60607	Gulmohar Residency	A	302	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	05-Mar-21	05-Mar-21	INR	doc_6041d57590079.pdf	A-302.Bill Inward ID 286.
60608	Gulmohar Residency	A	306	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	05-Mar-21	05-Mar-21	INR	doc_6041d5ee30845.pdf	A-306.Bill Inward ID 286.
60609	Gulmohar Residency	A	308	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	05-Mar-21	05-Mar-21	INR	doc_6041d64586aac.pdf	A-308.Bill Inward ID 286.
60610	Gulmohar Residency	A	309	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	05-Mar-21	05-Mar-21	INR	doc_6041d6badf333.pdf	A-309.Bill Inward ID 286.
60612	Gulmohar Residency	F	201	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	05-Mar-21	05-Mar-21	INR	doc_6041d92929756.pdf	F- 201.Bill Inward ID 288.
60613	Gulmohar Residency	F	206	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	05-Mar-21	05-Mar-21	INR	doc_6041d96ec4c3c.pdf	F- 206.Bill Inward ID 288.
60614	Gulmohar Residency	F	401	1360 N.Nagaraju - Electrical	Electrical - Inside flat	1.8	2,500	05-Mar-21	05-Mar-21	INR	doc_6041d9e5547e.pdf	F- 401.Bill Inward ID 289.
60615	Gulmohar Residency	F	406	1360 N.Nagaraju - Electrical	Electrical - Inside flat	1.8	2,500	05-Mar-21	05-Mar-21	INR	doc_6041da463dcf1.pdf	F- 406.Bill Inward ID 289.
60850	Gulmohar Residency	B	401	1660 V.Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	16-Mar-21	16-Mar-21	INR	doc_605096d488117.pdf	Towards electrical work done inside flats at B-Block. bill Inward no is 309 .
60851	Gulmohar Residency	B	402	1660 V.Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	16-Mar-21	16-Mar-21	INR	doc_6050970b87ce1.pdf	Towards electrical work done inside flats at B-Block. bill Inward no is 309 .
60852	Gulmohar Residency	B	407	1660 V.Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	16-Mar-21	16-Mar-21	INR	doc_6050973aac0de.pdf	Towards electrical work done inside flats at B-Block. bill Inward no is 309 .

60855	Gulmohar Residency	B	408	1660 V/Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	16-Mar-21		16-Mar-21	INR	doc_6050979d7f68.pdf	Towards electrical work done inside flats at B-Block, bill inward no is 309.
60855	Gulmohar Residency	B	501	1660 V/Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	16-Mar-21		16-Mar-21	INR	doc_605097043a2a.pdf	Towards electrical work done inside flats at B-Block, bill inward no is 309.
60855	Gulmohar Residency	B	508	1660 V/Bal Reddy - Electrical	Electrical - Inside flat	4.7	7,750	16-Mar-21		16-Mar-21	INR	doc_605098443370.pdf	Towards electrical work done inside flats at B-Block, bill inward no is 309.
61115	Gulmohar Residency	A	401	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at A-Block, bill inward no is 321.
61115	Gulmohar Residency	A	402	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at A-Block, bill inward no is 321.
61115	Gulmohar Residency	A	408	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at A-Block, bill inward no is 321.
61117	Gulmohar Residency	A	409	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at A-Block, bill inward no is 321.
61115	Gulmohar Residency	F	301	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at A-Block, bill inward no is 321.
61120	Gulmohar Residency	F	306	1360 N.Nagaraju - Electrical	Electrical - Inside flat	5.1	7,000	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at A-Block, bill inward no is 321.
61160	Gulmohar Residency	B	503	1660 S.Ganesh	Electrical - Inside flat	4.7	7,750	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at B-Block, bill inward no is 322.
61161	Gulmohar Residency	B	504	1660 S.Ganesh	Electrical - Inside flat	4.7	7,750	29-Mar-21		29-Mar-21	INR	doc_60616cd45370.pdf	Towards electrical work done inside flats at B-Block, bill inward no is 322.
59766	Gulmohar Residency	A	101	1360 K.Ramakrishna	Electrical - Misc.	1.3	1,800	05-Jan-21		05-Jan-21	INR	doc_5f427c743d53.pdf	Towards miscellaneous electricals works done for flat no 101, bill inward no is 202.
59767	Gulmohar Residency	A	109	1360 K.Ramakrishna	Electrical - Misc.	1.3	1,800	05-Jan-21		05-Jan-21	INR	doc_5f427c743d53.pdf	Towards miscellaneous electricals works done for flat no 109, bill inward no is 202.
59739	Gulmohar Residency	A	401	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	04-Jan-21		04-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 401 at A-Block, bill inward no is 192.
59742	Gulmohar Residency	F	106	1360 N.Nagaraju - Electrical	Electrical - Slab	1.4	1,900	04-Jan-21		04-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 106 at A-Block, bill inward no is 192.
59741	Gulmohar Residency	A	403	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	04-Jan-21		04-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 403 at A-Block, bill inward no is 192.
59742	Gulmohar Residency	F	201	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	04-Jan-21		04-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 201 at F-Block, bill inward no is 191.
59746	Gulmohar Residency	B	501	1660 V/Bal Reddy - Electrical	Electrical - Slab	1.8	3,000	04-Jan-21		04-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 501 B-Block, bill inward no is 196.
59747	Gulmohar Residency	B	401	1660 V/Bal Reddy - Electrical	Electrical - Slab	1.8	3,000	04-Jan-21		04-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 401 B-Block, bill inward no is 197.
59770	Gulmohar Residency	F	101	1360 N.Nagaraju - Electrical	Electrical - Slab	1.4	1,900	05-Jan-21		05-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 101 F-Block, bill inward no is 197.
59839	Gulmohar Residency	F	206	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	07-Jan-21		07-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 206 at F-Block, bill inward no is 191.
59840	Gulmohar Residency	A	402	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	07-Jan-21		07-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 402 at A-Block, bill inward no is 190.
59841	Gulmohar Residency	A	408	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	07-Jan-21		07-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 408 at A-Block, bill inward no is 190.
59842	Gulmohar Residency	A	409	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	07-Jan-21		07-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 409 at A-Block, bill inward no is 190.
59846	Gulmohar Residency	A	405	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	07-Jan-21		07-Jan-21	INR	doc_5f664e0849460.pdf	Towards slab electrical conducting work done for flat no 405 at A-Block, bill inward no is 192.

SS846 Gulmohar Residency	A	404	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	07-Jan-21	07-Jan-21	INR	doc_5f5fe14a78ec2.pdf	Slab electrical conducting work done for flat no 404 at A-Block. bill inward no is 192.
SS846 Gulmohar Residency	A	405	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	07-Jan-21	07-Jan-21	INR	doc_5f5fe13818c66.pdf	Slab electrical conducting work done for flat no 406 at A-Block. bill inward no is 192.
SS846 Gulmohar Residency	A	407	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	07-Jan-21	07-Jan-21	INR	doc_5f5fe13ae77415.pdf	Slab electrical conducting work done for flat no 407 at A-Block. bill inward no is 192.
SS855 Gulmohar Residency	B	502	1660 V.Bai Reddy - Electrical	Electrical - Slab	1.8	3,000	07-Jan-21	07-Jan-21	INR	doc_5f5feae01b46d.pdf	slab electrical conducting work done for flat no 502 B-Block. bill inward no is 196.
SS855 Gulmohar Residency	B	507	1660 V.Bai Reddy - Electrical	Electrical - Slab	1.8	3,000	07-Jan-21	07-Jan-21	INR	doc_5f5feae8288ee.pdf	slab electrical conducting work done for flat no 507 B-Block. bill inward no is 196.
SS855 Gulmohar Residency	B	508	1660 V.Bai Reddy - Electrical	Electrical - Slab	1.8	3,000	07-Jan-21	07-Jan-21	INR	doc_5f5feae080c4.pdf	slab electrical conducting work done for flat no 508 B-Block. bill inward no is 196.
SS855 Gulmohar Residency	B	402	1660 V.Bai Reddy - Electrical	Electrical - Slab	1.8	3,000	07-Jan-21	07-Jan-21	INR	doc_5f5feae7743200d.pdf	slab electrical conducting work done for flat no 402 B-Block. bill inward no is 197.
SS855 Gulmohar Residency	B	407	1660 V.Bai Reddy - Electrical	Electrical - Slab	1.8	3,000	07-Jan-21	07-Jan-21	INR	doc_5f5feae37d6413.pdf	slab electrical conducting work done for flat no 407 B-Block. bill inward no is 197.
SS855 Gulmohar Residency	B	408	1660 V.Bai Reddy - Electrical	Electrical - Slab	1.8	3,000	07-Jan-21	07-Jan-21	INR	doc_5f5feae086454.pdf	slab electrical conducting work done for flat no 408 B-Block. bill inward no is 197.
SS855 Gulmohar Residency	F	301	1360 N.Nagaji - Electrical	Electrical - Slab	1.8	2,500	10-Feb-21	10-Feb-21	INR	doc_60236664a4851.pdf	Towards slab electrical conducting work done for flat no 301 F-Block. bill inward no is 256.
SS455 Gulmohar Residency	A	503	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	18-Feb-21	18-Feb-21	INR	doc_602ae2a5a46852.pdf	Towards slab electrical conducting work done for flat no 503 A-Block. bill inward no is 271.
SS455 Gulmohar Residency	A	504	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	18-Feb-21	18-Feb-21	INR	doc_602ae3abbe8015.pdf	Towards slab electrical conducting work done for flat no 504 A-Block. bill inward no is 271.
SS455 Gulmohar Residency	A	505	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	18-Feb-21	18-Feb-21	INR	doc_602ae310e6910b.pdf	Towards slab electrical conducting work done for flat no 505 A-Block. bill inward no is 271.
SS455 Gulmohar Residency	A	505	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	18-Feb-21	18-Feb-21	INR	doc_602ae318515b1d.pdf	Towards slab electrical conducting work done for flat no 506 A-Block. bill inward no is 271.
SS455 Gulmohar Residency	A	507	1360 K.Ramakrishna	Electrical - Slab	1.8	2,500	18-Feb-21	18-Feb-21	INR	doc_602ae318515b1d.pdf	Towards slab electrical conducting work done for flat no 507 A-Block. bill inward no is 271.
SS455 Gulmohar Residency	A	501	1360 N.Nagaji - Electrical	Electrical - Slab	1.8	2,500	22-Feb-21	22-Feb-21	INR	doc_6033ae9c291ab.pdf	Towards Slab electrical work done for flat no 501A-Block. bill inward no is 277.
SS455 Gulmohar Residency	A	502	1360 N.Nagaji - Electrical	Electrical - Slab	1.8	2,500	22-Feb-21	22-Feb-21	INR	doc_6033ae9c291ab.pdf	Towards Slab electrical work done for flat no 502A-Block. bill inward no is 277.
SS455 Gulmohar Residency	A	508	1360 N.Nagaji - Electrical	Electrical - Slab	1.8	2,500	22-Feb-21	22-Feb-21	INR	doc_6033ae9c291ab.pdf	Towards Slab electrical work done for flat no 508A-Block. bill inward no is 277.
SS455 Gulmohar Residency	A	509	1360 N.Nagaji - Electrical	Electrical - Slab	1.8	2,500	22-Feb-21	22-Feb-21	INR	doc_6033ae9c291ab.pdf	Towards Slab electrical work done for flat no 509A-Block. bill inward no is 277.
SS455 Gulmohar Residency	F	102	1360 N.Nagaji - Electrical	Electrical - Slab	1.8	2,500	23-Feb-21	23-Feb-21	INR	doc_6034f7eeeb131e.pdf	Towards Slab electrical work done for flat no 102 F-Block. bill inward no is 280.
SS455 Gulmohar Residency	F	105	1360 N.Nagaji - Electrical	Electrical - Slab	1.8	2,500	23-Feb-21	23-Feb-21	INR	doc_6034f7eeeb131e.pdf	Towards Slab electrical work done for flat no 105 F-Block. bill inward no is 280.
SS782 Gulmohar Residency	A	403	1360 K.Ramakrishna	Electrical - Slab	5.1	7,000	16-Mar-21	16-Mar-21	INR	doc_6050373cb4bc3.pdf	Towards slab electrical pipes conducting work done for flat no 403 at A-Block. bill inward no is 302.
SS782 Gulmohar Residency	A	404	1360 K.Ramakrishna	Electrical - Slab	5.1	7,000	16-Mar-21	16-Mar-21	INR	doc_6050377745258.pdf	Towards slab electrical pipes conducting work done for flat no 404 at A-Block. bill inward no is 302.
SS782 Gulmohar Residency	A	405	1360 K.Ramakrishna	Electrical - Slab	5.1	7,000	16-Mar-21	16-Mar-21	INR	doc_605037747975.pdf	Towards slab electrical pipes conducting work done for flat no 405 at A-Block. bill inward no is 302.

60791 Gulmohar Residency	A	406	1360 K.Ramakrishna	Electrical - Slab	5.1	7,000	16-Mar-21	16-Mar-21	INR	doc_605037cfe1eca.pdf	Towards slab electrical pipes connecting work done for flat no 406 at A-block. bill inward no is 302.
60793 Gulmohar Residency	A	407	1360 K.Ramakrishna	Electrical - Slab	5.1	7,000	16-Mar-21	16-Mar-21	INR	doc_605037cfe1eca.pdf	Towards slab electrical pipes connecting work done for flat no 407 at A-block. bill inward no is 302.
61121 Gulmohar Residency	F	202	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	29-Mar-21	29-Mar-21	INR	doc_6061789ca29ca.pdf	Towards slab electrical conducting work done at F-Block. bill inward no is 323.
61122 Gulmohar Residency	F	205	1360 N.Nagaraju - Electrical	Electrical - Slab	1.8	2,500	29-Mar-21	29-Mar-21	INR	doc_6061789ca29ca.pdf	Towards slab electrical conducting work done at F-Block. bill inward no is 323.
60037 Gulmohar Residency	Misc		31540 O. Sweeny - Earth Work	Holes Drilling on rock	0.3	8,600	25-Jan-21	25-Jan-21	INR	doc_600a541be027.pdf	Towards dower holes drilling work done at D-Block. bill inward no is 263.
60267 Gulmohar Residency	D		0 B. Nareesh - Earth work	Holes Drilling on rock	0	35,600	10-Feb-21	10-Feb-21	INR	doc_6023670b70d15.pdf	Towards dower holes drilling work done at D-Block. bill inward no is 258.
60611 Gulmohar Residency	Misc		31540 B. Nareesh - Earth work	Holes Drilling on rock	0.8	23,800	05-Mar-21	05-Mar-21	INR	doc_6041d86e15d67.pdf	Towards dower holes drilling work done at D-Block. bill inward no is 287.
60861 Gulmohar Residency	Misc		31540 B. Nareesh - Earth work	Holes Drilling on rock	0.4	14,000	17-Mar-21	17-Mar-21	INR	doc_60514c605134a.pdf	Towards drilling holes on rock area at C,G & D Block. bill inward no is 308.
60444 Gulmohar Residency	CA		0 S.Mahesh (Painting)	Painting - Corridors	0	15,598	18-Feb-21	18-Feb-21	INR	doc_602e03a84b4ac.pdf	Towards painting work done for flat no 102 A-Block. bill inward no is 255.
60176 Gulmohar Residency	A	102	1360 S.Mahesh (Painting)	Painting - Inside flat	11.8	16,070	03-Feb-21	03-Feb-21	INR	doc_601a89b0d1441.pdf	Towards painting work done for flat no 103 A-Block. bill inward no is 255.
60177 Gulmohar Residency	A	103	1360 S.Mahesh (Painting)	Painting - Inside flat	11.8	16,070	03-Feb-21	03-Feb-21	INR	doc_601a89b0d1441.pdf	Towards painting work done for flat no 104 A-Block. bill inward no is 255.
60178 Gulmohar Residency	A	104	1360 S.Mahesh (Painting)	Painting - Inside flat	11.8	16,070	03-Feb-21	03-Feb-21	INR	doc_601a89b0d1441.pdf	Towards painting work done for flat no 105 A-Block. bill inward no is 255.
60179 Gulmohar Residency	A	105	1360 S.Mahesh (Painting)	Painting - Inside flat	11.8	16,070	03-Feb-21	03-Feb-21	INR	doc_601a89b0d1441.pdf	Towards painting work done for flat no 106 A-Block. bill inward no is 255.
60300 Gulmohar Residency	A	201	1360 S.Mahesh (Painting)	Painting - Inside flat	12	16,320	02-Mar-21	02-Mar-21	INR	doc_603e1c563d4de.pdf	Towards internal painting work done for flat no 201 A-block. bill inward no is 283.
60601 Gulmohar Residency	A	202	1360 S.Mahesh (Painting)	Painting - Inside flat	12	16,320	03-Mar-21	03-Mar-21	INR	doc_603f1094b0707.pdf	Towards internal painting work done for flat no 202 A-block. bill inward no is 283.
60602 Gulmohar Residency	A	203	1360 S.Mahesh (Painting)	Painting - Inside flat	12	16,320	03-Mar-21	03-Mar-21	INR	doc_603f1094b0707.pdf	Towards internal painting work done for flat no 203 A-block. bill inward no is 283.
60603 Gulmohar Residency	A	204	1360 S.Mahesh (Painting)	Painting - Inside flat	12	16,320	03-Mar-21	03-Mar-21	INR	doc_603f1094b0707.pdf	Towards internal painting work done for flat no 204 A-block. bill inward no is 283.
60604 Gulmohar Residency	A	205	1360 S.Mahesh (Painting)	Painting - Inside flat	12	16,320	03-Mar-21	03-Mar-21	INR	doc_603f1094b0707.pdf	Towards internal painting work done for flat no 205 A-block. bill inward no is 283.
60605 Gulmohar Residency	B	106	1660 Shoba Ram - Painting	Painting - Inside flat	30	49,800	05-Mar-21	05-Mar-21	INR	doc_6041d419a522.pdf	Towards inside flats painting work done at A-Block. bill inward no is 310.
60884 Gulmohar Residency	A	102	1360 S.Mahesh (Painting)	Painting - Inside flat	10.5	14,280	18-Mar-21	18-Mar-21	INR	doc_605303521945c.pdf	Towards inside flats painting work done at A-Block. bill inward no is 310.
60885 Gulmohar Residency	A	104	1360 S.Mahesh (Painting)	Painting - Inside flat	10.5	14,280	18-Mar-21	18-Mar-21	INR	doc_605303521945c.pdf	Towards inside flats painting work done at A-Block. bill inward no is 310.
60886 Gulmohar Residency	A	105	1360 S.Mahesh (Painting)	Painting - Inside flat	10.5	14,280	18-Mar-21	18-Mar-21	INR	doc_605303521945c.pdf	Towards inside flats painting work done at A-Block. bill inward no is 310.
60887 Gulmohar Residency	A	205	1360 S.Mahesh (Painting)	Painting - Inside flat	10.5	14,280	18-Mar-21	18-Mar-21	INR	doc_605303521945c.pdf	Towards inside flats painting work done at A-Block. bill inward no is 310.
60796 Gulmohar Residency	Misc		31540 S.Ramath jana	Plumbing - Misc.	0.3	9,620	16-Mar-21	16-Mar-21	INR	doc_60505e7ed3ba9.pdf	Towards HDPE pipe laying work come. bill inward no is 301.
55746 Gulmohar Residency	B	201	1660 Mohammed Khudooz - Plumbing	Plumbing-Inside flat	2.5	4,200	04-Jan-21	04-Jan-21	INR	doc_5f8eac8791ab.pdf	Towards inside plumbing works done for flat no 201 B-Block. bill inward no is 199.
55735 Gulmohar Residency	B	203	1660 Anirudh dhal	Plumbing-Inside flat	2.5	4,200	06-Jan-21	06-Jan-21	INR	doc_5f855b2762539.pdf	Towards inside plumbing works done for flat no 207 at B-Block. bill inward no is 207.
55960 Gulmohar Residency	B	202	1660 Mohammed Khudooz - Plumbing	Plumbing-Inside flat	2.5	4,200	07-Jan-21	07-Jan-21	INR	doc_5f8eac8791ab.pdf	Towards inside plumbing works done for flat no 202 B-Block. bill inward no is 199.
55961 Gulmohar Residency	B	207	1660 Mohammed Khudooz - Plumbing	Plumbing-Inside flat	2.5	4,200	07-Jan-21	07-Jan-21	INR	doc_5f8eac8791ab.pdf	Towards inside plumbing works done for flat no 202 B-Block. bill inward no is 199.
55962 Gulmohar Residency	B	208	1660 Mohammed Khudooz - Plumbing	Plumbing-Inside flat	2.5	4,200	07-Jan-21	07-Jan-21	INR	doc_5f8eac8791ab.pdf	Towards inside plumbing works done for flat no 208 B-Block. bill inward no is 199.

59885	Gulmohar Residency	B	304	1660 Srikanth Jene	Plumbing-Inside flat	2.5	4,200	12-Jan-21	12-Jan-21	INR	doc_5ffd289dc4f95.pdf	Inside plumbing works done for flat no 304 B-Block .bill Inward no is 219.
59886	Gulmohar Residency	B	305	1660 Srikanth Jene	Plumbing-Inside flat	2.5	4,200	12-Jan-21	12-Jan-21	INR	doc_5ffd2a6ce0ca8.pdf	Inside plumbing works done for flat no 305 B-Block .bill Inward no is 219.
59888	Gulmohar Residency	B	404	1660 Srikanth Jene	Plumbing-Inside flat	2.5	4,200	12-Jan-21	12-Jan-21	INR	doc_5ffd2ababf828.pdf	Inside plumbing works done for flat no 404 B-Block .bill Inward no is 219.
59890	Gulmohar Residency	B	405	1660 Srikanth Jene	Plumbing-Inside flat	2.5	4,200	12-Jan-21	12-Jan-21	INR	doc_5ffd2b0fedacc.pdf	Inside plumbing works done for flat no 405 B-Block .bill Inward no is 219.
59936	Gulmohar Residency	B	303	1660 Anirudh dhali	Plumbing-Inside flat	2.5	4,200	15-Jan-21	15-Jan-21	INR	doc_60011636ad091.pdf	Towards inside plumbing works done for flat no 303 at B-Block . bill Inward no is 207 .
59937	Gulmohar Residency	B	403	1660 Anirudh dhali	Plumbing-Inside flat	2.5	4,200	15-Jan-21	15-Jan-21	INR	doc_60011675721dd.pdf	Towards inside plumbing works done for flat no 403 at B-Block . bill Inward no is 207 .
59938	Gulmohar Residency	B	206	1660 Anirudh dhali	Plumbing-Inside flat	2.5	4,200	15-Jan-21	15-Jan-21	INR	doc_600116beaac2.pdf	Towards inside plumbing works done for flat no 206 at B-Block . bill Inward no is 207 .
59939	Gulmohar Residency	B	306	1660 Anirudh dhali	Plumbing-Inside flat	2.5	4,200	15-Jan-21	15-Jan-21	INR	doc_600116fcb852.pdf	Towards inside plumbing works done for flat no 306 at B-Block . bill Inward no is 207 .
59940	Gulmohar Residency	B	406	1660 Anirudh dhali	Plumbing-Inside flat	2.5	4,200	15-Jan-21	15-Jan-21	INR	doc_6001173508cd9.pdf	Towards inside plumbing works done for flat no 406 at B-Block . bill Inward no is 207 .
60274	Gulmohar Residency	A	301	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023bf5cae3d0.pdf	Towards inside flats plumbing works done for flat no 301 . Bill Inward no is 261.
60275	Gulmohar Residency	A	302	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023c0be7cb19.pdf	Towards inside flats plumbing works done for flat no 302 . Bill Inward no is 261.
60276	Gulmohar Residency	A	303	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023c0f518f40.pdf	Towards inside flats plumbing works done for flat no 303 . Bill Inward no is 261.
60277	Gulmohar Residency	A	304	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023c1215ab3f.pdf	Towards inside flats plumbing works done for flat no 304 . Bill Inward no is 261.
60278	Gulmohar Residency	A	305	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023c1644139c.pdf	Towards inside flats plumbing works done for flat no 305 . Bill Inward no is 261.
60279	Gulmohar Residency	A	306	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023c1ab94cd8.pdf	Towards inside flats plumbing works done for flat no 306 . Bill Inward no is 261.
60280	Gulmohar Residency	A	307	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023c263254bf.pdf	Towards inside flats plumbing works done for flat no 307 . Bill Inward no is 261.
60281	Gulmohar Residency	A	308	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	10-Feb-21	10-Feb-21	INR	doc_6023c28fb4594.pdf	Towards inside flats plumbing works done for flat no 308 . Bill Inward no is 261.
60440	Gulmohar Residency	B	301	1660 Mohammed Khudoos - Plumbing	Plumbing-Inside flat	2.5	4,200	17-Feb-21	17-Feb-21	INR	doc_602cfe610ef7a.pdf	Towards plumbing works done for flat no 301 at B-Block . Bill Inward no is 268 .
60441	Gulmohar Residency	B	302	1660 Mohammed Khudoos - Plumbing	Plumbing-Inside flat	2.5	4,200	17-Feb-21	17-Feb-21	INR	doc_602cfe612538f.pdf	Towards plumbing works done for flat no 302 at B-Block . Bill Inward no is 268 .
60442	Gulmohar Residency	B	307	1660 Mohammed Khudoos - Plumbing	Plumbing-Inside flat	2.5	4,200	17-Feb-21	17-Feb-21	INR	doc_602cfed98fc.pdf	Towards plumbing works done for flat no 307 at B-Block . Bill Inward no is 268 .
60443	Gulmohar Residency	B	308	1660 Mohammed Khudoos - Plumbing	Plumbing-Inside flat	2.5	4,200	17-Feb-21	17-Feb-21	INR	doc_602cff24e20d3.pdf	Towards plumbing works done for flat no 308 at B-Block . Bill Inward no is 268 .
60551	Gulmohar Residency	F	101	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	22-Feb-21	22-Feb-21	INR	doc_6033acf3ba409.pdf	Towards inside flats plumbing work done for flat no 101 F-Block . bill Inward no is 276.
60552	Gulmohar Residency	F	106	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	22-Feb-21	22-Feb-21	INR	doc_6033ad76af2cf.pdf	Towards inside flats plumbing work done for flat no 106 F-Block . bill Inward no is 276.
60557	Gulmohar Residency	F	101	1360 N.Nagaraju - Electrical	Plumbing-Inside flat	5.1	7,000	22-Feb-21	22-Feb-21	INR	doc_6033b15b3ff07.pdf	Towards inside flats electrical work done for flat no 101 F-Block . bill Inward no is 278.
60562	Gulmohar Residency	A	406	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	23-Feb-21	23-Feb-21	INR	doc_6034f7180797e.pdf	Towards inside flats plumbing work done for flat no 406 A-Block . bill Inward no is 279.
60563	Gulmohar Residency	A	407	1360 Srikanth jene	Plumbing-Inside flat	3.1	4,200	23-Feb-21	23-Feb-21	INR	doc_6034f768664d4.pdf	Towards inside flats plumbing work done for flat no 407 A-Block . bill Inward no is 279.

59824	Gulmohar Residency	A		403	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6a92bad8ae.pdf	Towards RCC slab 6 work done for flat no 403 at A-Block . bill Inward no is 208.
59825	Gulmohar Residency	A		404	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6a96232803.pdf	Towards RCC slab 6 work done for flat no 404 at A-Block . bill Inward no is 208.
59826	Gulmohar Residency	A		405	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6aa4d02173.pdf	Towards RCC slab 6 work done for flat no 40 at A-Block . bill Inward no is 208.
59827	Gulmohar Residency	A		406	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6aaa0b1144.pdf	Towards RCC slab 6 work done for flat no 406 at A-Block . bill Inward no is 208.
59828	Gulmohar Residency	A		407	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6aad8d76d1.pdf	Towards RCC slab 6 work done for flat no 407 at A-Block . bill Inward no is 208.
59829	Gulmohar Residency	A		401	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6ab1e34e13.pdf	Towards RCC slab 6 work done for flat no 401 at A-Block . bill Inward no is 210.
59830	Gulmohar Residency	A		402	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6ab4fc3fa3.pdf	Towards RCC slab 6 work done for flat no 402 at A-Block . bill Inward no is 210.
59831	Gulmohar Residency	A		408	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6ab8a34275.pdf	Towards RCC slab 6 work done for flat no 408 at A-Block . bill Inward no is 210.
59832	Gulmohar Residency	A		409	1360 Surasani Constructions Pvt Ltd	RCC-Slab 6	269.7	366,793	07-Jan-21	07-Jan-21	INR	doc_5ff6ac1ac14c4.pdf	Towards RCC slab 6 work done for flat no 409 at A-Block . bill Inward no is 210.
60516	Gulmohar Residency	A		407	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041e8248632b.pdf	A - Block. Bill Inward ID 292.
60517	Gulmohar Residency	A		408	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041e8b061efe.pdf	A - Block. Bill Inward ID 292.
60518	Gulmohar Residency	A		409	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041e9fc192e.pdf	A - Block 409 . Bill Inward ID 292.
60519	Gulmohar Residency	A		401	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041ea65bd064.pdf	A - Block 401 . Bill Inward ID 293.
60520	Gulmohar Residency	A		402	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041eabdb13ae.pdf	A - Block 402. Bill Inward ID 293.
60521	Gulmohar Residency	A		403	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041ea9707429.pdf	A - Block 403. Bill Inward ID 293.
60522	Gulmohar Residency	A		404	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041eb7f7744e.pdf	A - Block 404. Bill Inward ID 294.
60523	Gulmohar Residency	A		405	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041ebc726c49.pdf	A - Block 405. Bill Inward ID 294.
60524	Gulmohar Residency	A		406	1360 Surasani Constructions Pvt Ltd	RCC-Slab 7	269.7	366,793	05-Mar-21	05-Mar-21	INR	doc_6041ebfa5175e.pdf	A - Block 406. Bill Inward ID 294.
59836	Gulmohar Residency	Misc	Misc		31540 Varikuppala Raju - Earth Work - Misc.	Rock Cutting	12.2	384,424	07-Jan-21	07-Jan-21	INR	doc_5ff6c8ed090f5.pdf	Towards rock cutting work done at G-Block . bill Inward no is 213 .
60538	Gulmohar Residency	Misc	Misc		31540 Varikuppala Raju - Earth Work - Misc.	Rock Cutting	13.9	436,842	20-Feb-21	20-Feb-21	INR	doc_6030ff3c7ef3e.pdf	Towards rock cutting work done at G-Block part 3 . bill Inward no is 275 . (MD comment on bill-Deduct 1,20,000-fine and make separate statement & vouch
60991	Gulmohar Residency	D	Misc		D Varikuppala Raju - Earth Work - Misc.	Rock Cutting	0	170,000	25-Mar-21	25-Mar-21	INR	doc_605c1b4829aef.pdf	Towards rock cutting work done at D-Block . bill Inward no is 814 .
60258	Gulmohar Residency	A		201	1360 K.Krishna	Scaffolding	13.5	18,375	10-Feb-21	10-Feb-21	INR	doc_60236785be44e.pdf	Towards double scaffolding work done for plastering work for flat no 201 A-Block . bill Inward no is 257 .
60514	Gulmohar Residency	A		104	1360 Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	16.6	22,548	20-Mar-21	20-Mar-21	INR	doc_6055ab2ce04f8.pdf	Towards tiles flooring work done at A-Block . bill Inward no is 307 .
60515	Gulmohar Residency	A		105	1360 Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	16.6	22,548	20-Mar-21	20-Mar-21	INR	doc_6055ab6458fc3.pdf	Towards tiles flooring work done at A-Block . bill Inward no is 307 .
60516	Gulmohar Residency	A		205	1360 Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	16.6	22,548	20-Mar-21	20-Mar-21	INR	doc_6055aba86d0ab.pdf	Towards tiles flooring work done at A-Block . bill Inward no is 307 .
60564	Gulmohar Residency	A		102	1360 Janardhan prasad (Tiles)	Tiles fixing - Flat flooring	16.9	22,988	23-Mar-21	23-Mar-21	INR	doc_6059e0ee77412.pdf	Towards tiles flooring work done at A-Block . bill Inward no is 313 .
59900	Gulmohar Residency	Misc	Misc		31540 P Praveen kumar - Fabrication Work	Welding - Misc.	0.7	22,320	12-Jan-21	12-Jan-21	INR	doc_5ffd33876d753.pdf	Towards ms railings gates fabrication work done ms 3" l angles ms door frames making work done .bill Inward no is 218.
59768	Gulmohar Residency	A		101	1360 E.Ramababu	Windows	0.4	486	05-Jan-21	05-Jan-21	INR	doc_5ff428ce6e7cf.pdf	Towards MS grills fixing work done for flat no 101 at A-Block .bill Inward no is 146 .
59769	Gulmohar Residency	A		109	1360 E.Ramababu	Windows	0.4	486	05-Jan-21	05-Jan-21	INR	doc_5ff4291ac36b4.pdf	Towards MS grills fixing work done for flat no 109 at A-Block .bill Inward no is 146 .
59771	Gulmohar Residency	B		104	1660 E.Ramababu	Windows	0.2	356	05-Jan-21	05-Jan-21	INR	doc_5ff42970e7120.pdf	Towards MS grills fixing work done for flat no 104 at B-Block .bill Inward no is 146 .
59772	Gulmohar Residency	B		105	1660 E.Ramababu	Windows	0.2	356	05-Jan-21	05-Jan-21	INR	doc_5ff42970e7120.pdf	Towards MS grills fixing work done for flat no 105 at B-Block .bill Inward no is 146 .

*** The End ***

APPROVED BY
15 APR 2021
M. RAM PRASAD
PROJECT MANAGER