## Remarks from site on the 'Requisition by Site Report' of purchase division

Company:		MHPLSOV		Dat	te:	30-04-202	1	
		Silver Oak Villa	er Oak Villas part-III		pared by:	B.Meenakshi		
Report From / To 23-04		23-04-21 to 01-0	1-21 to 01-05-21(fri to sat)		proved by:	K Purshotham		
Report Date		30-04-2021						
List of requi	isitions num	bers missing in t	he repo	rt*:				
	THE RESERVE AND ADDRESS OF THE PARTY OF THE	re PO/WO not pr			s after requisition	on:		
Req No.			no of n Req	Item Description		Reason for not preparing PO/WO#		
185001	185001 23-04-2021		l	Ste	eel			
185002			-	RM				
List of requi	sitions when	e PO/WO is pre	pared a	nd items have n	ot been received	d at site beyond t	the lead time:	
Req No.	Req I		no of			Details of discussion with supplier <sup>s</sup>		
Items not ore Other correct	rt (MRN/oth dered but re- ctions & rem	n: 1 ner) & stock repo ceived: arks:	ort emai	Nil / 5	From No.  at to purchase?	Nill To	No. Yes / No	Nill
Details of sto	eel & cemen	it stock						
Sl. No	TO .	XX7.		XXI. C 10	0, 1	T. 1		
	Tor size	Wt per m	1000	Wt. for 12 mtr rod – kgs	Stock at site - no of rods	Stock at site i	n Previous st	ock in Kgs
1.	Tor size 8mm		1000	rod – kgs 4.74	- no of rods		n Previous st	ock in Kgs
2.			.395	rod – kgs	- no of rods		n Previous st	ock in Kgs
	8mm		.395	rod – kgs 4.74	- no of rods   -   -	Kgs -	n Previous st	ock in Kgs
2. 3. 4.	8mm 10mm		.395	rod – kgs 4.74 7.404	- no of rods 1	Kgs -	n Previous st	ock in Kgs
2. 3.	8mm 10mm 12mm		.395 .617 .89 1.58 2.47	rod – kgs 4.74 7.404 10.68	- no of rods  - no of rods	Kgs - -	n Previous st	ock in Kgs
2. 3. 4.	8mm 10mm 12mm 16mm		.395 .617 .89 1.58	rod – kgs 4.74 7.404 10.68 18.96	- no of rods  - no of rods	Kgs - - -	n Previous st	ock in Kgs
2. 3. 4. 5.	8mm 10mm 12mm 16mm 20mm		.395 .617 .89 1.58 2.47	rod – kgs 4.74 7.404 10.68 18.96 29.64	- no of rods  - no of rods	Kgs	n Previous st	ock in Kgs
2. 3. 4. 5. 6.	8mm 10mm 12mm 16mm 20mm 25mm	kgs	.395 .617 .89 1.58 2.47 3.86	rod – kgs 4.74 7.404 10.68 18.96 29.64 46.32	- no of rods  - no of rods	Kgs	n Previous st	ock in Kgs
2. 3. 4. 5. 6. 7.	8mm 10mm 12mm 16mm 20mm 25mm 32mm	kgs	.395 .617 .89 1.58 2.47 3.86 6.32	rod – kgs 4.74 7.404 10.68 18.96 29.64 46.32	- no of rods  - no of rods	Kgs		ock in Kgs
2. 3. 4. 5. 6. 7.	8mm 10mm 12mm 16mm 20mm 25mm 32mm Binding v	vire - OPC last	.395 .617 .89 1.58 2.47 3.86 6.32	rod – kgs 4.74 7.404 10.68 18.96 29.64 46.32 75.84 Nill	- no of rods - no	Kgs Nill Nill	Nill PPC/PSC last	
2. 3. 4. 5. 6. 7. 8. OPC stock	8mm 10mm 12mm 16mm 20mm 25mm 32mm Binding v	vire - OPC last weeks sto	.395 .617 .89 1.58 2.47 3.86 6.32	rod – kgs 4.74 7.404 10.68 18.96 29.64 46.32 75.84 Nill	- no of rods - no of rods	Kgs Nill Nill Nill	Nill PPC/PSC last weeks stock	

Notes: 1. \* Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <a href="mailto:purchase@modiproperties.com">purchase@modiproperties.com</a>, <a href="mailto:ashaiya@modiproperties.com">ashaiya@modiproperties.com</a> and <a href="mailto:rajkumarn@modiproperties.com">rajkumarn@modiproperties.com</a> on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. Suggested remarks – Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!