Remarks from site on the 'Requisition by Site Report' of purchase division

Company: Silve		Silver	er oak villas LLP		Date:			30-04-2021				
			er Oak Villas			Prepared by:		P.Aishwarya				
			4-2021 to 30-04-2021(Fri to		Approved by:			K.Purshotham				
			1-2021									
			issing in the rep	ort*:					100		-	
			WO not prepare		days	after requisit	tion:					
Reg-No.	Req Date				Description		Reason for not preparing PO/WO#					
156333	21-01-2021		1			name plate		2104501111	71 110	t propuring r	Ormo	
156334	22-01-2021		1-5	Window (
156340			1	Laptop Ch.		arger &						
156394	156394 22-02-2021		7	Broom I								
List of requi	sitions wh	ere PO/	WO is prepared	and items ha	ave no	t been receiv	red a	t site beyond	the l	ead time:		
Req No.			Serial no of item in Req.	rial no of Item		Description		Details of discussion with supplier ^{\$}				
156441	19-04-2021		1	Panel d		ors	No:			stock at SSLLP		
156440	40 17-04-2021		1			PLATE			with supplier, will be delivered be Monday			
Inward report Items not ord	t (MRN/c	other) & received:	24-04-2021, 26-0 stock report ema	iled in pdf f	format	to purchase'	?		1	Yes / No		
Details of ste				ew gate pass	S UUUK	with series s	Starti	ing from 343	i			
Sl. No	Tor size		Wt per mtr kgs	r Wt. for 12 rod - kgs		Stock at site – no of rods		Stock at site in Kgs		Previous stock in Kgs		
1.	8mm		.395		4.74	-						
2.	10mm		.617	7	7.404	-						
3.	12mm		.89	1	0.68	-	-					
4.	16mm		1.58	1	8.96	-						
5.	20mm	EAST T	2.47	2	9.64	-						
6.	25mm		3.86 46.3		6.32	-						
7.	32mm		6.32	7	5.84							
8.	Binding	wire				•						
PC stock			OPC last weeks stock			PPC/PSC stock		0		PC/PSC last eeks stock	0	
Details			Project Manager			Admin Officer/Manager			-	dmin Audit		
Sign			A CONTRACTOR OF THE PROPERTY O			Ashways						
Date			30-04-2021			30-04-2021						

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <u>purchase@modiproperties.com</u>, <u>ashaiya@modiproperties.com</u> and <u>rajkumarn@modiproperties.com</u> on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks – Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!