## Remarks from site on the 'Requisition by Site Report of purchase division

Company:	Modi	Realty Miryalage	ıda LLP	Date:	. <u>.</u>	21-06-2021	
		Gulmohar Homes		Prepared by:		Zakir	
Report From / To 12-06		5-2021 to 21-06-2021		Approved by:			
Report Date	-2021	11		·-			
List of requisitions numbers missing in the report							
List of requisitions where PO/WO not prepared 3 working days after requisition:							
Req No.	Req Date	Serial no of item in Req.	Item Description		Reason for not preparing PO/WO		
165362	28-04-2021	1 to 6	Fisher plugs		PO to	PO to be issue	
165296	11-02-21	1 to 8	AL.Windows		PO to be issue		
165374	26-05-2021	1 to 3	Paint m	aterials	PO to be issue		
165393	21-06-2021	1 to 2	Tan brown granite		PO to be issue		
165394	21-06-2021	1 to 6	Villa tiles		PO to be issue		
165396	21-06-2021	1 to 9	Electrical pipes		PO to be issue		
List of requisitions where PO/WO is prepared and items have not been received at site beyond the lead time:							
Req. No.	Req. Date	Serial no of item in Req.	Item Description		Details of discussion with supplier		
165250	4.1.2021	1 to 4	Door frames		90% received; remaining will delivered by next week		
165310	22-02-2021	1 to 09	Panel door		95% received; remaining will		
165324	05-06-2021	4	Earth beige tiles		delivered by next week 90% material received at site		
165334	26-03-2021	1&7	Windows grill			eceived; remaining will	
165336	26-03-2021	11	Bathroom tiles		delivered by next week 90% received materials at site		
165351	20-04-2021	1 & 2	Armored cable		90% received materials at site		
165355	23-04-2021	1to 4	Utility tiles		Tomorrow will be delivered		
165365	07-05-2021	1 to 22	Consumable items		80% received material at site		
165370	19-05-2021	1	Road Blockers		Ready to supplies		
165375	28-05-2021	1 to 2	Gate light		Ready to supplies		
165376	28-05-2021	1	Video door phone		Ready to supplies		
165379	05-06-2021	1	Spring wire		Ready to supplies		
165380	05-06-2021	1 to 4	Oxides		Ready to supplies		
165381	05-06-2021	1 to 2	Cards key rings		Ready to supplies		
165383	05-06-2021	3 & 5	Tiles		Ready to supplies		
165386	12-06-2021	1	2.5HP Cutter pump		Ready to supplies		
165388	12-06-2021	1	Villa Railing		Ready to supplies		
165389	12-06-2021	1 to 3	Carpet lawn		Ready to supplies		
165391	12-06-2021	1 to 38	PVC pipes		Ready to supplies		
165392	12-06-2021	1 TO 41	CPVC pipes		Ready to supplies		
165390	12-06-2021	1	Bosch machine		Ready to supplies		
165395	21-06-2021	l	Cement		Ready to supplies		
165397	21-06-2021	1 to 2	Flat patti L angle		Ready to supplies		
165398	21-06-2021	<del></del>	Altek Luppum		Ready to supplies		
No. of gate passes issued this week:					1434	To No. 1435	
Delivery van last site visit on: 13-06-2021							
Inward report (MRN/other) & stock report emailed in pdf format to Yes purchase?							
DC register Sl.No. during the week From No. 14635 To No. 14658							
Items not ordered but received:							
Other corrections & remarks: We have send 2HP Submersible pump for repairing purpose to SVR pump service center.							
Details		roject Manager	T A	Admin Officer/I		Admin Audit	
Sign Jan 1 J							

Notes: 1. \* Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <u>purchase@modiproperties.com</u>, <u>ashaiya@modiproperties.com</u> and <u>rajkumam@modiproperties.com</u> on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks — For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks — Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site — purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up — DO NOT CALL PURCHASE!

.