## Remarks from site on the 'Requisition by Site Report' of purchase division

Company: MHPL		SOV		Date:			03-07-2021			
		er Oak Villas part-I	П	Prepared by:			B.Meenakshi			
Report From / To 25-06- to Sat)		-2021 to 02-07-2021(Fri		Approved by:			K Purshotham			
Report Date	03-0	7-2021								
List of requis	itions numbers	missing in the repo	ort*:							
List of requis	itions where PO	O/WO not prepared	3 working	days a	after requis	ition:				
Req No.	Req Date		Item Descr			n Reason for r			t preparing PO	D/WO#
185007	01.06.21	1	Sim based Landli Telephone		dline					
185011 07-06-21		1	MI camera							
List of requis		O/WO is prepared a	and items ha	ave not	been recei	ived a	t site bey	ond the 1	ead time:	
Req No.	Req Date			Item Description		Details of discussion with supplier <sup>s</sup>				
185014	08-06-2021			Curb Stone		Material ready with supplier will be delivered by next week				
	asses issued thi	s week:		Nil / 5 From No.			Nill To No. Nill 2021, 01.07.21,02.07.21			
Delivery van	site visit on:1						, 01.07.	21,02.07.		
Inward repor	t (MRN/other)	& stock report ema	illed in pdf	tormat	to purchas	se?			Yes / No	
Items not ord	lered but receiv	ed:								
Other correct	ions & remarks	S:								
Details of ste	el & cement sto	ock								
Sl. No	Tor size	Wt per mtr kgs	Wt. for 12 rod – kgs	Wt. for 12 mtr rod – kgs		site ods	Stock at site in Kgs		Previous stock in Kgs	
1.	8mm	.395		4.74	450		-			
2.	10mm	.617		7.404	420	-				
3.	12mm	.89		10.68	105		-			
4.	16mm	1.58		18.96			-	NEW YORK		
5.	20mm	2.47		29.64			-			
6.	25mm	3.86		46.32	-		-			
7.	32mm	6.32		75.84	-		-			
8.	Binding wire	-			Nill		Nill		Nill	
OPC stock	Nill	OPC last weeks stock	Nill		PPC/PSC stock				PPC/PSC last veeks stock	Nill
Details			Project Manager		Admin Office		cer/Manager A		Admin Audit	
Sign		The state of the s			Munaku					
		The state of the s			Mu	mak				

Notes: 1. \* Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <a href="mailto:purchase@modiproperties.com">purchase@modiproperties.com</a>, <a href="mailto:ashaiya@modiproperties.com">ashaiya@modiproperties.com</a>, ashaiya@modiproperties.com</a> and <a href="mailto:rajkumarn@modiproperties.com">rajkumarn@modiproperties.com</a> on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis.

5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks – Ready with supplier, Supplier not contacted/, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!