Remarks from site on the 'Requisition by Site Report' of purchase division

Company: MHP		MHPL	LSOV		Date:			10-07-2021			
		Silver	r Oak Villas part-III			Prepared by:		B.Meenakshi			
			7-2021 to 10-07-2021(Fri to		Approved by:			K Purshotham			
Report Date 10-07			-2021								
List of requi	sitions num	nbers m	issing in the repo	ort*:							
List of requi	sitions whe	ere PO/	WO not prepared	3 working	g days	after requis	ition:				
Req No.	eq No. Req Date		Serial no of item in Req	Item Desc		ription		Reason for not preparing PO/WO#			
185007	185007 01.06.21		1		Sim based Landline Telephone						
185011 07-06-2		6-21	1	MI cam	MI camera						
List of requi	sitions whe	ere PO/	WO is prepared a			t been recei	ved at	site bey	ond the	lead time:	
Req No. Req Date			Serial no of item in Req.	Item Description				Details of discussion with supplier\$			
185014 08-06-2021		-2021	1	Curb St	Curb Stone		Mate	laterial ready with supplier delivery by Monday			
No. of gate p	passes issue	ed this v	veek:	Nil / 5	F	From No.	N	ill	To No		Nill
Delivery var						05-07-2021	-	-			
			stock report ema							Yes / No	
Items not ord			-								
Other correc											
Details of ste		The second second second		ne see a dimension of							
Sl. No	Tor size		Wt per mtr	Wt. for 12	2 mtr	Stock at s	ite	e Stock at site in		Previous stock in Kgs	
			kgs	rod - kgs	- no of ro		ods Kgs				
1.	8mm		.395	4.74		450				2025	
2.	10mm		.617	7.404		420		-		3150	
3.	12mm		.89	10.68		105		•		1120	
4.	4, 16mm		1.58	18.96		-					
5.	5. 20mm		2.47	29.64		-		-			
6.	6. 25mm		3.86	46.32		-					
7.	7. 32mm		6.32	75.8		-		-			
8.	Binding	wire				Nill	Nill			Nill	
OPC stock	The same of the sa		OPC last weeks stock			PPC/PSC stock	1			PPC/PSC last veeks stock	Nill
Details			Project Manager							Admin Audit	
Sign			75			Newatrhi					
Sign			0/ 2			10 100	V CV V V				

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks – Ready with supplier, Supplier not contacted/, Supplier not reachable, Material in transit, WO – under fabrication, WO – material for fabrication not received, WO – material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!