

QC - Concrete Cube Testing Report.															
Company:		SOVLLP													
Project:		SOV													
Report for Month:		Apr - July = 2021.													
Prepared By:		QC Team													
Date:		28-07-2021													
S. No.	Date of casting	Site Mix or RMC	Specified Grade of Concrete	Supplier / Contractor	D. C. No	Block No. / Bungalow No.	Used for Slab / Columns	Slab No. or Column No.	Date of Testing	No. of days	Specified Strength	Tested Strength Kilo-newtons	Tested Strength in N per sq. mm	Avg. of three tests	Remarks
7463	30-03-2021	RMC	M20	Ishaq		163	footing		7-4-21	8	14.0	345.0	15.3		
											14.0	340.0	15.1	14.9	
											14.0	320.0	14.2		
7463	30-03-2021	RMC	M20	Ishaq		163	footing		28-4-21	29	20.0	465.0	20.7		
											20.0	460.0	20.4	20.4	
											20.0	455.0	20.2		
7464	30-03-2021	RMC	M20	Ishaq		182	footing		7-4-21	8	14.0	340.0	15.1		
											14.0	335.0	14.9	14.8	
											14.0	325.0	14.4		
7464	30-03-2021	RMC	M20	Ishaq		182	footing		28-4-21	29	20.0	470.0	20.9		
											20.0	465.0	20.7	20.7	
											20.0	460.0	20.4		
7465	05-04-2021	RMC	M20	SCPL		123	slab	1	14-4-21	9	14.0	335.0	14.9		
											14.0	330.0	14.7	14.6	
											14.0	320.0	14.2		
7465	05-04-2021	RMC	M20	SCPL		123	slab	1	4-5-21	29	20.0	465.0	20.7		
											20.0	460.0	20.4	20.4	
											20.0	455.0	20.2		
7466	05-04-2021	RMC	M20	RCPL		101	slab	3	14-4-21	9	14.0	330.0	14.7		
											14.0	325.0	14.4	14.4	
											14.0	315.0	14.0		
7466	05-04-2021	RMC	M20	RCPL		101	slab	3	4-5-21	29	20.0	460.0	20.4		
											20.0	455.0	20.2	20.2	
											20.0	450.0	20.0		
7467	05-04-2021	RMC	M20	RCPL		102	slab	3	14-4-21	9	14.0	325.0	14.4		
											14.0	320.0	14.2	14.1	
											14.0	310.0	13.8		
7467	05-04-2021	RMC	M20	RCPL		102	slab	3	4-5-21	29	20.0	455.0	20.2		
											20.0	450.0	20.0	20.1	
											20.0	450.0	20.0		
7468	06-04-2021	RMC	M20	RCPL		109	plinth		14-4-21	8	14.0	330.0	14.7		
											14.0	325.0	14.4	14.4	
											14.0	315.0	14.0		
7468	06-04-2021	RMC	M20	RCPL		109	plinth		4-5-21	28	20.0	460.0	20.4		
											20.0	455.0	20.2	20.3	
											20.0	455.0	20.2		
7469	06-04-2021	RMC	M25	RCPL		107	Col	1	14-4-21	8	17.5	390.0	17.3		
											17.5	395.0	17.6	17.6	
											17.5	400.0	17.8		
7469	06-04-2021	RMC	M25	RCPL		107	Col	1	4-5-21	28	25.0	590.0	26.2		
											25.0	590.0	26.2	26.4	
											25.0	605.0	26.9		
7470	14-04-2021	RMC	M20	SCPL		143	plinth		22-4-21	8	14.0	335.0	14.9		
											14.0	330.0	14.7	14.6	
											14.0	320.0	14.2		
7470	14-04-2021	RMC	M20	SCPL		143	plinth		22-4-21	8	14.0	335.0	14.9		
											14.0	330.0	14.7	14.6	
											14.0	320.0	14.2		

7471	16-04-2021	RMC	M20	SCPL		125	slab	2	22-4-21	6	14.0	330.0	14.7			
											14.0	325.0	14.4	14.4		
											14.0	315.0	14.0			
7472	21-04-2021	RMC	M20	RCPL		105	slab	2	30-4-21	9	14.0	345.0	15.3			
											14.0	340.0	15.1	15.1		
											14.0	335.0	14.9			
7473	22-04-2021	RMC	M20	SCPL		144	plinth		30-4-21	8	14.0	340.0	15.1			
											14.0	335.0	14.9	14.8		
											14.0	325.0	14.4			
7474	22-04-2021	RMC	M25	RCPL		110	Col	1	30-4-21	8	17.5	390.0	17.3			
											17.5	395.0	17.6	17.6		
											17.5	400.0	17.8			
7475	23-04-2021	RMC	M25	RCPL		115	Col	2	30-4-21	7	17.5	395.0	17.6			
											17.5	400.0	17.8	17.9		
											17.5	410.0	18.2			
7476	24-04-2021	RMC	M25	RCPL		114	Col	2	30-4-21	6	17.5	385.0	17.1			
											17.5	385.0	17.1	17.2		
											17.5	390.0	17.3			
7477	26-04-2021	RMC	M20	RCPL		120	plinth		4-5-21	8	14.0	340.0	15.1			
											14.0	335.0	14.9	14.8		
											14.0	325.0	14.4			
7478	26-04-2021	RMC	M20	RCPL		108	plinth		4-5-21	8	14.0	345.0	15.3			
											14.0	345.0	15.3	15.1		
											14.0	330.0	14.7			
7479	27-04-2021	RMC	M25	SCPL		124	Col	2	4-5-21	7	17.5	390.0	17.3			
											17.5	395.0	17.6	17.6		
											17.5	400.0	17.8			
7480	05-05-2021	RMC	M20	Ishaq		164	footing		14-5-21	9	14.0	350.0	15.6			
											14.0	350.0	15.6	15.4		
											14.0	340.0	15.1			
7481	05-05-2021	RMC	M20	Ishaq		165	footing		14-5-21	9	14.0	355.0	15.8			
											14.0	355.0	15.8	15.6		
											14.0	345.0	15.3			
7482	05-05-2021	RMC	M20	Ishaq		180	footing		14-5-21	9	14.0	360.0	16.0			
											14.0	360.0	16.0	15.9		
											14.0	350.0	15.6			
7483	05-05-2021	RMC	M20	Ishaq		181	footing		14-5-21	9	14.0	365.0	16.2			
											14.0	365.0	16.2	16.1		
											14.0	355.0	15.8			
7484	06-05-2021	RMC	M25	RCPL		109	Col	1	14-5-21	8	17.5	390.0	17.3			
											17.5	395.0	17.6	17.6		
											17.5	405.0	18.0			

7485	07-05-2021	RMC	M20	SCPL		132	slab	1	14-5-21	7	14.0	315.0	14.0			
											14.0	315.0	14.0	14.1		
											14.0	320.0	14.2			
7486	10-05-2021	RMC	M25	RCPL		108	Col	1	18-5-21	8	17.5	395.0	17.6			
											17.5	400.0	17.8	17.9		
											17.5	410.0	18.2			
7495	09-06-2021	RMC	M20	RCPL		103	slab	2	17-6-21	8	14.0	315.0	14.0			
											14.0	315.0	14.0	14.1		
											14.0	320.0	14.2			
7495	09-06-2021	RMC	M20	RCPL		103	slab	2	7-7-21	28	20.0	450.0	20.0			
											20.0	465.0	20.7	20.3		
											20.0	455.0	20.2			
7496	09-06-2021	RMC	M25	SCPL		132	Col	2	17-6-21	8	17.5	415.0	18.4			
											17.5	415.0	18.4	18.5		
											17.5	420.0	18.7			
7496	09-06-2021	RMC	M25	SCPL		132	Col	2	7-7-21	28	25.0	585.0	26.0			
											25.0	580.0	25.8	25.6		
											25.0	560.0	24.9			
7497	09-06-2021	RMC	M20	RCPL		104	slab	3	17-6-21	8	14.0	320.0	14.2			
											14.0	320.0	14.2	14.3		
											14.0	325.0	14.4			
7497	09-06-2021	RMC	M20	RCPL		104	slab	3	7-7-21	28	20.0	445.0	19.8			
											20.0	445.0	19.8	20.2		
											20.0	475.0	21.1			
7498	09-06-2021	RMC	M20	RCPL		109	plinth		17-6-21	8	14.0	325.0	14.4			
											14.0	325.0	14.4	14.5		
											14.0	330.0	14.7			
7498	09-06-2021	RMC	M20	RCPL		109	plinth		7-7-21	28	20.0	450.0	20.0			
											20.0	450.0	20.0	20.3		
											20.0	470.0	20.9			
7499	11-06-2021	RMC	M20	Ishaq		160	footing		19-6-21	8	14.0	325.0	14.4			
											14.0	325.0	14.4	14.4		
											14.0	320.0	14.2			
7499	11-06-2021	RMC	M20	Ishaq		160	footing		9-7-21	28	20.0	465.0	20.7			
											20.0	455.0	20.2	20.3		
											20.0	450.0	20.0			
7500	11-06-2021	RMC	M20	Ishaq		185	footing		19-6-21	8	14.0	330.0	14.7			
											14.0	330.0	14.7	14.6		
											14.0	325.0	14.4			
7500	11-06-2021	RMC	M20	Ishaq		185	footing		9-7-21	28	20.0	470.0	20.9			
											20.0	460.0	20.4	20.5		
											20.0	455.0	20.2			
7501	12-06-2021	RMC	M20	SCPL		142	plinth		19-6-21	7	14.0	325.0	14.4			
											14.0	320.0	14.2	14.3		
											14.0	320.0	14.2			
7501	12-06-2021	RMC	M20	SCPL		142	plinth		9-7-21	27	20.0	465.0	20.7			
											20.0	450.0	20.0	20.1		
											20.0	445.0	19.8			
7502	15-06-2021	RMC	M25	RCPL		117	Col	1	23-6-21	8	17.5	395.0	17.6			
											17.5	390.0	17.3	17.7		
											17.5	410.0	18.2			
7502	15-06-2021	RMC	M25	RCPL		117	Col	1	13-7-21	28	25.0	585.0	26.0			
											25.0	585.0	26.0	26.1		
											25.0	595.0	26.4			
7503	18-06-2021	RMC	M20	RCPL		112	slab	1	26-6-21	8	14.0	325.0	14.4			
											14.0	325.0	14.4	14.3		
											14.0	315.0	14.0			

7503	18-06-2021	RMC	M20	RCPL		112	slab	1	16-7-21	28	20.0	470.0	20.9			
											20.0	455.0	20.2	20.4		
											20.0	455.0	20.2			
7504	21-06-2021	RMC	M25	RCPL		120	Col	1	29-6-21	8	17.5	390.0	17.3			
											17.5	385.0	17.1	17.5		
											17.5	405.0	18.0			
7504	21-06-2021	RMC	M25	RCPL		120	Col	1	19-7-21	28	25.0	590.0	26.2			
											25.0	585.0	26.0	26.4		
											25.0	605.0	26.9			
7505	22-06-2021	RMC	M20	SCPL		141	plinth		29-6-21	7	14.0	345.0	15.3			
											14.0	335.0	14.9	14.9		
											14.0	325.0	14.4			
7505	22-06-2021	RMC	M20	SCPL		141	plinth		19-7-21	27	20.0	455.0	20.2			
											20.0	465.0	20.7	20.7		
											20.0	480.0	21.3			
7506	22-06-2021	RMC	M25	RCPL		119	Col	1	29-6-21	7	17.5	395.0	17.6			
											17.5	390.0	17.3	17.6		
											17.5	405.0	18.0			
7506	22-06-2021	RMC	M25	RCPL		119	Col	1	19-7-21	27	25.0	575.0	25.6			
											25.0	585.0	26.0	25.9		
											25.0	590.0	26.2			
7507	26-06-2021	RMC	M20	Ishaq		183	plinth		3-7-21	7	14.0	340.0	15.1			
											14.0	330.0	14.7	14.7		
											14.0	320.0	14.2			
7507	26-06-2021	RMC	M20	Ishaq		183	plinth		24-7-21	28	20.0	450.0	20.0			
											20.0	460.0	20.4	20.5		
											20.0	475.0	21.1			
7508	26-06-2021	RMC	M20	Ishaq		162	plinth		3-7-21	7	14.0	350.0	15.6			
											14.0	340.0	15.1	15.1		
											14.0	330.0	14.7			
7508	26-06-2021	RMC	M20	Ishaq		162	plinth		24-7-21	28	20.0	460.0	20.4			
											20.0	470.0	20.9	20.8		
											20.0	475.0	21.1			
7509	29-06-2021	RMC	M25	SCPL		140	Col	1	7-7-21	8	17.5	405.0	18.0			
											17.5	400.0	17.8	18.1		
											17.5	415.0	18.4			
7509	29-06-2021	RMC	M25	SCPL		140	Col	1	27-7-21	28	25.0	590.0	26.2			
											25.0	590.0	26.2	26.1		
											25.0	585.0	26.0			
7510	30-06-2021	RMC	M20	SCPL		133	slab	1	9-7-21	9	14.0	345.0	15.3			
											14.0	335.0	14.9	14.9		
											14.0	325.0	14.4			
7511	30-06-2021	RMC	M20	SCPL		134	slab	1	9-7-21	9	14.0	340.0	15.1			
											14.0	330.0	14.7	14.7		
											14.0	320.0	14.2			
7512	30-06-2021	RMC	M20	SCPL		135	slab	1	9-7-21	9	14.0	335.0	14.9			
											14.0	325.0	14.4	14.4		
											14.0	315.0	14.0			
7513	30-06-2021	RMC	M20	SCPL		122	slab	1	9-7-21	9	14.0	330.0	14.7			
											14.0	320.0	14.2	14.2		
											14.0	310.0	13.8			
7514	30-06-2021	RMC	M25	SCPL		142	Col	1	9-7-21	9	17.5	405.0	18.0			
											17.5	390.0	17.3	17.6		
											17.5	390.0	17.3			
7515	01-07-2021	RMC	M25	SCPL		141	Col	1	9-7-21	8	17.5	385.0	17.1			
											17.5	385.0	17.1	17.3		
											17.5	395.0	17.6			
7516	01-07-2021	RMC	M25	RCPL		112	Col	2	9-7-21	8	17.5	405.0	18.0			
											17.5	395.0	17.6	17.6		
											17.5	390.0	17.3			

7517	01-07-2021	RMC	M20	Shravan		148	footing		9-7-21	8	14.0	335.0	14.9			
											14.0	325.0	14.4	14.4		
											14.0	310.0	13.8			
7518	01-07-2021	RMC	M20	Ishaq		163	plinth		9-7-21	8	14.0	340.0	15.1			
											14.0	330.0	14.7	14.6		
											14.0	315.0	14.0			
7519	01-07-2021	RMC	M20	Ishaq		182	plinth		9-7-21	8	14.0	345.0	15.3			
											14.0	335.0	14.9	14.8		
											14.0	320.0	14.2			
7520	03-07-2021	RMC	M20	RCPL		107	slab	1	10-7-21	7	14.0	350.0	15.6			
											14.0	340.0	15.1	15.0		
											14.0	325.0	14.4			
7521	06-07-2021	RMC	M25	SCPL		139	Col	1	14-7-21	8	17.5	410.0	18.2			
											17.5	390.0	17.3	17.7		
											17.5	395.0	17.6			
7522	06-07-2021	RMC	M20	SCPL		145	plinth		14-7-21	8	14.0	340.0	15.1			
											14.0	330.0	14.7	14.7		
											14.0	325.0	14.4			
7523	06-07-2021	RMC	M20	Ishaq		181	plinth		14-7-21	8	14.0	345.0	15.3			
											14.0	335.0	14.9	15.1		
											14.0	340.0	15.1			
7524	06-07-2021	RMC	M25	SCPL		133	Col	2	14-7-21	8	17.5	415.0	18.4			
											17.5	415.0	18.4	18.1		
											17.5	390.0	17.3			
7525	07-07-2021	RMC	M25	SCPL		122	Col	2	14-7-21	7	17.5	390.0	17.3			
											17.5	395.0	17.6	17.5		
											17.5	395.0	17.6			
7526	07-07-2021	RMC	M25	RCPL		110	Col	2	14-7-21	7	17.5	395.0	17.6			
											17.5	400.0	17.8	17.9		
											17.5	410.0	18.2			
7527	07-07-2021	RMC	M25	SCPL		135	Col	2	14-7-21	7	17.5	390.0	17.3			
											17.5	395.0	17.6	17.4		
											17.5	390.0	17.3			
7528	07-07-2021	RMC	M20	RCPL		111	slab	1	14-7-21	7	14.0	315.0	14.0			
											14.0	325.0	14.4	14.1		
											14.0	310.0	13.8			
											-					
7529	10-07-2021	RMC	M20	Ishaq		166	footing		17-7-21	7	14.0	320.0	14.2			
											14.0	320.0	14.2	14.3		
											14.0	325.0	14.4			
7530	10-07-2021	RMC	M20	Ishaq		167	footing		17-7-21	7	14.0	325.0	14.4			
											14.0	325.0	14.4	14.5		
											14.0	330.0	14.7			
7531	12-07-2021	RMC	M25	RCPL		107	Col	2	20-7-21	8	17.5	395.0	17.6			
											17.5	395.0	17.6	17.5		
											17.5	390.0	17.3			
7532	12-07-2021	RMC	M20	Shravan		149	footing		20-7-21	8	14.0	330.0	14.7			
											14.0	335.0	14.9	14.7		
											14.0	330.0	14.7			
7533	14-07-2021	RMC	M20	Ishaq		164	plinth		20-7-21	6	14.0	335.0	14.9			
											14.0	345.0	15.3	14.8		
											14.0	320.0	14.2			
7534	14-07-2021	RMC	M25	Ishaq		182	Col	1	20-7-21	6	17.5	400.0	17.8			
											17.5	410.0	18.2	18.1		
											17.5	410.0	18.2			
7535	14-07-2021	RMC	M20	SCPL		144	slab	1	20-7-21	6	14.0	330.0	14.7			
											14.0	340.0	15.1	14.7		
											14.0	325.0	14.4			
7536	15-07-2021	Site Mix	M25	SCPL		124	Col	3	24-7-21	9	17.5	395.0	17.6			
											17.5	395.0	17.6	17.8		
											17.5	410.0	18.2			

7537	16-07-2021	RMC	M20	RCPL		109	slab	1	24-7-21	8	14.0 14.0 14.0	315.0 315.0 310.0	14.0 14.0 13.8	13.9			
7538	16-07-2021	RMC	M20	SCPL		132	slab	2	24-7-21	8	14.0 14.0 14.0	330.0 310.0 310.0	14.7 13.8 13.8	14.1			
7539	16-07-2021	RMC	M20	RCPL		105	slab	3	24-7-21	8	14.0 14.0 14.0	345.0 315.0 320.0	15.3 14.0 14.2	14.5			
7540	17-07-2021	RMC	M25	Ishaq		163	Col	1	24-7-21	7	17.5 17.5 17.5	405.0 395.0 425.0	18.0 17.6 18.9	18.1			
7541	19-07-2021	RMC	M20	Ishaq		165	plinth		27-7-21	8	14.0 14.0 14.0	355.0 320.0 310.0	15.8 14.2 13.8	14.6			
7542	19-07-2021	RMC	M25	Ishaq		162	Col	1	27-7-21	8	17.5 17.5 17.5	400.0 390.0 385.0	17.8 17.3 17.1	17.4			
7543	19-07-2021	RMC	M20	SCPL		137	plinth		27-7-21	8	14.0 14.0 14.0	345.0 315.0 305.0	15.3 14.0 13.6	14.3			
7544	19-07-2021	RMC	M25	RCPL		111	Col	2	27-7-21	8	17.5 17.5 17.5	405.0 395.0 395.0	18.0 17.6 17.6	17.7			
7545	20-07-2021	RMC	M25	SCPL		145	Col	1	27-7-21	7	17.5 17.5 17.5	410.0 390.0 405.0	18.2 17.3 18.0	17.9			
7546	20-07-2021	RMC	M25	Ishaq		183	Col	1	27-7-21	7	17.5 17.5 17.5	410.0 395.0 390.0	18.2 17.6 17.3	17.7			
7547	20-07-2021	Site Mix	M25	SCPL		132	Col	3	27-7-21	7	17.5 17.5 17.5	395.0 395.0 410.0	17.6 17.6 18.2	17.8			
7548	23-07-2021	RMC	M25	SCPL		144	Col	2	31-7-21	8	17.5 17.5 17.5	425.0 410.0 390.0	18.9 18.2 17.3	18.1			
7549	23-07-2021	RMC	M20	SCPL		123	slab	2	31-7-21	8	14.0 14.0 14.0	345.0 315.0 305.0	15.3 14.0 13.6	14.3			
7550	23-07-2021	RMC	M20	RCPL		116	slab	3	31-7-21	8	14.0 14.0 14.0	350.0 325.0 315.0	15.6 14.4 14.0	14.7			
7551	24-07-2021	RMC	M25	Ishaq		181	Col	1	31-7-21	7	17.5 17.5 17.5	410.0 395.0 395.0	18.2 17.6 17.6	17.8			
7552	24-07-2021	RMC	M20	Ishaq		179	footing		31-7-21	7	14.0 14.0 14.0	350.0 325.0 325.0	15.6 14.4 14.4	14.8			
7553	24-07-2021	RMC	M20	RCPL		106	slab	1	31-7-21	7	14.0 14.0 14.0	340.0 320.0 310.0	15.1 14.2 13.8	14.4			