Remarks from site on the 'Requisition by Site Report' of purchase division

IVIC	Mehta&Modi Realty Kowkur		Date:	22-01-202	22-01-2022	
Company: Mehta&Modi Realty Kow Site: Greenwood Heights			Prepared by:		K.Sneha	
ort From / To 15-01-22 To 22-01-22					A.Suresh	
Date						
itions number	s missing in the rep	ort*:-	4.76	1 1 m m m m		
itions where I	PO/WO not prepared	d 3 working da	ys after requisiti	ion:	Remarks and residence of the state of	
	e Serial no of	Item De	Item Description		Reason for not preparing PO/WO#	
14-01-202				PO to be issued		
sitions where I	PO/WO is prepared	and items have	not been receive	ed at site beyond	the lead time:	
Req Dat		Item Description		Details of discussion with supplier ⁸		
13-08-20		_	Powder coated grills		PO No. 79763,Under Fabrication.	
12-10-20	21 1	MS F	MS Railing		PO No,81767,Under Fabrication.	
_				PO No.83314, We will get if from SSLLP by		
				Tuesday.		
15-12-20	21 1-2			PO no.83869,We will get it from SSLLP by Tuesday.		
31-12-202	21 1	Openable	glass door	Po No.84096, Supplier: Sri Sai Rohith Marketing Company. Under Fabrication.		
30-12-202	1	Sera	board	Po No:84221,Sup:Shri Kripalu Trading Company.Supplier said deliver the material by Wednesday.		
07-01-202	22 1	SS R	SS Railing		Po No:84406 ,Sup:Leela Steel Railing&Furniture.Supplier said deliver the material by this week.	
12-01-202	22 1	Fruit pack	cing cover's			
14-01-202	22 1	Breath	analiser			
_				PO no 84556		
					PO no 84605	
	& stock report em				Yes	
Tor size	Wt per mtr					
8mm				2 211	Nil	
					Nil	
12mm	.89			Nil	Nil	
16mm	_	-			Nil	
-		+		Nil Nil		
25mm	3.86	+		Nil Nil		
32mm	6.32	-				
					Nil	
	OPC last weeks stock		PPC/PSC stock	and the state of	PPC/PSC last - weeks stock	
	Weeks stock			Officer/Manager Admin Audit		
	To	To 15-01-22 To 22-01-22		To	To	

_			
Sign	A.Suresh	K.Sneha	
Date	17-01-2022	17-01-2022	

Notes: 1. * Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to purchase@modiproperties.com, ashaiya@modiproperties.com and rajkumarn@modiproperties.com on every Saturday. 3. Admin offices shall not leave the site without completing this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$ Suggested remarks – Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!

