## Remarks from site on the 'Requisition by Site Report' of purchase division

Company:		Modi Realty Mallapur LLP			Date:		19.03.22			
Site: Gulm			r Residency	Prepared by:		A.Janaki				
Report From / To 13.03.22					Approved by:					
Report Date         19.03.22										
			ing in the report							
					g days after requisit		C , DOMYO			
Req No.	Req No. Req Date		serial no of iteam in Req	Item Description		Reason for not preparing PO/WO				
192891	24.02.22		1 to 10	Hydrant valve		Requisition send to MD approval				
192892	24.02.22		1 to 6	MS coupling		Requisition send to MD approval				
192872	22.02.22		1,2	Fire safety doors		Requisition send to MD approval				
192873	22.02.22		1	Fire safety doors		Requisition send to MD approval				
192871	22.02.22		1,2	Fire safety doors		Requisition send to MD approval				
192936	12.03.22		1	SS glass balcony railing		Requisition send to MD approval				
192937	12.03.22		1	XL PHT armored cable(3core)		Po to	b be issue			
192943	12.03.22		1 to 6	Brass NRV (bore motor		Po to	o be issue			
192945	14.03.22		1 to 15	connection material ) Electrical wires		Po to	o be issue			
List of requisit	ions wh	nere PO/WO	) is prepared and	d items h	ave not been receiv	ed at	site beyond the lead time:			
Req No.	Req Date		Serial no of item in Req.	Item Description			Details of discussion with supplier			
192762	31.01	.22	1 to 3	Templates		No s	o stock at SSLLP			
192766	31.01.22		1 to 4	Templates		No s	stock at SSLLP			
192798	05.02	2.22	1	Fire extinguisher		Part	Partly material received			
192802	07.02	2.22	1 to 4	Templates		No s	No stock at supplier			
192803	07.02	2.22	1 to 4	Templates		Deli	Delivery pending from SSLLP			
192830	12.02	2.22	1,2	MS rect. Pipe		Deli	very pending from SSLLP			
192862	21.02	2.22	1 to 3	PVC pipes (FRLS)		Ready with supplier				
192867	21.02	2.22	5,6,7,10	Electric	cal internal	Part	ly material received			
192868	21.02	2.22	6,7&10	Metal boxes		Part	Partly material received			
192902	01.03	3.22	1 to 3	Templates		No s	stock at SSLLP			
192903	01.03	3.22	1 to 4	Templates		No s	No stock at SSLLP			
192909	01.03	3.22	1to 4	Templates		No s	No stock at SSLLP			
192816	12.03	3.22	2&7	Panel d	oor	Part	artly material received			
192917	09.03	3.22	1,2	Holdfast		Read	Ready with supplier			
192922	08.03	3.22	1,2	Holdfast		Ready with supplier				
192931	08.03	3.22	1	Concealed flush tanks		No stock at SSLLP				
192935	08.03	3.22	1 to 4	WPC door frames		No stock at supplier				
192933	08.03	3.22	1 to 3	FP Isolator		Ready with supplier				
192934	08.03	3.22	1 to 4	Tube li	ghts (LED)	Read	ly to supplier			
192935	12.03.22		1	Flush doors		No stock at supplier Wednesday will be delivered				

192940	12.03.22	1	1 63amps PVC o		nector Ready with supplier					
192941	12.03.22	1,2	LED flood lig	hts	Ready wi	Ready with supplier				
192911	12.03.22	1 to 4	Grills		No stock at SSLLP					
192946	14.03.22	1 to 3	WPC door frame		No stock at supplier					
192948	14.03.22	1 to 12	PVC material	PVC material		Ready with supplier				
192949	15.03.22	1 to 5	Panel doors		Ready with supplier					
192950	15.03.22	1	Lap top bags		Online purchase					
192951	15.03.22	1 to 5	Panel doors		No stock at SSLLP					
192952	15.03.22	1 to 21	Switches		Ready with SSLLP					
192961	16.03.22	1	Cement solid blocks		Ready with supplier					
	asses issued this	weak		From No.	-	To No.	1_	T_		
Two or gate p	asses issued this	······································		10111110.		10110.				
Delivery van	n site visit on:		15.03.22(Tues	15.03.22(Tuesday ) 17.03.22(Thursday )13.03.22(Saturday)						
Inward repor	rt (MRN/other) &	kstock report ema	iled in pdf forma	t to purchase			Yes			
	el & cement stock									
SI NO	Tor size	Wt per mtr	Wt. for 12 mtr	Stock at sit		at site in Kg	S	Previous stock		
		kgs	rod – kgs	– no of rod		0		in kgs		
1.	8mm	0.395	4.74		Nill					
2.	10mm	0.617	7.41	Nill		Nill				
3.	12mm	0.888	10.6	Nill		Nill				
4.										
	16mm	1.580	18.9	100	1890					
5.	20mm	2.469	18.9 29.6	100 50	1890 1480					
5. 6.	20mm 25mm	2.469 3.86	18.9	100 50 50	1890 1480 2316					
5. 6. 7.	20mm 25mm 32mm	2.469	18.9 29.6	100 50 50 Nill	1890 1480 2316 Nill					
5. 6. 7.	20mm 25mm	2.469 3.86	18.9 29.6	100 50 50	1890 1480 2316					
5. 6.	20mm 25mm 32mm	2.469 3.86	18.9 29.6	100 50 50 Nill	1890 1480 2316 Nill	PP	C/PSC last	2 70		
5. 6. 7. 8.	20mm 25mm 32mm Binding wire	2.469 3.86 66.67	18.9 29.6 46.32	100 50 50 Nill Nill	1890 1480 2316 Nill Nill		C/PSC last	70		
5. 6. 7. 8. OPC stock	20mm 25mm 32mm Binding wire	2.469 3.86 66.67 OPC last weeks stock	18.9 29.6 46.32 Nill	100 50 50 Nill Nill PPC/PSC stock	1890 1480 2316 Nill Nill 150	we	eks stock			
5. 6. 7. 8.	20mm 25mm 32mm Binding wire	2.469 3.86 66.67 OPC last	18.9 29.6 46.32 Nill	100 50 50 Nill Nill PPC/PSC	1890 1480 2316 Nill Nill 150	we				

Notes: 1. \* Send a copy of the missing requisitions to Purchase immediately. 2. Send this report to <a href="mailto:purchase@modiproperties.com">purchase@modiproperties.com</a>, <a href="mailto:ashaiya@modiproperties.com">ashaiya@modiproperties.com</a>, ashaiya@modiproperties.com</a> on every Saturday. 3. Admin offices shall not leave the site without ompleting this report. 4. Ensure that inward numbers are written on the Requisitions, clearly showing the items not received on a daily basis. 5. Mention PO & MRN no. on DCs / bills. 6. Report to be signed by Admin manager & Project manager at site and filed at site. 7. #Suggested remarks – For technical details from site, For negotiations/quotations, Local purchase, For MDs approval/input, 8. \$Suggested remarks - Ready with supplier, Supplier not contacted, Supplier not reachable, Material in transit, WO - under fabrication, WO - material for fabrication not received, WO - material received fabrication not started, Delivery van delay, Delay by purchase assistant, Supplier arranging for material, 9. Purchase to send reply to this report within one week. 10. Follow up for WO is the responsibility of engineers at site – purchase to write 'NA' in reply to this report. 11. Admin officers/managers must call all suppliers on a daily basis for follow-up – DO NOT CALL PURCHASE!