


Construction division.  
Advice for giving credit to contractors/suppliers.

Sl. No. – site bills register		1124		Date - site bills Register		03/02/2022	
Company Name:		MPL		Site:		MFP	
Name of Contractor		G. Snehalatha					
Nature of work		Earth work					
Work done		From Date		To Date			
		10/10/2021		02/12/2021			
Sl. No.	Villa/Flat/block no.	Qty.	Rate	Units	Amount	Contractors bill no	
①	C-Block Terrace						
2.	Debris cleaning	18,954.00	1.50	Sft	28,432.00		
②	Club house Debris						
4.	cleaning.	12,209.00	1.50	Sft	19,213.00		
③	C-Block Corridors						
6.	Debris cleaning.	19,859.00	1.50	Sft	29,788.00		
7.							
8.							
9.							
10.							
11.	Total:				77,234.00/-		
Bill required		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO.		GST bill required		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO.	
Measurement & estimate sheet:		<input checked="" type="checkbox"/> Required <input type="checkbox"/> Not required		Measurement & estimate sheet:		<input checked="" type="checkbox"/> Enclosed <input type="checkbox"/> Not enclosed	
PO/WO no.				PO/WO date:			
Remarks :							
Approved by Project Manager		Approved by Design Team		Approved by M.D.			
Date: 03/02/2022		Date:		Date:			
Sign: 		Sign:		Sign:			

Notes: 1. This advice must be sent within 7 days of completing work. 2. This form can be used for certifying labour bills, bills for hire charges, earth work, turnkey civil contractors. 3. Wherever not applicable – fill NA. 4. Estimate and measurement sheets are not required for turnkey jobs where guideline rates are clearly given.

## Bill for Consumables

G.Snehalatha.  
Mallapur, Malkajigiri.  
Hyderabad.

Date :03-02-2022

**In favor of:** MPL  
**Project / Site:** MFP  
**Location:** 82/1. Mallapur  
**Type of Work:** Civil works  
**Towards:** Allowance for Consumables

S No.	Description	Amount
1.	Brief description of work done: Towards C-Block Terrace, Corridors and Club house Debris Cleaning work Total amount = Rs. 77,434.00/- Work done from date 10-10-2021 to 02-12-2021	Rs. 15,486.00/-

Amount in Words: Fifteen Thousand Four Hundred and Eighty Six Rupees Only.

Sign: \_\_\_\_\_

## Bill for Equipment Allowance

G.Snehalatha.  
Mallapur, Malkajigiri.  
Hyderabad.

Date :03-02-2022

**In favor of:** MPL  
**Project / Site:** MFP  
**Location:** 82/1. Mallapur  
**Type of Work:** Civil Works  
**Towards:** Allowance for Equipment.

S No.	Description	Amount
1.	Brief description of work done: Towards C-Block Terrace, Corridors and Club house Debris Cleaning work Total amount = Rs. 77,434.00/- Work done from date 10-10-2021 to 02-12-2021	Rs. 30,973.00/-

Amount in Words: Thirty Thousand Nine Hundred and Seventy Three Rupees Only.

Sign: \_\_\_\_\_

## Bill for Labour charges

G.Snehalatha.  
Mallapur, Malkajigiri.  
Hyderabad.

Date :03-02-2022

**In favor of:** MPL  
**Project / Site:** MFP  
**Location:** 82/1. Mallapur  
**Type of Work:** Civil Works  
**Towards:** Allowance for Labour charges

S No.	Description	Amount
1.	Brief description of work done: Towards C-Block Terrace, Corridors and Club house Debris Cleaning work Total amount = Rs. 77,434.00/- Work done from date 10-10-2021 to 02-12-2021	Rs. 30,973.00/-

Amount in Words: Thirty Thousand Nine Hundred and Seventy Three Rupees Only.

Sign: \_\_\_\_\_

<b>ESTIMATE SHEET</b>									
Company Name:		MPL		Prepared by:		R.Ashok			
Project:		May Flower Platinum							
Work Description:		C-Block Terrace, Corridors and Club house Debris Cleaning							
Contractor Name:		G.Snehalatha							
Date:		02.02.2022							
S.No.	Item Head	Item Description	Quantity	Units	Rate	Amount	Grand Total		
1	C-Block Terrace Debris Cleaning		18,954.95	Sft	1.50	28,432.43			
2	Club House Debris Cleaning		12,809.02	Sft	1.50	19,213.53			
3	C-Block Corridors Debris Cleaning		19,859.08	Sft	1.50	29,788.61			
			<b>Total Amount</b>			<b>77,434.57</b>			
<b>Amount in words :- Seventy Seven Thousand Four Hundred and Thirty Four Rupees Only</b>									



<b>MEASUREMENT SHEET</b>									
Company Name:		MPL		Prepared by:		R.Ashok			
Project:		May Flower Platinum							
Work Description:		C-Block Terrace, Corridors and Club house Debris Cleaning							
Contractor Name:		G.Snehalatha							
Date:		02.02.2022							
S.No	Item Head	Item Description	A Length	B Width	C Height	Nos	Quantity	Units	Total Head
<b>1 C-Block Terrace Debris Cleaning</b>									
	C1		40.50	32.50	1.00	1.00	1,316.25	Sft	
	C2		39.75	34.00	1.00	1.00	1,351.50	Sft	
	C3 & C4		40.50	32.50	1.00	2.00	2,632.50	Sft	
	C5,C6,B3 & B4		33.75	44.58	1.00	4.00	6,018.30	Sft	
	B2		56.75	32.33	1.00	1.00	1,834.73	Sft	
	Club house Terrace		1,829.86	1.00	1.00	1.00	1,829.86	Sft	
	Corridors		33.91	7.00	2.00	1.00	474.74	Sft	
			12.58	7.00	2.00	1.00	176.12	Sft	
			77.75	9.25	2.00	1.00	1,438.38	Sft	
			41.14	7.00	2.00	1.00	575.96	Sft	
			93.33	7.00	2.00	1.00	1,306.62	Sft	
							<b>Total Area</b>	<b>Sft</b>	<b>18,954.95</b>
<b>2 Club House Debris Cleaning</b>									
			42.00	32.91	1.00	1.00	1,382.22	Sft	
			23.00	8.60	1.00	1.00	197.80	Sft	
			18.00	13.88	1.00	1.00	249.84	Sft	
								Sft	1,829.86
							<b>Total Area</b>	<b>Sft</b>	<b>12,809.02</b>
<b>3 C-Block Corridors Debris Cleaning</b>									
		Up to 7th Floor	33.91	7.00	1.00	1.00	237.37	Sft	
			12.58	7.00	1.00	1.00	88.06	Sft	
			77.75	9.25	1.00	1.00	719.19	Sft	
			41.14	7.00	1.00	1.00	287.98	Sft	
			93.33	7.00	1.00	1.00	653.31	Sft	
							<b>Total Area</b>	<b>Sft</b>	<b>1,985.91</b>
		Up to 10th Floor						<b>Sft</b>	<b>19,859.08</b>