





| ESTIMATE SHEET  |                      |   |          |       |       |          |                 |
|---|----------------------|---|----------|-------|-------|----------|-----------------|
| Company Name:   |                      | MHPL-SOV-3  |          |       |       |          |                 |
| Project:  |                      | Silver Oak Villas -3  |          |       |       |          |                 |
| Work Description:   |                      | RCC works   |          |       |       |          |                 |
| Name of the Contractor  |                      | T Yellanna  |          |       |       |          |                 |
| Prepared By   |                      | Kiran kumar.J   |          |       |       |          |                 |
| Date:   |                      | 17-12-2022  |          |       |       |          |                 |
| S No.   | Item Head            | Item Description  | Quantity | Units | Rate  | Amount   | Item Head Total |
| 1   | Rcc works Footings   | Footing for Debris collecting tank purpose in south side nala   | 40.50    | Cft   | 40.00 | 1620.00  |                 |
| 2   | Rcc works core walls | Core walls for Debris collecting tank purpose in south side nala<br>security room slab near 129<br>security room slab near south gate | 419.00   | Sft   | 40.00 | 16760.00 |                 |
|   |                      |   |          |       |       |          | 18,380.00       |
| <b>Total amount : Eighteen thousand three hundred and eighty rupees</b> |                      |   |          |       |       |          |                 |

  
**APPROVED BY**  
**19 DEC 2022**  
**K. PURSHOTHAM**  
 Project Manager (Silver Oak Villas Part-III)



| MEASUREMENT SHEET |                      |  |        |       |        |              |          |       |                 |
|-------------------|----------------------|--|--------|-------|--------|--------------|----------|-------|-----------------|
| Company Name:     |                      | MHPL-SOV   |        |       |        | Approved by: |          |       |                 |
| Project:          |                      | Silver Oak Villas -III   |        |       |        | Sign:        |          |       |                 |
| Work Description: |                      | RCC works  |        |       |        |              |          |       |                 |
| Contractor Name   |                      | T Yellanna   |        |       |        |              |          |       |                 |
| Prepared By       |                      | Kiran kumar.J  |        |       |        |              |          |       |                 |
| Date:             |                      | 17-12-2022   |        |       |        |              |          |       |                 |
| S No.             | Item Head            | Item Description   | Length | Width | Height | Nos.         | Quantity | Units | Item Head Total |
| 1                 | Rcc works Footings   | Footing for Debrics colleceng tank purpose<br>in south side nala   | 9.0    | 9.00  | 0.50   | 1.00         | 40.50    | Cft   | 40.50           |
| 2                 | Rcc works core walls | Core walls for Debris colleceng tank purpose<br>in south side nala | 8.00   | 1.00  | 3.00   | 4.00         | 96.00    | Sft   | 419.00          |
|                   |                      | security room slab near 129  | 7.00   | 1.00  | 3.00   | 4.00         | 84.00    | Sft   |                 |
|                   |                      | security room slab near south gate                                 | 10.00  | 10.00 | 1.00   | 1.00         | 100.00   | Sft   |                 |
|                   |                      | security room slab near south gate                                 | 11.00  | 9.00  | 1.00   | 1.00         | 99.00    | Sft   |                 |
|                   |                      | Beam in nala   | 10.0   | 1.00  | 4.00   | 1.00         | 40.00    | Sft   |                 |



## Bill for Labour Charges

T. YELLANNA  
Cherlapally

Date: 17-12-2022

**In favor of:** M/s. Silver Oak Villas LLP  
**Project / Site:** Silver Oak Villas  
**Location:** Cherlapally  
**Type of Work:** RCC Work  
**Towards:** Labour Charges

| S No. | Description   | Amount       |
|-------|---|--------------|
| 1.    | Brief description of work done:<br>Towards:-Footings & Core Walls for Debris Collecting tank Purpose in south side nala security room slab near v.no.129 & south Gate<br><b>Total Amount:- 18,380/-.</b><br>Work Done from date: 03.12.22 to date:16.12.22. | Rs.14,704/-. |

Amount in words: Fourteen Thousand Seven Hundred Four Rupees Only/-.

Sign: \_\_\_\_\_



## Bill for Allowance for Equipment

T. YELLANNA  
Cherlapally

Date: 17-12-2022

**In favor of:** M/s. Silver Oak Villas LLP  
**Project / Site:** Silver Oak Villas  
**Location:** Cherlapally  
**Type of Work:** RCC Work  
**Towards:** Allowance Equipment

| S No. | Description   | Amount     |
|-------|---|------------|
| 1.    | Brief description of work done:<br>Towards:-Footings & Core Walls for Debris Collecting tank Purpose in south side nala security room slab near v.no.129 & south Gate<br><b>Total Amount:- 18,380/-.</b><br>Work Done from date: 03.12.22 to date:16.12.22. | Rs.3,676/- |

Amount in words: Three Thousand Six Hundred Seventy Six Rupees Only/-

Sign: \_\_\_\_\_