


Construction division.
Advice for giving credit to contractors/suppliers.

Sl. No. – site bills register		333.		Date - site bills Register		4/10/23	
Company Name:		Paramount		Site:		PMP II	
Name of Contractor		Parardan					
Nature of work		Piles Work.					
Work done		From Date				To Date	
Sl. No.	Villa/Flat/block no.	Qty.	Rate	Units	Amount	Contractors bill no	
1.	Souconete/norward	344	35	sqft	12040		
2.	Stc Sidewall Gravel	216	25%	sqft			
3.	Hole driv.	110	100	no's	16632		
4.	Central lobby wall	90	45	sqft	4050		
5.	Parking Skirny, part	173	25	sqft/sq	4325		
6.	Shedded North/east	4782	11.5	sqft	54,993		
7.	Bms room, sqft	165	32	sqft	5280		
8.							
9.							
10.							
11.	Total:				97,320		
Bill required		<input type="checkbox"/> YES <input type="checkbox"/> NO.		GST bill required		<input type="checkbox"/> YES <input type="checkbox"/> NO.	
Measurement & estimate sheet:		<input type="checkbox"/> Required <input type="checkbox"/> Not required		Measurement & estimate sheet:		<input type="checkbox"/> Enclosed <input type="checkbox"/> Not enclosed	
PO/WO no.				PO/WO date:			
Remarks :							
Approved by Project Manager		Approved by Design Team		Approved by M.D.			
Date: 04/11/2023		Date:		Date:			
Sign: 		Sign:		Sign:			

Notes: 1. This advice must be sent within 7 days of completing work. 2. This form can be used for certifying labour bills, bills for hire charges, earth work, turnkey civil contractors. 3. Wherever not applicable – fill NA. 4. Estimate and measurement sheets are not required for turnkey jobs where guideline rates are clearly given.

ESTIMATE SHEET

Company Name: paramount
 Project: pmpl
 Work Description: tiles work
 Contractor: janardan
 Prepared By: sulhan
 Date: 03-11-2023

Approved by: subba reddy
 Sign: _____

S No	Item Head	Item Description	Quantity	Units	Rate	Amount	Item Head Total
1	tiles work	south side staircase side wall tiles repair work	192	sft	35	6720	12040
		north side staircase side wall tiles repair work	152	sft	35	5320	
		staircase side wall tiles top granite beading fixing work	58	rf	25	1450	
		granite on top of staircase clamping	116	rf	27	3132	16632
		skirting repair work	42	rf	25	1050	
		hole drill in lift and fire line purpose	110	nos	100	11000	4050
		central lobby wall cladding tiles work	27	sft	45	1215	
		parking area skirting	63	sft	45	2835	
		generator side skirting	54	rf	25	1350	4325
		south side ramp granite refixing work	92	rf	25	2300	
		shabad laying at north side road	27	sft	25	675	54993
		shabad repair work at east and north side plantation area	4422	sft	11.5	50853	
		bus room files flooring work	360	sft	11.5	4140	5280
		skirting	120	sft	32	3840	
			45	rf	32	1440	97320
Grand Total							

MEASUREMENT SHEET							Approved by:		Subba Reddy		
Measurement Name	paramount	Project	pmpl	Contractor	renardan	Prepared By	sulhan	Date	03-11-2023	Sign:	
S No	Item Head	Item Description	A Length	B Width	C Height	D Nos	E Quantity	F Units			
1	tiles work	south side staircase side wall tiles repair work	4	2	1	24	192	sft			
		north side staircase side wall tiles repair work	4	2	1	19	152	sft			
		staircase side wall tiles top granite beading fixing work	58	1	1	1	58	ft			
		granite on top of staircase champering	116	1	1	1	116	ft			
		skirting repair work	42	1	1	1	42	ft			
		hole drill in lift and fire line purpose	110	1	1	1	110	nos			
		central lobby wall cladding tiles work	9	3	1	1	27	sft			
			7	9	1	1	63	sft			
		parking area skirting	54	1	1	1	54	ft			
		generator side skirting	92	1	1	1	92	ft			
		south side ramp granite refixing work	9	3	1	1	27	sft			
		shabad laying at north side road	134	33	1	1	4422	sft			
		shabad repair work at east and north side plantation area	2	3	1	1	60	sft			
		brns room tiles flooring work	15	8	1	1	120	sft			
skirting	46	1	1	1	46	ft					