Anx B - Work Completion Report

(Date:	Sign:	Approved by	Remarks:	10.	9.	œ	7.	6.	5.	4.	<u>.</u>		2.		1.	Sl. No.	WO date	WO no.		Block no.		Project/site	Company
100	X 229	V.	Approved by project manage										staircase	H-block south	block	Clubhouse,H-	Unit/floor no			-				
	a k	10.	gar		Total Amount						GST 18%		painting(Luppam+2 coatspaint)	Stairca	wall		o Details of work			upperbasement	Clubhouse,H-block		GMR	MRMLLP
	Date:	Sign:	Approved by QS team										n+2 coatspaint)	iling	wall painting work	Panel room, lift, electrical ducts parapet		Contractor bill no.	Work done to date		Work done from date		Nature of work	Name of contractor
														792.75		3,949.44	Qty	1	30-01-2024		21.01.2024	rooms, lift, electrical ducts & parapet wall	Painting works	Basappa
														sft	Sft		Units					lectrical	rks	
	Date:	Sign:	Approved by Director/E&D team											PT109		PT135	Rate ID	GST bill required?	WO issued?		M-codex bill ID.		Dt. site bills reg.	Sl. No. site bills reg.
			tor/E&D tea											9.50	6.75		Rate	Yes	No				19-02	g. 3408
			am		40,344 /-						6,154.17			7,531.13	26,658.70		Amount						19-02-2024	80

Company Name:	MRMallapurLLP			Approved by:		Ahmed Khan		
Project:	Gulmohar Residency	су		Sion.		, Hillian Latina		
Work Description:	H-block upperbase	H-block upperbasement panel rooms, ducts ¶pet wall external painting work(prime+2 coats paint)	iting work(p	rime+2 coate no	int			
Contractor:	Basappa		d	1 00 m				
Prepared By:	V.Sanketh							
Date:	17-02-2024							
			>	В	C	D	E = AxBxCxD	Ŧ
S No.	Item Head	Item Description	Length	Width	Height	Nos	Quantity	Units
-	Clubhouse	Ramp-Iupperbasement parapet wall east side	71.00	1.00	8.75	1.00	621.25	sft
		painting						
2	H-block	upperbasement parapet wall painting	76.25	3	3 75	3	78 580	2 →
	upperbasement	at south side						
		H-block ventilation duct painting	51.00	1.00	3.75	1.00	191.25	sft
		Northern panel room external painting	129.00	1.00	10.50	1.00	1,354.50	sft
		Northern lift duct (service) internal painting	18.50	1.00	11.00	1.00	203.50	sft
		Southern panel room external painting	98.00	1.00	10.50	1.00	1,029.00	sft
		Southern lift duct internal painting	24.00	1.00	11.00	1.00	264.00	sft
								3,949.44
3	H-block south	staircase painting (Luppam, primer, 2 coats paint)	36.00	1.00	11.00	1.50	594,00	sft
	staircase	Ceiling painting	13.25	10.00	1.00	1.50	198.75	sft
								792.75
								The state of the s

L