ESTIMATE SI	HEET					Approved by	T Madhu
Company Nam	ie:	GVRC					
Project:		Innopolis					
Work Descripti	ion:	3600 ground floor upvc windows fixing work done					
repared By		K.Srikanth					
Date:		03.06.2024				1	Item Head Total
Jak.			Quantity	Units	Rate	Amount	Item Head Total
No.	Item Head	Item Description					
,,,,,			84.24	sqm	538.00	45321.12	
00	3600.00	3600 ground floor upvc windows fixing work done	3.60	sqm	807.00	2905.20	
.00	3000.00	broken glass	2.00	boxes	600.00	600.00	
		Fitting screws	2.00	boxes	100.00	100.00	
	-	Plugs	2.50			48926.32	
		1.1.5					
				-			
		Amount In Words:Fourty eight Thousand Nine Hundread Twenty six Rupees Only					
		Amount In Words:Fourty eight Thousand Wife Transfered	,				

MEACI	REMENT SHEET						T .		
Company Name:		GVRC				Approved by:		T, Madhu	
Project:		Innopolis			-	Sign:			
		3600 ground floor upvc windows fixing work done				Work Start Date:		23-05-2023	
Contractor Name		M.Sudharshan				Work End Date:		01-06-2023	
Prepare		K.Srikanth							
Date:		03.06.2023							
		Year Described on	Length	Width	Height	Nos.	Quantity	Units	Item Head Total
S No.	Item Head	Item Description	Length	Widen	110.6.	1,55			
. 00	3600.00	3600 ground floor upve windows fixing work done	-,						
.00	3000.00	5000 glound 11001 upte windows taking work done	1.50	1.20	1.00	14.00	25.20	sqm	
			1.20	1.20	1.00	21.00	30.24	som	
			1.80	1.20	1.00	10.00	21.60	sqm	
			0.90	1.20	1.00	4.00	4.32	sqm	
			0.60	1.20	1.00	4.00	2.88	som	
		broken glass					84.24		
		0,0,000	0.60	1.20	1.00	2.00	1.44	sqm	
			0.90	1.20	1.00	2.00	2.16	sqm	
							3.60		

Fabrication of Aluminium Partitions, Door's, Windows & Glazing Work's H.No. 1348, Poineer Bazar, Bolarum, Sec-bad. Cell:9849102251

Flow doll

2024 l Ś 0 23

Per Spring sarolong ou Alymmm

50~ til 1500 7 1200

20N 01 Sar 2) NOS 1800 × 1200 1200 × 1200

Son t 7 1200 gas × 1200

909

25.2

30.24

el

Samo B3.94

For SFT SDEOD K

538:00 Sgumi

00=65154 1 83.94 × 538-00

0.91 = 0-42 7 2,0x4,0 12 Not 3 Broken Would

0.04

Fighting Swood 2 130x 2 600200 21304 = 100 = 03

(mo) (5)

2880200

15,00

002006 Plugs

Sever hundred Anorty Dogwar Lag 48139 GNowd Total 45159= +2880+700 ? Forey Grade-Thouse

Anx B – Work Completion Report

Company		GVRC	Name of contractor	M.Sudarshan		Sl. No. site bills reg.		is reg.		
Project/site		Innoplis	Nature of work	UPVC Windows fixing		Dt. site bills reg.			03-06-2024	
Block no.		3600	Work done from date	23-05-2023		M-codex bill ID.				
WO no.			Work done to date	01-06-2023		WO issued?				
WO date			Contractor bill no.			GST bill required?				
Sl. No.	Unit/floor no		Details of work	Qty		Units	Rate ID	Rate	Amount	
1	3600	3600 ground floor upvc windows fixing work done.			8	4 sqm	CP158	538.00	45,321	
2		broken glass				4 sqm	CP159	807.00	2,905	
3	Fitting screws					2 boxes	CP160	600.00	600	
4		plugs				2 boxes	CP161	100.00	100	
5										
6										
7										
8										
9										
10										
	•							Total	48,926	
									48,926	
Total Amount for Work done										
Remarks:		D. RY								
Approved by	Areject manag	ger	Approved by QS team			Approved by	y Director/E&D	team		
Sign:	No yach 2	224	Sign:			Sign:				
Date:	T MADH	Date:				Date:				
Notes: 1. This she	et replacification	ion Deport and advice for	or credit to contractors. 2. This word form must be than 10k QS manager and directors approval i	be typed. 3. Use this form experience of For bill amounts.	ven if work ord	er is not issued. 4.	Attach measurement a	and estimate sheets of	nly if required	
i.e., details cannot E&D member to b	be entered above. 5	o. For bill amount greate include – Soham Ana	er than 10k QS manager and directors approval to and Mehta (for GHT + GMR), Sachin (for Vivopo	olis), B. anand Kumar (for l	NGH + NRK)	8. Entry of rate ID	is mandatory, 9. This	s sheet must be sent v	within 2 working	

days of work completion (with or without contractors bill). 10. Contractors to send scanned copy of bill to site and QS by email. 11. Contractors must submit original bills at HO (can be sent by courier).