					Amount	25 116	16.380	2,268	2,268	5,460				51.492				
516			NA	No	Rate	7 00	7.00	7.00	7.00	7.00				Total		or/E&D team		
SI. No. site hills rea	Dt. site bills reg.	M-codex bill ID.	WO issued?	GST bill required?	Rate ID	SCF119	SCF119	SCF119	SCF119	SCF119						Approved by Director/E&D team	Sign:	Date:
				)	Units	Sff	Sft	Sft	Sft	Sft						A	S	Δ .
K.Krishna	Scaffolding	11/12/24	16/01/25		Qty	3,588.00	2,340.00	324.00	324.00	780.00								
Name of contractor	Nature of work	Work done from date	Work done to date	Contractor bill no.		ty kiosk	ide	Flat no 1 balcony extension on drive way	extension on drive way	extension on drive way						Approved by QS team	Sign:	Date:
Modi Realty Pocharam LLP	eights				Details of work	Arch gate & security kiosk	Service lift north side	Flat no 1 balcony e	Flat no 2 balcony	Flat no 4 balcony of						Approved by projectmanages VFD BY		3006 1441
Modi Rea	A Block	NA	AN	I Init/floor	no	A-Block	Double Section	Scarrolding								projectmana		660
Company Project/site	Block no.	WO no.	WO date	SI. No.		1.	i n	٠. ٨	· v	9	7.	8.	9.	10.	Remarks:	Approved by	Sign:	Date:

Notes: 1. This sheet replaces installation report and addited by credit to contractors. 2. This word form must be typed. 3. Use this form even if work order is not issued. 4. Attach measurement and estimate sheets only if required i.e., details cannot be entered above. 5. For bill amount greater than 10k QS manager and directors approval is required. 6. For bill amount less than 10k any QS team member may sign and in place of director sign of respective E&D member to be taken 7. Directon include — Soham, Anand Mehta (for GHT + GMR), Sachin (for Vivopolis), B. anand Kumar (for NGH + NRK). 8. Entry of rate ID is mandatory. 9. This sheet must be sent within 2 working darsoof work completion without contractors bill). 10. Contractors to send scanned copy of bill to site and QS by email. 11. Contractors must submit original bills at HO (can be sent by courier).

	2.4 Balcony Painting	Grand Total						51,492.00
	h side, Flat No - 1,	Amount	25,116.00	16,380.00	2,268.00	2,268.00	5,460.00	
	Vijay Raj	Rate Painting work	7.00	7.00	7.00	7.00	7.00	
	rch Gate, S	Units ,4 Balcony	Sft	Sff	Sft	Sft	Sft	
	Prepared by: ainting at Entrance A	Quantity th side, Flat No - 1,2	3,588.00	2,340.00	324.00	324.00	780.00	Total Amount Only
	MRPLLP Nilgiri Heights Scaffolding work for External Painting at Entrance Arch Gate , Service Lift North side, Flat No - 1,2,4 Balcony Painting	Item Description Quantity Units Rate  Constitution One Arch Gate, Service Lift North side, Flat No - 1,2,4 Balcony Painting work	Double Scaffolding Work	Double Scaffolding Work	Double Scaffolding Work	Double Scaffolding Work	Double Scaffolding Work	undred and Ninety Two Rupees
ESTIMATE SHEET Company Name:	Work Description: Contractor Name:  Date:	Scaffolding work for External Painting at Entr	(1 Coat External Emulsion)	Service Lift - North Side Out Side For Lift Assembling work	Flat No - 1 - Balcony Extenstion on Driveway (1 Coat External Emulsion)	4 Flat No - 2 - Balcony Extenstion on Driveway (1 Coat External Emulsion)	5 Flat No - 4 - Balcony Extenstion on Driveway (1 Coat External Emulsion)	Amount in words :- Fifty One Thousand Four Hundred and Ninety Two Rupees Only



ny Painting work	Total Head	3,588.00	2,340.00	324.00	324.00	780.00
2,4 Balco	Units	Sft	Sft	Sft	Sft	Sft
ı side, Flat No - 1,	Quantity	3,588.00	2,340.00	324.00	324.00	780.00
se Lift North	No's work	1.00	1.00	1.00	1.00	1.00
Vijay Raj	C Height	26.00	130.00	18.00	18.00	26.00
ance Arch (	B Width 1,2,4 Balco	1.00	1.00	1.00	1.00	1.00
Prepared by:	A Length 1 side, Flat No -	138.00	18.00	18.00	18.00	30.00
MRPLLP Nilgiri Heights Scaffolding work for External Painting at Entrance Arch Gate, Service Lift North side, Flat No - 1,2,4 Balcony Painting work	U6-01-2025 Item Description e Arch Gate , Service Lift North	Double Scaffolding Work	Double Scaffolding Work	Double Scaffolding Work	Double Scaffolding Work	Double Scaffolding Work
SHEET	Scaffolding work for External Painting at Entrance Arch Gate, Service Lift North side, Flat No - 1,2,4 Balcony Painting work	1 Entrance Arch Gate and Security Kiosk (1 Coat External Emulsion)	2 Service Lift - North Side Out Side For Lift Assembling work	3 Flat No - 1 - Balcony Extenstion on Driveway (1 Coat External Emulsion)	4 Flat No - 2 - Balcony Extenstion on Driveway (1 Coat External Emulsion)	5 Flat No - 4 - Balcony Extenstion on Driveway (1 Coat External Emulsion)
MEASUREMENT Company Name: Project: Work Description: Contractor Name: Date:	S.No					

## Bill for Labour Charges

K.Krishna, Mallapur,Malkagiri Hyderabad.

Date: 06.01.2025.

In favor of:
Project / Site:
Location:
Pocharam.
Type of Work:

Caffolding Works.
Towards:
Labour Charges

Amount	Description	S No.
Rs. 20,597/-	Brief description of work done: Towards Completion of Scaffolding work for External Painting at Entrance Arch Gate, Service Lift North side, Flat No - 1,2,4 Balcony	.I.
	Painting work.	
	Total Amount = 51,492/- Work done from date 01.12.2024 to 17.12.2024	
	4202.21.\ T 01 4202.21.T0 5160 HIOH 51100 ATOW	

Amount in words: Twenty Thousand Five Hundred and Ninety Seven Rupees Only.

Sign:
.0

## Bill for Equipment Allowance

Hyderabad. Mallapur, Malkagiri K.Krishna,

Date: 06.01.2025.

Allowance for Equipment Scaffolding Works. Type of Work: Pocharam. Nilgiri Heights. Project / Site: MRPLLP.

Towards:

Location:

in favor of:

S No. Description of work description	Amount Rs. 20,597/-	Description of work done: Towards Completion of Scaffolding work for External Painting at Entrance Arch Gate, Service Lift North side, Flat No - 1,2,4 Balcony Painting work.  Total Amount = 51,492/- Work done from date 01.12.2024 to 17.12.2024	.i
---------------------------------------	------------------------	---	----

Amount in words: Twenty Thousand Five Hundred and Ninety Seven Rupees Only.

	IISIC
	Sign:

K.Krishna, Mallapur,Malkagiri Hyderabad.

Date: 06.01.2025.

MRPLLP.
Nilgiri Heights.
Pocharam.
Scaffolding Work.
Allowance for Consumables

In favor of: Project / Site: Type of Work: Towards:

Brief description of work	ı
Brief description of work done: Towards Completion of Scaffolding work for External Painting at Entrance Arch	
Gate, Service Lift North side, Flat No - 1.2.4 Balcony	
Painting work.	
	Scaffolding work for External Painting at Entrance Arch Painting work.  Painting work.  Total Amount = 51,492/- Work done from date 01.12.2024 to 17.12.2024

Sign:

Amount in words: Ten Thousand Two Hundred and Ninety Eight Rupees Only.