Anx B - Work Completion Report

Company	GVRC			Name of contractor	Eshwar rao		SI No site	hillereg		150
Project/site	Innopolis		Nature of work	scaffolding			Sl. No. site bills reg. Dt. site bills reg.		1736	
Block no.	2727&4545			Work done from date	Junorumg	Sourrolding		oill ID.		25-01-2025
WO no.				Work done to date			WO issued			
WO date				Contractor bill no.			GST bill required?			
Sl. No.	Unit/floor no		Details o			Otri	Units			
· · · · · · · · · · · · · · · · · · ·			2 Citais 0	· WOLK		Qty	Units	Rate ID	Rate	Amount
1	2727	2727 north side broken glass removing				11,200	sft	scf116+117	4.00	44,800
2	2727	2727 west side staircase lighting fixing			100	sft	scf116+117	4.00	400	
3	4545	north side glass broken remov	ing			4,050	sft	scf116+117	4.00	16,200
4	4545	East side cladding granite repair				2,000	sft	scf116+117	4.00	8,000
5	4545	west side acp and glass fixing			7,200	sft	scf116	2.50	18,000	
6	Atrium	internal acp sheet frame repairing				1,800	sft	scf116+117	4.00	7,200
7	3600	South side glass and frame fixing			12,160	sft	scf116	2.50	30,400	
8	3600	East side glass and frame fixir	ıg	2		7,680	sft	scf116	2.50	19,200
9										
10					,					
									Total	1,44,200
		_ \ \ \						Add GST @		(
		Mula				Tot	al amount	including taxes fo	r work done	1,44,200
Remarks:		TIED BY		1			1			
Approved by project manage PROVED BY			Approved by QS team	Approved by Director/E&D team						
Sign:		11110001		Sign:			Sign:			
Date:	Sign: 25 JAN 2021 Date: Date: cet replaces installation report and advice for credit to contractors. 2. This word form must be typed. 3. Use this form even if work order is not issued. 4. Attach measurement and estimate sheets only if required i.e. T. M. C. T. S. T. S. D. S. D									
entered above. 5. F	et replaces installat For bill amount greaters (for GUT). GU	ion report and advice for credit to contract ster than full cost manager of Rirectors a MR Section for Vironolia). B. anadd Ku hill to cite and O S by email. 11. Contractor	pprovat is required, mar (for NGH + N	RK). 8. Entry of rate ID is mand	atory. 9. This sheet mu	is not issued. 4. Att may sign and in pla ist be sent within 2 v	aon measureme ce of director si vorking days of	nt and estimate sheets on ign of respective E&D me f work completion (with c	ry ir required i.e., do imber to be taken. 7 or without contracto	: Director include ~ rs bill). 10.

ESTIN	MATE SHEET								
Company Name:		GVRC							
Project:		Innopolis							
Work Description:		Ms scoffolding works							
Contractor Name		Eashwar rao							
Prepared By		T Madhu							
Date:	1000	24.1.25					77 177 1		
S No.	Item Head	Item Description	Quantity	Units	Rate	Amount	Item Head Total		
3 140.	2727 north side Broken glass removing purpose	Ms scoffolding tying and remoiving	11200		4.00	44,800			
1	2727 west side staircase lighting fixing purpose	Ms scoffolding tying and remoivng	100		4.00	400			
3	4545 north side glass broken removing purpose	Ms scoffolding tying and remoivng	4050	Sft	4.00	16,200			
3	4545 East side cladding granite repair purpose	Ms scoffolding tying and remoiving	2000	Sft	4.00	8,000			
4	4545 west side Acp and glass fixing purpose	Ms scoffolding tying	7200		2.50	18,000			
	Atrium internal acp sheet frame repaing	Ms scoffolding tying and remoiving	1800	Sft	4.00	7,200			
6	Atrium internal acp sheet frame fepting	Ms scoffolding tying	12160	Sft	2.50	30,400			
7	3600 south side gkass and frame fixing	Ms scoffolding tying	7680	Sft	2.50	19,200			
9	3600 east side gkass and frame fixing	1110 0001101-1-1-1-1-1	,				1,44,20		
		Grand total:-					1,44,20		
		Amount in words: One lakh for	Amount in words: One lakh forty four thousand two hundred rupees only						

MEASU	REMENT SHEET							Γ	
Company Name:		GVRC				Approved by:		T. Madhu	
Project:		Innopolis				Sign:	u bj.	1. Mading	
Work Description:		Ms scoffolding works							
Contractor Name		Eashwar rao							
Prepared By		T Madhu							
Date:		24.1.25							
S No.	Item Head	Item Description	Length	Width	Height	Nos.	Quantity	Units	Item Head Total
1	2727 north side Broken glass removing purpose	Ms scoffolding tying and remoiving	70.00	80.00	1.00	2.00	11,200	Sft	
2	2727 west side staircase lighting fixing purpose	Ms scoffolding tying and remoiving	50.00	1.00	1.00	2.00	100	Sft	
3	4545 north side glass broken removing purpose	Ms scoffolding tying and remoiving	45.00	90.00	1.00	1.00	4,050	Sft	
4	4545 East side cladding granite repair purpose	Ms scoffolding tying and remoiving	20.00	100.00	1.00	1.00	2,000	·	
5	4545 west side Acp and glass fixing purpose	Ms scoffolding tying and remoiving	90.00	80.00	1.00	1.00	7,200		
6	Atrium internal acp sheet frame repaing	Ms scoffolding tying and remoiving	30.00	60.00	1.00	1.00	1,800		
7	3600 south side gkass and frame fixing	Ms scoffolding tying	64.00	190.00	1.00	1.00	12,160		
9	3600 east side gkass and frame fixing	Ms scoffolding tying	120.00	64.00	1.00	1.00	7,680	Sft	