

Company	MRMILLP	Name of contractor	Valludasu vinod	Sl. No. site bills reg.	1581		
Project/site	AGH	Nature of work	Seepage repairing work	Dt. site bills reg.	01-04-2025		
Block no.	88	Work done from date	25-03-2025	M-codex bill ID.			
WO no.	Nil	Work done to date	01-04-2025	WO issued ?	Nil		
WO date	Nil	Contractor bill no.	14	GST bill required?	NO		
Sl. No.	Unit/floor no	Details of work	Qty	Units	Rate ID	Rate	Amount
1	88	Seepage repairing work	1.00	Nos	LS	3590/-	3590/-
2							
3							
4							
5							
6							
7							
8							
9							
10							
Total							3590/-
Add GST @ 18.00%							0.00
Total amount including taxes for work done							3590/-
Remarks: As per estimate sheet approved by MD Sir, attaching approved estimate copy.							
Approved by project manager		Approved by QS team		Approved by Director/E&D team			
Sign:		Sign:		Sign:			
Date:		Date:		Date:			

Notes: 1. This sheet replaces installation report and advice for credit to contractors. 2. This work form must be typed. 3. Use this form even if work order is not issued. 4. Attach measurement and estimate sheets only if required i.e., details cannot be entered above. 5. For bill amount greater than 10k QS manager and directors approval is required. 6. For bill amount less than 10k any QS team member may sign and in place of director sign of respective E&D member to be taken. 7. Director include - Soham, Anand Mehta (for GHT + GMR), Sachin (for Vivopols), B. anand Kumar (for NGH + NRK). 8. Entry of rate ID is mandatory. 9. This sheet must be sent within 2 working days of work completion (with or without contractors bill). 10. Contractors to send scanned copy of bill to site and QS by email. 11. Contractors must submit original bills at HO (can be sent by courier).

Measurement Sheet								
Company Name		Modi Realty Nivatalayuda LLP						
Project		AVR Gulmohar Homes						
Work Description		Owner share villas seepage work						
Prepared By		Suman						
Date		3-Mar-2025						
1	Villa No. 88 internal side applying dampproof seepage effected area		A	B	C	D	F=AxBxCxDxE	
		Pooja (E+W+N+S)	8.00	0.00	2.00	1.00	16.00	sft
		Dining-east wall	6.00	0.00	2.00	1.00	12.00	sft
		Dining-south wall	10.00	0.00	2.00	1.00	20.00	sft
		Dressing -South east wall	5.00	0.00	2.00	1.00	10.00	sft
		Kids Bedroom-east wall	4.00	0.00	2.00	1.00	8.00	sft
		Master Bedroom - west wall	10.00	0.00	2.00	1.00	20.00	sft
		Living -West wall	10.00	0.00	2.00	1.00	20.00	sft
		Living -North wall	6.00	0.00	2.00	1.00	12.00	sft
		Total					48.00	sft
2	External Walls	North side	35.00	0.00	2.00	1.00	70.00	sft
		South side	28.00	0.00	2.00	1.00	56.00	sft
		Total					126.00	sft

Estimate Sheet									
Company Name	Modi Realty Miryalaguda LLP								
Project	AVR Gulmohar Homes								
Work Description	Owner share villas seepage work								
Prepared By	Suman								
Date	3-Mar-2025								
Sl. No.	Item Head	Item Description	Quantity	Units	Materials Cost per sft	labour cost/ per sft	Materials amount	Labour Amount	
1	Villa No.88	Applying Dampproof for seepage effected walls height of 2ft for internal side	48.00	sft	25	10.00	1200.00	480.00	
2	Villa No.88	Applying Dampproof for seepage effected walls height of 2ft for external side	126.00	sft	10	5.00	1260.00	630.00	
Total							2,460.00	1,130.00	
								3590/-	

APPROVED BY
04 MAR 2025
SOHAM MODI

Allowance for Labour Charges
Name Of Contractor
Place
Vallapudasu Vinod
AVR Gulmohar Homes

Date 1-Apr-2025

Vallapudasu Vinod
In Favour Of MRMLLP
Project / Site AVR Gulmohar Homes
Location Miryalaguda

Type Of Work Owner share villas seepage work

Towards Labour Charges

S No	Description	Amount
1	Brief Description Of Work	
	Towards : Owner share villa no 88 seepege repairing work	
	Total Amount : Rs.3590 /-	1,436.00

Amount In Words :- One thousand four hundred thirty six rupees only

Sign: _____

Name Of
Contractor
Place

Allowance for Consumable
Vallapudasu Vinod
Miryalaguda

Date 1-Apr-2025

In Favour Of
Vallapudasu Vinod
MRMLLP

Project / Site
AVR Gulmohar Homes

Location
Miryalaguda

Type Of Work Owner share villas seepage work

Towards **Allowance for Consumable**

S No	Description	Amount
1	Brief Description Of Work	
	Towards : Owner share villa no 88 seepege repairing work	
	Total Amount : Rs.3590 /-	718.00

Amount In Words :- Seven hundred eighteen rupees only

Sign: _____

Name Of
Contractor
Place

Allowance For Equipment

Vallapudasu vinod

AVR Gulmohar Homes

Date 1-Apr-2025

Vallapudasu Vinod

In Favour Of

MRMLLP

Project / Site

AVR Gulmohar Homes

Location

Miryalaguda

Type Of Work

Owner share villas seepage work

Towards

Allowance for Equipment

S No	Description	Amount
1	Brief Description Of Work	
	Towards : Owner share villa no 88 seepege repairing work	
	Total Amount : Rs.3590 /-	1,436.00

Amount In Words :- One thousand four hundred thirty six rupees only

Sign: _____