	Τ							Т	Ţ		18	13	בוי	3
				-	-				Date	repared By	Work Description	roject	Company Name	Measurement Sheet
			seepage effected area	appying damproof	VIIIa No. 12 internal side Kids Bedroom-East wall						ption		me	t Sheet
Total	Daining west wall	MB- East wall	MB- South wall	Kids Bedroom-north wall	Kids Bedroom-East wall	Living Area-west wall	Living Area-north wall		19-Apr-2025	Suman	Owner share villa seepage work	AVR Gulmohar Homes	Modi Realty Miryalaguda LLP	
	7.00	6.00	10.00	10.00	8.00	9.00	12.00	Α				Sign	Approved By	
	0.00	0.00	0.00	0.00	0.00	0.00	0.00	В					Ву	
	3.00	2.00	2.00	2.00	3.00	2.00	3.00	С						
	1.00	1.00	1.00	1.00	1.00	1.00	1.00	D						
151.00	21.00	12.00	20.00	20.00	24.00	18.00	36.00	F=AxBxCxDxE						
sft	sft	sft	sft	sft	sft	sft	sft	F						

					Total			
3775.00	1	10.00	25	sft	151.00	Applying Damproof for seepage effected walls	Villa No.12	posit
Materials amount Labour Amoun		Units Materials labour cost/ per sft	Materials Cost per sft	Units	Quantity	Item Description	Item Head	SL No.
	1		-			17-Арм-2025		Date
	1					Suman	d By	Prepared By
	1					Owner share villa seepage work	Work Description	Work D
						AVR Gulmohar Homes		Project
						Modi Realty Miryalaguda LLP	mpany Name	Compa
							Estimate Sheet	Patities

12/on/52

APPROVED BY

1 9 APR 2025

SOHAM MODI

Allowance for	Labour	Charges
---------------	--------	---------

Name Of Contractor

Vallapudasu Vinod

Place

AVR Gulmohar Homes

Date

6 (109-Apr-2025

Vallapudasu Vinod

In Favour Of

MRMLLP

Project / Site

AVR Gulmohar Homes

Location

Miryalaguda

Type Of Work

Owner share villa seepage work

Towards

Labour Charges

S No	Description	Amount
	Brief Description Of Work	
1	Towards: Ownar share villa no 12 seepege repairing work Total Amount: Rs. 5285/-	2,114.00

Amount In Words:- Two thousand one houndred fourteen rupees only

Sign:			
	 		_

Allowance for Consumable

Name Of Contractor

Vallapudasu Vinod

Place

Miryalaguda

Date 8 8-Apr-2025

Vallapudasu Vinod

In Favour Of

MRMLLP

Project / Site

AVR Gulmohar Homes

Location

Miryalaguda

Type Of Work

Owner share villa seepage work

Towards

Allowance for Consumable

S No	Description	Amount
	Brief Description Of Work	
1	Towards: Ownar share villa no 12 seepege repairing work Total Amount: Rs. 5285/-	1,057.00

Amount In Words:- One thou

One thousand fifty seven rupees only

Sign:	

4 11	**	Y	
Allowance	ror	Eau	oment

Name Of Contractor

Vallapudasu vinod

Place

AVR Gulmohar Homes

Date

8-Apr-2025

Vallapudasu Vinod

In Favour Of

MRMLLP

Project / Site

AVR Gulmohar Homes

Location

Miryalaguda

Type Of Work

Owner share villa seepage work

Towards

Allowance for Equipment

S No	Description	Amount
	Brief Description Of Work	
1	Towards: Ownar share villa no 12 seepege repairing work Total Amount: Rs. 5285/-	2,114.00

Amount In Words:- Two thousand one houndred fourteen rupees only

Sign:			
~.5			

Anx-B.report on account bill formate for villa no 10

			Date:	11 1 9 H . 11 . 2	Date: Date: Date:	Notes: 1. This leggl philips it said A Mile And Advice for credit to contractors. 2. This word form must be typed. 3. Use this form even if work order is not issued. A Arrich and the said of the sai	I. This bee
			oign:		Date:		Date:
	realli	2000	2		Sign:	CZUZ YAMIST	Sign:
	feam	Approved by Director/F&D team	Approved by		Approved by QS team	by project manager	Approved by p
						A PPH O WE DO B Neted,	Kemarks Ap
5285/-	work done	otal amount including taxes for work done	ગી amount incl	Tota			1
	18.00%	Add GST @					
5,285	Total						
							10
							9
							∞
							7
							6
							v
							4
							w
5,285	5,285	S	Nos	Ork	Scepage repairing Work		2
Amount	Rate	Rate ID	Units	Qiy	Samon or Holk	Villa no 12	_
No		uired?	GS1 bill required?	2	Details of work	Unit/floor no	SI. No.
Nill			WO issued ?			2:	WO date
		ID.	M-codex bill ID.	0.502-03-2023		N.II	WO no.
08-05-2025		reg.	Dt. site bills reg.	Seepage repairing work	n date	12	Block no.
1581		ills reg.	Sl. No. site bills reg.	Vallupudasu vinod	Nature of work	AGH	Project/site
							Colors or an improper of the second