## Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

Recommendation: Stop further work. Stop further work. Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.		10.	T. Modhu	P. Sin Kum	1/1sta homes	C-403
eport to QC team. Proc ter submitting ATR on sing corrections pointed ired.	MD Sign	30744	Sign	Sign	Project	Other
eed only after recheck QC report to QC team d out in the QC report.		Report filed and signed by PM	S KA	Prody	Votakomes	
by QC. a.  ATR not required.	For filling	ed by PM	Date	Date	Phase	SI. No.
	□Yes □No	Yes No	8114 2	26 7 18	j	30963

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc. In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

## Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

TATIOCOTION OF OTHER			
Modular kitchen to be provided	∏Ýes □No	Modular kitchen provided	L√Yes ∐ No
Modular kitchen workman ship	Good Avg Poor Modular kitchen gran	Modular kitchen granite & dado	Good Avg Poor
		workman ship & finishing	
Video door phone to be provided	Yes No	Video door phone provided	Yes No
		)	The second secon

Ren	15	14	13	12	11	10	9	8	7	6	5	4	ß	2	Н	S No	
Remarks	Other	Other	Toilet.3	Toilet 2 CT	Toilet 1 ゃって	Kitchen	Utility/-balcony-3	Utility / balcony 2	Utility / balcony 1	Lobby 1	Dining	Drawing	Bedreom 3	Bedroom 2 195	Bedroom 1 MB	Room	
				ς .	V	V		1	<	\	١	<	grander .	$\checkmark$	<	Door, door knob & door stopper fitting	
				<	<u> </u>	<	1	• -	./	ĵ	15	, ,		~	<	Door, door knob & door stopper cleaning	
				<	<	<	8	į	\	١	``		1		1	Window grills quality	Rate the quality of (Good
				<	<	<b>V</b>	}	1	١	1	<	\	ì	(	<	Window grills fitting & finishing	uality of
				<	<,	<	)	•	1	١	/	<	1	<	<	Windows quality	(Good ✓
				<	<.	<	)	Ì	1	)	1	./	}	<	<	Window fitting & finishing	, Avg.
				[	J		\	<	1	)		1	ļ	1	)	Balcony railing quality & finishing	X, Poor-
				(		1	1	<	1	\  \ 		j	1	1	)	French door quality & fitting	
				<	<		)	1	5				)		)	CP jali quality and fitting	needs correction XX, NA)
				7	<	<	9	<	5	1	<	<	1	<	<	Edge building	XX,
				\	<	<		<	7	1	<	<		<	<	Switch boards fitting & covering with plastic covers	(A)
				<	<	<	900	1	7	7	-			<	<	Junction box covers painting	No. of the last of