

Quality Control Check Report **Stage: After Finishing Stage II (Apartments)**

Flat No	C-404	Other	—	Sl. No.	29100
Company	BNC	Project	ME4	Phase	II
Prepared by	M. Teja Sridhar	Sign	AS	Date	23/01/18
Project Manager	Subba Reddy	Sign		Date	23/01/18
Previous stage report no.		Report filed and signed by PM			
Checked By MD on		MD Sign	26/9/12	For filling	
Recommendation: <input type="checkbox"/> Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. <input type="checkbox"/> Stop further work. Proceed with work after submitting ATR on QC report to QC team. <input checked="" type="checkbox"/> Proceed with further work only after making corrections pointed out in the QC report. ATR not required. <input type="checkbox"/> Proceed with further work. ATR not required.					

Inspection should be done after:

- Completion of flooring, bathroom/utility tiles, first coat of paint.
- Completion of doors, windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

Main door fixed with lock & stopper	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Granite soffit for balcony provided	<input type="checkbox"/> Yes <input type="checkbox"/> No
Granite soffit for balcony required	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Balcony granite soffit edge polishing	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor
Balcony granite soffit workmanship	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor	Granite soffit for main door provided	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Granite soffit for main door required	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Main door granite soffit edge polishing	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor
Main door granite soffit workmanship	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor	False ceiling workmanship	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor
False ceiling to be provided ?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		

Quality Control Check Report. Stage: After Finishing Stage II (Apartments)

Tiling & granite work		Rate the quality of (Good <, Avg. X, Poor – needs correction XX, NA)																		
1	S No																			
2	Room																			
1	Toilet 1 (MT)	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
2	Toilet 2 (CT)	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
3	Toilet 3	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
4	Toilet 4	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
5	Wash basin in dining area	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
6	Kitchen	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
7	Utility	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
8	Other	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
9	Other	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<	<
Remarks		XX) In Utility flooring was not done.																		

Quality Control Check Report. Stage: After Finishing Stage II (Apartments)

S No	Room	Rate the quality of (Good ✓, Avg. X, Poor - needs correction XX, NA)										
		Color variation of floor tiles	Flooring workmanship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	General quality of painting & finishing	Door & frame painting quality	Door beading, luppam and painting quality.
1	Bedroom 1 (MB)	✓	X	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Bedroom 2 (KB)	✓	X	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Bedroom 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Drawing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Hobby 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility/balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	X
8	Utility/balcony 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	X
9	Utility/balcony 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	Other											
12	Other											
Remarks		Notes: Grouting was not done properly in M. Bedroom & K. Bedroom.										