	Quality Control Check Repot.		Stage: After Finishing Stage III (Apartments)	ge III (Apartments)	
Flat No	E-806	Other		Sl. No.	32650
Company	0 NC	Project	MFG	Phase	
Prepared by	S-SUNU Kumas Sign	Sign		Date	14/01/19
Project Manager	VIJAY RAJ	Sign	7	Date	14/01/19
Previous stage report no.	no.	3839	Report filed and signed	by PM	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Stop further work. Submit ATR on QC report Stop further work. Proceed with work after suppressed with further work only after making a Proceed with further work. ATR not required.	port to QC team. Pr ter submitting ATR ing corrections poin	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	by QC. L. ATR not required.	

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

## Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided	ATTACA CALLES OF CALCULATION
Yes No	1	Good Avg Poor	☐ Yes ☑ No	
Video door phone provided	workman ship & finishing	☐ Good ☐ Avg ☐ Poor   Modular kitchen granite & dado	Modular kitchen provided	
⊠Yes □No		☐ Good ☐ Avg ☐ Poor	☐ Yes ☐ No -	

29	Ren	15	14	13	12	11	10	9	8	7	9	5	4	3	2	_	S No
F.O. will be	Remarks () GJULS	Other	Other	Toilet 3	Toilet 2 CAON	Toilet 1 M. Toi	Kitchen	Utility / balcony 3-	Utility / balcony-2-	Utility-/ balcony 1	Lobby +	Dining	Drawing	Bedroom 3 A. Bed	Bedroom 2 K. Bed	Bedroom 1 M.Bed	Room
Pix ed	and				<	ς	1	1	(	1	١	9	ς	ς	ς	ς.	Door, door knob & door stopper fitting
	Some				ς.	(	1	4	<	1	1	1	ς	ζ.	ς	<	Door, door knob & door stopper cleaning
	elf of		5000000		1	1	ı	1	-	1	1	ı	1	1	1	1	Window grills quality  Window grills fitting & finishing  Windows quality
	TO 27				9.457	1	1	1	ſ	}	1	1	1	1	١	1	Window grills fitting & finishing
	wetin				ζ	ς.	(	j	1	1	1	1	1	1	۲	۲	Windows quality
	So box				<	<	<	1	1	١.		ſ	1	ζ	ζ	<	Window fitting & finishing
						1	١		١	ζ	1	•	9	1	7	1	Balcony railing quality & finishing
	OB-NO				١	l	3	,	1	3		,	)	1	-	Y	French door quality & fitting
	nat Brovided				ς	ζ	j		3	ζ	ſ	ľ	1	}	1	1	French door quality & fitting  CP jali quality and fitting  Edge building  Switch boards fitting &
	SONIC			The second secon	j	1	×	ſ	×	メ	1	1	ζ	5	۲	5	Edge building
	Jed.			0.000	ζ	<	ζ	1	<	ζ		1	ζ	ζ	ς,	ς	Switch boards fitting & covering with plastic covers
					)	ì	1	)	}	1	)	)	1	)	1	]	Junction box covers painting