

Quality Control Check Report Stage: After Finishing Stage II (Apartments)

Flat No	G1-204	Other		Sl. No.	28991
Company	VSTA HOMES	Project	VSTA HOMES	Phase	-
Prepared by	M. Teja Sridhar	Sign	AT	Date	14/01/18
Project Manager	T. Madhu	Sign	Madhu	Date	14/01/18
Previous stage report no.	28700	Report filed and signed by PM		Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Checked By MD on		MD Sign		For filling	Yes <input type="checkbox"/> No <input type="checkbox"/>

Recommendation:

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

Inspection should be done after:

- Completion of flooring, bathroom/utility tiles, doors & beading, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

Main door fixed with lock & stopper	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>			
Granite soffit for balcony required	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Granite soffit for balcony provided	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Balcony granite soffit workmanship	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>	Balcony granite soffit edge polishing	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>	
Granite soffit for main door required	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Granite soffit for main door provided	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Main door granite soffit workmanship	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>	Main door granite soffit edge polishing	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>	
False ceiling to be provided ?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	False ceiling workmanship	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>	

Tiling & granite work		Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA)												
S No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform
1	Toilet 1 (MT)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Toilet 2 (CT)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Toilet 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Toilet 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Wash-basin in dining area	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Other													
9	Other													
Remarks														

Flooring & painting		Rate the quality of (Good ✓, Avg. X, Poor - needs correction XX, NA)											
S No	Room	Color variation of floor tiles	Flooring workmanship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	General quality of painting & finishing	Door & frame painting quality	Door beading, luppam and painting quality.	Edge building
1	Bedroom 1 (MB)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Bedroom 2 (KB)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Bedroom-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Drawing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Lobby-1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility / balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Utility / balcony 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	Utility / balcony 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	Other												
12	Other												
Remarks		1) K. Bedroom Door was not fixed as Per random suggest.											