	Quality Control Check Repot.	neck Repot.	Stage: After Finishing Stage III (/	ge III (Apartments)	
Flat No	B-209	Other	X	Sl. No.	83648
Company	PMR	Project	PMR-I	Phase	H
Prepared by	M. Tega Stidher Sign	Sign	12 A	Date	11/09/11
Project Manager	K SHIRISH	Sign	A.	Date	41/60/11
Previous stage report no.	no.	27612	Report filed and signed by PM	ed by PM	Yes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work.	Submit ATR on QC re Proceed with work af	eport to QC tear	ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team.	by QC.	

Inspection should be done after:

Proceed with further work. ATR not required.

- Completing stage II works.

 Complete works like windows, grills, electrical wiring, switches, french door glass, etc.

Proceed with further work only after making corrections pointed out in the QC report. ATR not required.

- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

☐Yes ☐No	Video door phone provided	☐Yes ☑No	Video door phone to be provided
0 0 0	workman ship & finishing		
☐Good MAvg☐Poor	☐ Good ✓ Avg ☐ Poor Modular kitchen granite & dado	☐ Good ☑ Avg ☐ Poor	Modular kitchen workman ship
√Yes □No	Modular kitchen provided	✓ Yes □ No	Modular kitchen to be provided
			THE OCCUPANT OF STREET

	Τ.	72	F-3		<u> </u>		T	Ţ	9	∞	7	6	S		Ī,		1		1-
		Remarks	15		13		₩	-	Ľ		_	2			ယ	2		S No	
		arks	Other	Other	Toilet-3	Toilet 2 (CT)	Toilet 1 (MT)	Kitchen	Utility/balcony3-	Utility / balcony-2	Utility/ balcony 1	Lebby-1	Dining	Drawing	Bedroom-3	Bedroom 2. (KB)	Bedroom 1 (ME)	Room	
					1	<	1	1	-	1	ſ	\	}	<		4	<	Door, door knob & door stopper fitting	
				2	1	<	1	1		١	1	(1	ζ.	1	4	<	Door, door knob & door stopper cleaning	
					\	く	〈	〈	1	1	ļ	1	1	(1	<	<	Window grills quality	Rate the quality of (Good
					1	۷.	〈	۷,	-	1	1	1	1	<	\		۲	Window grills fitting & finishing	luality of
					1	く	٢	<	1	1	١	١	1	<	١	۷	4	Windows quality	1 1
					1	~	۲,	<	1	l	!	1	١		١	j.	ブ	Window fitting & finishing	v, Avg. >
					[1	}	1	1	1	<	1	1	5	1	(1	Balcony railing quality & finishing	X, Poor-
					1	1	}	1	1	1	<	1	1	3	1	1	1	French door quality & fitting	ne
2000					1	4	<		!	< '	1	1	\	ſ	1	ĺ	1	CP jali quality and fitting	eds correction XX, NA)
					1	1	۲,	X		<	〈	1	\$ 7	1	1	×	×E	Edge building	X X
					9	4	<	<	1	<u>`</u>	<	•	\ 		•	< .	` c	Switch boards fitting & covering with plastic covers	JA)
					1	<	<		1	۷,			۷,	\	,	<		Junction box covers painting	es