Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

Flat NO	8409	Other	*	Sl. No.	14485
Company	PMR	Project	PMR	Phase	FÌ
Prepared by	M. Tiga Sridber	Sign	A A	Date	t//11/91
Project Manager	K-SHIRISH	Sign	X,2	Date	4/11/31
Previous stage report no.	no.	28075	Report filed and signed by PM	d by PM	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Subnessed with further work. Proceed with further work. Proceed with further work. Proceed with further work.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Procler submitting ATR on ing corrections pointedired.	ced only after recheck b QC report to QC team. I out in the QC report. I	y QC. ATR not required.	

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of 1/4" from the wall.

 2. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
☐Yes ☑No		☐Good Avg ☐Poor	⊠Yes □No
Video door phone provided	workman ship & finishing	☐ Good ☑ Avg ☐ Poor Modular kitchen granite & dado	Modular kitchen provided
☐ Yes ☐ No —		☐ Good ☑ Avg ☐ Poor	NYes □No

Page 2 of 2

Ren	15	14	13.	12	11	10	9	∞	7	6	S	4	ယ	2	1	S No	
Remarks	Other	Other	Toilet3-	Toilet 2 (Cs ⁻)	Toilet 1(MT)	Kitchen	Utility/balcony-3-	Utility / baleony-2	Utility/balcony 1	Lobby-1-	Dining	Drawing	Bedroom-3	Bedroom 2 (KB)	Bedroom 1 (内B)	Room	7
50 state (600 m)			1	<	•	•••		{	1	Ţ	1	<	1	<	<	Door, door knob & door stopper fitting	
			ţ	<		-		\	-		/	<u> </u>		<u>√</u>	〈	Door, door knob & door stopper cleaning	
			1	<	✓	V		1			1	V	1	<	<	Window grills quality	Rate the quality of (Good
			ļ	\checkmark	<	<u> </u>	-	1	1	١	1	<	1	۷		Window grills fitting & finishing	quality of
			1	く	✓	<	4	1	1	1	1	<	ļ	۷,	く	Windows quality	
			1	<	۷	<		1		-	1	<	ļ	۷	く	Window fitting & finishing	V, Avg.
			1		1	1	1	1	<	1	١	[1	1	-	Balcony railing quality & finishing	X, Poor-
			1	-	1	1	ļ	1	<	-		j	1	1	1	French door quality & fitting	needs co
			1	人	<		1	く	<		1	١	†	1	,	CP jali quality and fitting	needs correction XX, NA)
			1	4	<	<	1	X	×	1	Į	<	1	<	<	Edge building	X X,
			-	<	<	<		4	<		<	<	١	<	•	Switch boards fitting & covering with plastic covers	√A)
			1	<	5	<		<	<	1	<	7		<	<	Junction box covers painting	

Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)