Quality
Contro
Quality Control Check Repot.
₹epot.
Stage:
After
Finishing
Stage I
III (A
Stage: After Finishing Stage III (Apartments)

Flat No	SI. No.	33.526
Company Project	Pink-正 Phase	H
Prepared by V. Sarituh Sign	J. L. K.J. Date	04 05 18
Project Manager 4. Bhirigh Sign	QC Date	94/05/19
Previous stage report no. 31937	Report filed and signed by PM	Yes No
Checked By MD on MD Sign	For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	m. Proceed only after recheck by QC. ATR on QC report to QC team. s pointed out in the QC report. ATR not require	đ.

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/2" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with coment covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
☐ Ycs ☑ No		☐ Good ☐ Avg ☐ Poor Modular kitchen gran	Yes No
Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided
☐ Yes ☐ No —		Good Avg Poor	✓Yes □No

Rem	15	14		12		- TO	9	∞	7	6	S	4	ω	2	_	S No	
Remarks	Other	Other	Twilet 3	Toilet 2 C.76?	Toilet 1 Tr. Toi	Kitchen	Utility / baleony-3	Utility / balcony-2	Utility / balcony 1	Lobby 1	Dining	Drawing	Bedroom 3	Bedroom 2 火. 写	Bedroom 1 M.B	Room	
		:	1	× ×	~	1	•	4	۷	I	1	4	1	4	<	Door, door knob & door stopper fitting	
			١	×	۷	! 	1	<	<	Ţ	1	<	ſ	く	, <u>, , , , , , , , , , , , , , , , , , </u>	Door, door knob & door stopper cleaning	
			1	1	4	<	J	۷,	1	1	4	<u>\</u>	1	<	<	Window grills quality	Rate the quality of (Good
			1	<	۷,	<u> </u>	ĭ	4	1	j	۷,	<u> </u>	1	<	<	Window grills fitting & finishing	quality of
81 A A A A			1	<	<	`	!	1	+	1		<u> </u>	1	<	<	Windows quality	(Good 🗸
			1	<	۷	<	1	•	1	1	<u> </u>	~	1	~	<u> </u>	Window fitting & finishing	, Avg.
			1	١	١	1	1	1	\ \ \	١	١		1	١	1	Balcony railing quality & finishing	X. Poor
			1		1	١	}	1	١	1	1	1	1	٩	١	French door quality & fitting	– needs co
			1	Υ.	< ۱	١	Ī	۷	۷.	1	١		1	1	1	CP jali quality and fitting	needs correction XX, NA)
			1	ж.	×	<	1	×	<		<	<	١	۷	×	Edge building	×
)	/	<	<	1	<	۷,	1	<	<	!	×		Switch boards fitting & covering with plastic covers	VA)
			ļ	×	۷.	<	}	<	<	1	<	<	1	<.	<	Junction box covers painting	