Flat No	7-815	Other	SI. No.	32115
Company	032	Project	Phase Phase	
Prepared by	S.C. MILY WOOD	Sign	Date	19 1
Project Manager		Sign	QC: Date	1011118
Previous stage report no.	no.	@1335	Report filed and signed by PM	Yes No
Checked By MD on		MD Sign	For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work. Proceed with furth	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck leads for further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report.	port to QC team. Procter submitting ATR on ing corrections pointed	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	,
Proceed with furth	Proceed with further work. ATR not required	ired.		•

Quality Control Check Repot.

Stage: After Finishing Stage III (Apartments)

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.

 Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
∐Yes ∠No		Good Avg Poor Modular kitchen gr	Yes □No
Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided
☐Yes ☐No —		Good Avg Poor	☐Yes ☐No

Remarks	15	14	13	12	11	10	9	∞	7	6	2	4	ယ	2	1	S No
natke .	Other	Other	Toilet 3	Toilet 2 C. Toi	Toilet 1 M. TOI	Kitchen	Utility/balcony-3-	Utility / balcony 2-	**************************************	Lobby-1-	Dining	Drawing	Bedroom 3 S. Sed	Bedroom 2 大.Bed	Bedroom 1 M.Bed	Room
_				<	ς	Ş	1	۲	1	1	j	ς.	ς.	ς	ς	Door, door knob & door stopper fitting
-				ζ.	<	J	1	<	1	g/m	1	<	۲	(ς	Door, door knob & door stopper cleaning
				<	ς	<		<	1	1	î	١	ς	ζ	۲	Window grills quality
				ζ	ζ	~	ţ	~)	1	1	1	×	ς	ς.	Window grills fitting & finishing
>				ζ	ζ	\	1	-	Ţ	1	f	ſ	ζ	ς.	۲	Windows quality
			100	ς`	×	×	1	1	1	}	1	1	ς	<	ς	Window fitting & finishing
				١	i	[-	•	ς.	1	1	١	١	1	١	Balcony railing quality & finishing
				1	I				~		1	1	1	1	1	French door quality & fitting
				(ζ	ς,		ς.	ζ	ļ	1	١	ς	۲	<	CP jali quality and fitting
				5	ζ		ı	X	×	ļ	1	(×	5	×	Edge building
				<	ζ	ζ	ĺ	ς	ζ	•		ζ	ζ	ς		Switch boards fitting & covering with plastic covers
				<	ζ.	(1	ζ		ו	1	ζ	ς.	ς	ζ	Junction box covers painting