	Quality Control Check Repot.
	H
	Y (
	, O
1	Ŧ
	은
	Che
	ec.
ı	R
ł	e
ı	3
1	
ı	C D
l	2
ľ	œ:
ı	\geq
ı	fter
ı	E
ı	
1	E.
١	no
١	S
١	19e
ĺ	
ŀ	Stage: After Finishing Stage II (Apartments)
	Da
	ner er
	3

Flat No	D-307	Other		SI. No.	28840
Company	BNC	Project	ŊŦĠ.	Phase	
Prepared by	M. Kya Sridhur Sign	Sign		Date	02/01/18
Project Manager	Subba Reddy	Sign	noch	Date	81/10/20
Previous stage report no.	no.	28111	Report filed and signed by PM	d by PM	Nycs □ No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proceed ter submitting ATR on ing corrections pointed ired.	ced only after recheck b QC report to QC team. I out in the QC report. A	y QC. ATR not required.	

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.

 Completion of windows, grills, electrical wiring, switches must be done in next stage.

 False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided. Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

Good Mavg Poor	False ceiling workmanship	⊠Ýes □No	False ceiling to be provided?
\	polishing	<i>\</i>	
Good Navg Poor	Main door granite soffit edge	☐ Good · Avg ☐ Poor	Main door granite soffit workmanship Good WAvg Poor Main door granite soffit edge
NYes □No	Granite soffit for main door provided ☐ Yes ☐ No		Granite soffit for main door required Yes \(\sum No
☐ Good ☐ Avg ☐ Poor	Balcony granite soffit workmanship Good YAvg Poor Balcony granite soffit edge polishing Good Avg Poor	Good YAvg Poor	Balcony granite soffit workmanship
provided Xes No	Granite soffit for balcony provided	☑Yes □No/	Granite soffit for balcony required
		Nyes □No	Main door fixed with lock & stopper

Ren	9	8	7	6		. מע	4	w	2	_	S No	
Remarks	Other	Other	Utility	Kitchen	dining-area	Wash have a	Tailet 4	Toilet-3	Toilet 2 (CT)	Toilet 1 (州下)	Room	Tiling & granite work
			<	*	1		Ţ	١	<	<	Workmanship of tiling	
			<	<	{	:	,	ļ	<	<	White cement filling around CPVC lines	
			<	<				1	<	<	Corners finishing	Rate the
			~	-	(<	<	Finishing near doors	Rate the quality of (Good ✓, Avg. X, Poor – ne
			<	1	1				<	7	Finishing on top of tiles	of (Good
			l	-	(.	{	ļ	\checkmark	\	Finishing near ventilators	d ν, Αι
			<	1	_				〈	<	Step at bathroom entrance / utility	g X, P
0	i.		<	1	1	1		ĺ	<		Step for shower / pot wash	oor – ne
			<		(}	ĵ	<	<	Tile joint grouting	eds corre
			1		1			1	ļ		Granite platform finishing and edge polishing	eds correction XX, NA)
				1	į		1)	1	<	Granite platform slope	X, NA)
					1		1	1	1	<	Granite platform height	
					A. Campania	7	1	1	1	ζ.	Finishing under granite platform	

12

Other Other

10

Kitchen

4

Drawing Bedroom 3 Bedroom 2 Bedroom 1

Dining

Lebby-1

2

S No

Room

Edge building