	Quality
-	Control
	Quality Control Check Repot.
	Stage: Aft
	er Finishing
	Stage II
	Stage: After Finishing Stage II (Apartments)

		E			Ties.
Flat No	D-601	Other	1	SI. No.	カカナルダ
Company	BNC	Project	NFW	Phase	4
Prepared by	M. Teja Sidher Sign	Sign		Date	20 03 18
Project Manager	Suppalady Sign	Sign	1 of l	Date	20/03/18
Previous stage report no.).	4018B	Report filed and signed by PM	d by PM	NYes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	ubmit ATR on QC re Proceed with work aft work only after mak work. ATR not requi	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck to Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not Proceed with further work. ATR not required.	y QC. ATR not required.	

- Completion of flooring, bathroom /utility tiles, first coat of paint.
- Completion of doors, windows, grills, electrical wiring, switches must be done in next stage False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided. Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

		0.0	
Good Avg Poor	False ceiling workmanship	☐Yes ☑No	False ceiling to be provided?
	polishing		
Good Avg Poor	Main door granite soffit edge	☐Good ☐Avg ☐Poor	Main door granite soffit workmanship
No No	Granite soffit for main door provided $ \square Y$ es $\square $ No		Granite soffit for main door required ☐ Yes ☐ No
Good Mavg Poor	Balcony granite soffit edge polishing	☐ Good ☐ Avg ☐ Poor	Balcony granite soffit workmanship Good Avg Poor Balcony granite soffit edge polishing
□Yes □No	Granite soffit for balcony provided	No □ No	Granite soffit for balcony required
		☐Yes ☐No	Main door fixed with lock & stopper ☐ Yes ☐ No

Quality Control Check Repot. Stage: After Finishing Stage II (Apartments)

l			7.7	3 5	1 2	5 6	×		6	ပ	4		2	اد	S No	
		Kemarks	Outer	Outer	Other	Utility/balcony3	Utility /_balcony-2	Lility / balcony 1	-Lebby-1	Dining	Drawing	Bedroom 3	Bedroom Z-	Bedroom I (Mb)	Room	Flooring & painting
					1		1			1		1	1	1	Color variation of floor tiles	
						1	1	1				\	l l		Flooring workman ship & grouting	
					-		1	1	1				1	1	Skirting size (3")	Rate
					-	Ĭ	-	-	1			1	1	1	Skirting workmanship	Rate the quality of (Good
					1		\	ļ		\			-	1	Plastering above skirting	ty of (Go
					1			-		1	1	\	[1	Plastering & finishing of walls	
		İ	į		1			!		1				ļ	Crack filling	V, Avg. X, P
	Č		i		1		[-	1		1	1	1		Loft Finishing	Poor – need
						1	1		1	1	1]	{	General quality of painting & finishing	needs correction XX, NA)
					1	1		1	1			Ţ			Door & frame painting quality	ion ×
					!	1		1			1	1			Door beading, luppam and painting quality.	NA)
					1	1	1	1)		1	1]	1	Edge building	i i