

**Quality Control Check Report      Stage: After Finishing Stage II (Apartments)**

Flat No	D-803	Other		Sl. No.	30967
Company	BMC	Project	MFG	Phase	II
Prepared by	S. Sund Kumar	Sign	<i>[Signature]</i>	Date	08/6/18
Project Manager	Subba Reddy	Sign	<i>[Signature]</i>	Date	08/6/18
Previous stage report no.			Report filed and signed by PM		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Checked By MID on		MD Sign		For filling	<input type="checkbox"/> Yes <input type="checkbox"/> No

**Recommendation:**

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

**Inspection should be done after:**

- Completion of flooring, bathroom/utility tiles, doors & beading, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

**Miscellaneous check:**

Main door fixed with lock & stopper	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				
Granite soffit for balcony required	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Granite soffit for balcony provided		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Balcony granite soffit workmanship	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor	Balcony granite soffit edge polishing		<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor	
Granite soffit for main door required	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Granite soffit for main door provided		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Main door granite soffit workmanship	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor	Main door granite soffit edge polishing		<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor	
False ceiling to be provided ?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	False ceiling workmanship		<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg <input type="checkbox"/> Poor	

Tiling & granite work		Rate the quality of (Good >, Avg. X, Poor - needs correction XX, NA)												
S No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform
1	Toilet 1 <del>M. Rd</del>	>	>	>	>	>	>	>	>	XX	>	>	>	>
2	Toilet 2 C-Toi	>	>	>	>	>	>	>	>	XX	>	>	>	>
3	Toilet 3	>	>	>	>	>	>	>	>	X	>	>	>	>
4	Toilet 4	>	>	>	>	>	>	>	>	>	>	>	>	>
5	Wash basin in dining area	>	>	>	>	>	>	>	>	>	>	>	>	>
6	Kitchen	>	>	>	>	>	>	>	>	>	>	>	>	>
7	Utility	>	>	>	>	>	>	>	>	>	>	>	>	>
8	Other	>	>	>	>	>	>	>	>	>	>	>	>	>
9	Other	>	>	>	>	>	>	>	>	>	>	>	>	>
Remarks		① Provision for wall in kitchen												

Quality Control Check Report. Stage: After Finishing Stage II (Apartments)

Flooring & painting		Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA)											
S No	Room	Color variation of floor tiles	Flooring workmanship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	General quality of painting & finishing	Door & frame painting quality	Door beading, luppam and painting quality.	Edge building
1	Bedroom 1 M. Bed	>	>	>	>	>	>	>	1	>	>	>	>
2	Bedroom 2 K. Bed	>	>	>	>	>	>	>	1	>	>	>	>
3	Bedroom 3 G. Bed	>	>	>	>	>	>	>	1	>	>	>	>
4	Drawing	>	>	>	>	>	>	>	1	>	>	>	>
5	Dining	1	1	1	1	1	1	1	1	1	1	1	1
6	Lobby-1	1	1	1	1	1	1	1	1	1	1	1	1
7	Utility- / balcony 1	>	>	>	>	>	>	>	1	>	1	1	>
8	Utility / balcony-2	>	>	>	>	>	>	>	1	>	>	>	>
9	Utility- / balcony-3	1	1	1	1	1	1	1	1	1	1	1	1
10	Kitchen	>	>	>	>	>	>	>	X	>	1	1	>
11	Other												
12	Other												
Remarks													