	lity
	Quality Control Check Repot.
	ol Check Re
	Repot.
	Stage
	: After
	Stage: After Finishing Stage III (Apartments)
	Stage III (A)
	T (Apar
	partments)
l	

Flat No D	0-824	Other		SI. No.	33219
Company	6-11-11-11	Project	£1-224	Phase	(3)
Prepared by \mathcal{D}	P. Soi Kny Sign	Sign	RAL	Date	21/2/19
Project Manager K.,	K. SHIRISH KUMAR	Sign	562	Date	21/3/19
Previous stage report no.		32888	Report filed and signed by PM	d by PM	☐Yes ☐No
Checked By MD on		MD Sign		For filling	☐Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck I Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	mit ATR on QC resceed with work after making ork. ATR not requi	port to QC team. Proce er submitting ATR on ing corrections pointed ired.		by QC. n. ATR not required.	

inspection should be done after:

- Completing stage II works.
- Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.

 Switchboards must be fitted to plum.

 Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

	Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided	IATIOCCITATICONO CITCOV.
Control agency of the first of the control of the c	□Yes □No —		Good Mvg Poor Modular kitchen granite	□Yes □ No	
the second control of	Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided	
the contract of the contract o	□Yes □No		Good Avg Poor	V Yes □No	``

Rer	15	14	13	12	=	10	9	8	7	6	5	4	3	2	_	S No
Remarks	Other	Other	Toilet 3	Toilet 2 Cゴ	Toilet 1 Mコ	Kitchen	Utility/balcony-3	Utility / balcony 2	Utility / balcony-1	Lobby 1	Dining	Drawing	Bedroom-3	Bedroom 2 1-45	Bedroom 1 MB	Room
				<	<	<)	ſ	4)	۲	2	<	<	Door, door knob & door stopper fitting
				<	<	<		/	<	-	(<	•	<	<	Door, door knob & door stopper cleaning
				<	<			\	<		(<		<	<	Window grills quality
				<	<	<	\	Ŋ	<	1	1	<	,	<	<	Window grills quality Window grills fitting & finishing Windows quality
				\	<	<	Î	1	<)	1	<	1	<	<	Windows quality
				<	<	<	,	į	<	١	ì	<		<u> </u>	<	Window fitting & finishing
				\	N.	1	١	<)	ı		1	1		1 (Balcony railing quality & finishing
				\	1	}		<	•)	1	ſ	,	į	1	French door quality & fitting
				7	5	1	1	<	<		(1		,	1 1	French door quality & fitting CP jali quality and fitting Edge building Switch boards fitting &
				<	. 5	,<		15	, n/	. (<	<	1	<	<	Edge building
				<		<	(X		<)	<		bytten bounds fitting &
0.00				7		(<	ſ	<	<	1	<	3		\ \		Junction box covers painting