uality
Control
Juality Control Check Repot. Stage
Stage:
After
Stage: After Finishing Stage II (Apartme
hing Stage II
(Apartments)

Flat No	7	Other		SI. No.	2100
Company	BNC	Project	MEG	Phase	=[
Prepared by	S. Survit Yuman	Sign	7(=>	Date	04/02/19
Project Manager	Subba Reddy.	Sign	L. S	Date	04/02/19
Previous stage report no.	no.	89743	Report filed and signed by PM	d by PM	∠Yes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Sub Stop further work. Proceed with further work. Proceed with further work.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointedired.	eed only after recheck bed only after recheck bed QC report to QC team.	y QC. ATR not required.	

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.
 Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

		The second secon	
Good Avg Poor-	False ceiling workmanship	☐ Yes ☑ No	False ceiling to be provided?
25	polishing		
Good Avg Poor	Main door granite soffit edge	☐ Good ☐ Avg ☐ Poor	Main door granite soffit workmanship Good Avg Poor Main door granite soffit edge
Yes No	Granite soffit for main door provided Yes No		Granite soffit for main door required Yes No
Good ⊿Avg ☐ Poor	Balcony granite soffit edge polishing	☑Good ☐ Avg ☐ Poor	Balcony granite soffit workmanship Good Avg Poor Balcony granite soffit edge polishing Good Avg Poor
Yes No	Granite soffit for balcony provided	☐Yes ☐No	Granite soffit for balcony required
		∠Yes □No	Main door fixed with lock & stopper ☐ Yes ☐ No

- 23	1 1 1 1 1 1	1 100 to 10	_	_	_		-			-						
			12	11	10	9	8	7	6	S	4	ယ	2		S No	
		Remarks	Other	Other	Kitchen	Wility / balcony 3	Utility / baleony 27	-Utility → balcony 1	Lobby 1	Dining	Drawing	Bedroom 3 R-Bed	Bedroom 2 K. Bed	Bedroom 1 M.Bed	Room	Flooring & painting
					ς	1	<	7	7	1	ζ	ζ	ς	<	Color variation of floor tiles	
					ζ	1	Ç	ς	1)	ζ`	X	<	<	Flooring workman ship & grouting	
					<	\$	ζ	<	1	1	ζ	۲	<	(Skirting size (3")	Rate
					ς	7	ς	ζ	1)	ζ	ς	<	(Skirting workmanship	Rate the quality of (Good
			e Paus Gamas		ς	1	ζ	ζ)	}	((ς	(Plastering above skirting	ty of (Go
					ζ		ζ	ζ	, man)	ς	<	ζ	ζ	Plastering & finishing of walls	
:					5	***************************************	ζ	۷	١	1	<	<	<	ζ	Crack filling	V, Avg. X, P
	i i			1	X	(1	1	1	Ī		1	١	1	Loft Finishing	Poor – needs correction 🗙 🗙, NA)
					ζ	Ì	(ζ	١	}	ζ	ζ	ζ	ζ	General quality of painting & finishing	ds correct
						1	ζ	1	1	j	<	<	ς		Door & frame painting quality	ion ××,
)	•	<)		Ţ	<	(7		Door beading, luppam and painting quality.	NA)
					X) .	X	ζ	}	1	メ	×	メ	X	Edge building	