Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

Flat No	F-105	Other		Sl. No.	32930
Company	BNC	Project	WEG	Phase	<u>L</u>
Prepared by S.	Sikulder	Sign	Souther-	Date	16/20/11
Project Manager & w	Subba Riddy	Sign	roll	Date	16/02/19
Previous stage report no.		32727	Report filed and signed by PM	d by PM	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	nit ATR on QC receed with work aftork only after mak	port to QC team. Proceer submitting ATR on ing corrections pointed ired.	eed only after recheck be QC report to QC team. out in the QC report	k by QC. m. t. ATR not required.	

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

## lage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided
☐Yes ☐No	1	☐ Good ☐ Avg ☐ Poor   Modular kitchen gran	☐ Yes ☐No
Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided
Yes Wo	>	Good Avg Poor	Yes No

		Re	15	14	13	12		10	9	8	7	6	5	4	w	2	<u> </u>	S No	
		Remarks	Other	Other	10.0	Poilet 2		) Kitchen	Utilit	Utilit	Utilit	Lobb	Dining	Drawing	Bedr	Bedr	Bedroom	Room	
				•	7	t2 C.T	3	en	July / balcony 3	Jtility / balcony 2	July balcony 1	<u>у1</u>	18	/ing	Bedroom 3	Bedroom 2	oom l	:	
		2				H	7		ny3	₽¥-2	ny I			200	K, 62	e E	છ	4	an American
		VUTE:			1	٢	٢	1	1	1	t	1	Ţ	(	¢ .	۲	ς.	Door, door knob & door stopper fitting	
	معتجر	window			ţ	ς	ς.	!	ſ	1	-	1	1.	X,	(	5	13	Door, door knob & door stopper cleaning	
	zeguestic	se co			1	ī	1	1	1	1	1	ı	1	1	1	١	ſ	Window grills quality	Rate the
	12	ills or			,	1	)	<b>†</b>	1	1	1	1	1	!	1	1	1	Window grills fitting & finishing	Rate the quality of (Good
	È -	not as			١	Ç	<	7	1	1	1	!	1	/	7	1	٢	Windows quality	
	Captain	suride			-	ς	7	Ĺ	1	[	1		1	1	7	۲	7	Window fitting & finishing	·, Avg.
	Correct -	d do			†	1	1	1	)	1 ,	K	1	1	1	1	1	,	Balcony railing quality & finishing	X, Poor-
Û	Uina	ኦ ይ/			1	1	1	ļ	1	1	ς	1	(	ļ	ı	1	١	French door quality & fitting	Ħ
		the 4			1	7	٢	•	1	1	7	1	1	)	1	1	1	CP jali quality and fitting	eeds correction XX, NA)
		Hat			1	ζ.	X	Χ	ı	X	5	1	<	7	X	Edge building	Edge building	××	
		· oustoner			,	ĺ	ς .	(	1	<	<	1	<	ς.	7	۲	- 1	Switch boards fitting & covering with plastic covers	NA)
		\$			)	ς.	٢	1	]	<	<	1	(	7	\	7	۲	Junction box covers painting	