Quality Control Check Repot. Stage: After Finishing Stage III (Apartments)

				21.11	
Flat No	G-308	Other	١	SI. No.	24++2
Company	VISTA HOMES	Project	VISTA HOMES	Phase	j
Prepared by	M. Tigo Svidher	Sign	4	Date	23/03/18
Project Manager	1. Madhu	Sign	R)	Date	23/03/18
Previous stage report no.	no.	29327	Report filed and signed	ed by PM	√Yes □ No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Stop further work. Submit ATR on QC report Stop further work. Proceed with work after support Proceed with further work only after making a Proceed with further work. ATR not required.	eport to QC team. Proc fter submitting ATR or king corrections pointe uired.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	by QC. ATR not required.	*

Inspection should be done after:

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of 1/4" from the wall.
- Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

<u><</u>		Z	Z	M
Video door phone to be provided	•	Modular kitchen workman ship	Modular kitchen to be provided	Miscellaneous check:
NYes □ No		☐ Good ☐ Avg ☐ Pool	⊠Yes □No	
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided	
YYes ∐No		Good Avg Poor	☐ Yes ☑No	

Ren	15	14	13	12	11	10	9	8	7	6	5	4	ω	2	1	S No	
Remarks	Other	Other	-Foilet-3	Toilet 2 ((-f)	Toilet 1 (MT)	Kitchen	Utility/baleony-3	Utility / balcony-2	Utility/ balcony 1	Lobby	Dining	Drawing	Bedroom 3(4b)	Bedroom 2 (Kb)	Bedroom 1 (Mg)	Room	
			1	<			I	1	1	1	1	<	<	<	(Door, door knob & door stopper fitting	
			1	<	-	1	1	1	1	1	(<	~	<	(Door, door knob & door stopper cleaning	
			1	<	4	<	1	1	1	(!	1	1	4	<	Window grills quality	Kate the quality of (Good
			1	<	<	<	1	1	١	1	1	1	<	5	<	Window grills fitting & finishing	quanty or
			1	<	<	<	1	1	1	1	1	١	<	<	<	Windows quality	(0000
			1	<	<	<	1	-	1	١	1	1	4	<	<	Window fitting & finishing	, 178.
			1	1	1	1	1	1	<	1	1	1	(1	1	Balcony railing quality & finishing	>, 1001
			1	1	ſ	1	1	١	<	1		1	1	1	1	French door quality & fitting	Hoods of
			1	<	<	1	1	<	<	1	1	١	1	1	1	CP jali quality and fitting	moods component and the
			1	<	1	<		X	X		<	5	<	<	<	Edge building	,,,,
			1	<	<	<		<	5		<	1	<	4	<	Switch boards fitting & covering with plastic covers	
			١	7	5	<	1	<	<	1	<	3	<	4	<	Junction box covers painting	