Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

| Flat No | 84 | Other | | Sl. No. | 31237 |
|--|---|---|--|----------------------------|------------|
| Company | | Project | rilgiei Estates | Phase | |
| Prepared by | P. Son Kenn | Sign | M.A. | Date | 23/8/18 |
| Project Manager µ | Madwinster | Sign | Minney | -Date | 23/8/18 |
| Previous stage report no. | | 25+92 | Report filed and signed by PM | d by PM | Xes No |
| Checked By MD on | | MD Sign | | For filling | ☐ Yes ☐ No |
| Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. | Ibmit ATR on QC re roceed with work aft work only after mak work. ATR not requ | port to QC team. Proceer submitting ATR on ing corrections pointedired. | sed only after recheck b QC report to QC team. I out in the QC report. A | y QC. ATR not required. | |

mspection should be done arter:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.

 Completion of windows, grills, electrical wiring, switches must be done in next stage

 False ceiling must be completed before flooring.

 Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

| | | | γ |
|-----------|---|---|--|
| | Main door granite soffit workmanship Good Avg Poor Main door granite sc | Granite soffit for main door required Yes YNo | Main door fixed with lock & stopper Yes No |
| 1 | Good Avg Poor | Yes YNo | ∠Yes □No |
| polishing | iffit edge | Granite soffit for main door provided | |
| | Good Avg Poor | ☐ Yes ☐ No —— | |

| Rei | 9 | 8 | 7 | 9 | | 2 | 4 | သ | 2 | - | S | No | |
|---------|-------|---------|---------|---------|-------------|---------------|----------|----------|-------------|-------------|-----|--|-------------------------------------|
| Remarks | Other | Portico | Utility | Kitchen | dining area | Wash basin in | Toilet-4 | Toilet-3 | Toilet 2 CT | Toilet 1 MT | Ro | oom | Tiling & granite work |
| | | | 1 | < | 1 | (| Ţ | \ | < | | W | orkmanship of tiling | |
| | | | < | < | 1 | | 1 | 1 | Κ. | < | | /hite cement filling ound CPVC lines | † |
| | | | < | < | | / | ١ | Ţ | < | < | Со | omers finishing | Rate the |
| | | | ١ | ١ | | l | 1 | 1 | < | < | Fin | nishing near doors | quality |
| | | | < | < | | į, | , | 1 | < | \ \ | Fin | nishing on top of tiles | Rate the quanty of (Good V, Avg. A, |
| | | | 1 | 1 | | 1 | 1 | 1 | < | < | Fin | nishing near ventilators | , AV |
| | | | < | 1 | | (| 1 | 1 | < | < | | ep at bathroom entrance | , id |
| | | | < | 1 | | - | | 1 | < | < | | ep for shower / pot ash | LOOI — Heedis contection > > 1 - 12 |
| | | | < | (< | | ţ | | ĺ | < | < | 7 | File joint grouting | da corre |
| | | | j | < | | 1 | | | 1 | | | ranite platform finishing nd edge polishing | |
| | | | (| , < | | - | | 1 | [| | | Granite platform slope |), har |
| | | | 1 | , | | [| | | | | ' | Granite platform height | |
| | | | | , | | Ţ | | | | | | Finishing under granite platform | |

| Remarks | 15. | 14. | 13. | 12. | Ε. | 10. | 9. | 8. | 7. | 6. | 5. | 4. | 3. | 2. | 1. | S No | 7 |
|---------|-------|---------|---------|---------|-----------|---------------------|--------------------|---------|----------------|--------|---------|-----------|-----------|--------------|-----|--|---------------------------------|
| rks | Other | Utility | Kitchen | Portico | Head room | Terrace / balcony 2 | Terrace/_balcony 1 | Lobby-2 | Lobby-1 | Dining | Drawing | Bedroom 4 | Bedroom-s | Bedroom 2 KS | | Room Spanning & painung | Discourse Or pointing |
| | | < | < | < | < | **** | | 1 | E and a second | < | < | (| / | < | < | Color variation of floor tiles | |
| | | > | < | < | < | | | | | < | ζ. | | , | < | , < | Flooring workman ship & grouting | |
| | | < | 7 | < | < | ĺ | ļ | \ |) | 7 | 5 | 1 | (| < | 7 | Skirting size (3") | Rate |
| | | < | 5 | < | ζ | 1 | (|) | ١ | 1 | 7 | 1 | 8 | < | \ | Skirting & & & & & & & & & & & & & & & & & & & | Rate the quality of (Good |
| | | 5 | 5 | ζ, | < | 1 | } | } | 1 | | 1 | 1 | , | K | < | Plastering above skirting | ty of (Go |
| | | < | < | 1 | < | 1 |) | 1 | 1 | 7 | , \ | 1 | , | 1 | < | Plastering & | d V. Avg |
| | | 1 | 5 | < | ? | (| ſ | ſ | | < | 7 | 1 | · \ | < | | Crack filling | × |
| | | (| < | [| 1 | 1 | 1 | 1 | 1 | 1 | 1 | (| V |) X | | Loft Finishing | Poor – needs correction XX, NA) |
| | | 1 | < | × | . × | 1 |) | 5 |) | * | < | | 1 | , | | General quality of painting & finishing | ls correct |
| | | 1 | \ | - | < | Į |) |) | 1 | l | < | 7 | (| 4: | < | Door & frame painting quality | ion XX, |
| | | [| < | 1 | < | 1 | | 1 | 1 | | | | | | | Door beading, luppam and painting quality. | NA) |
| | | À | 7 | X | , × | 5/ | 1 | 1 | 1 | | | | | 1 | | Edge building | |

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

| | Miscellaneous check – after finishing stage II | |
|-----|---|----------------|
| _ | Quality and workmanship of portico tiles | Good Avg. Poor |
| 7 | Quality and workmanship of flooring & setbacks | Good Avg. Poor |
| | Quality and workmanship of external cladding/ texture | Good Avg. Poor |
| - 1 | Remarks: | |
| | | |
| | | |
| 1 | | |