

**Quality Control Check Report      Stage: After Finishing Stage III (Villas)**

Flat No	10	Other		Sl. No.	33525
Company	Sov (LLP)	Project		Phase	TK
Prepared by	V. Saaketh	Sign		Date	04/05/19
Project Manager	K. Raveesh Kumar	Sign		Date	04/05/19
Previous stage report no.				Report filed and signed by PM	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Checked By MD on		MD Sign	32742	For filling	<input type="checkbox"/> Yes <input type="checkbox"/> No

**Recommendation:**

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

Inspection should be done after :

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

**Stage III check notes:**

1. Window grills must be fitted at the depth of 1/4" from the wall.
2. Switchboards must be fitted to plumb.
3. Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

**Miscellaneous check:**

Modular kitchen to be provided	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Modular kitchen provided	<input type="checkbox"/> Yes <input type="checkbox"/> No
Modular kitchen workman ship	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor	Modular kitchen granite & dado workman ship & finishing	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor
Video door phone to be provided	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Video door phone provided	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

		Rate the quality of (Good ✓, Avg. X, Poor - needs correction XX, NA)											
S No	Room	Door, door knob & door stopper fitting	Door, door knob & door stopper cleaning	Window grills & quality	Window grills fitting & finishing	Windows quality	Window fitting & finishing	Balcony railing quality & finishing	CP jali quality and fitting	Edge building	Switch boards fitting & covering with plastic covers	Junction box covers painting	
1	Bedroom 1 M.B	✓	✓	✓	✓	✓	✓	-	-	✓	✓	✓	
2	Bedroom 2 K.B	✓	✓	✓	✓	✓	✓	-	-	✓	✓	✓	
3	Bedroom 3 -	-	-	-	-	-	-	-	-	-	-	✓	
4	Drawing	✓	✓	✓	✓	✓	✓	-	-	✓	✓	✓	
5	Dining	-	-	✓	✓	✓	✓	-	-	✓	✓	✓	
6	Lobby 1	-	-	-	-	-	-	-	-	-	-	-	
7	Utility / balcony 1.	✓	✓	-	-	-	-	-	✓	-	✓	✓	
8	Utility / balcony 2	-	-	-	-	-	-	-	-	-	-	-	
9	Utility / balcony 3	-	-	-	-	-	-	-	-	-	-	-	
10	Kitchen	-	-	✓	✓	✓	✓	-	-	✓	✓	✓	
11	Toilet 1 M.T	✓	✓	✓	✓	✓	✓	-	✓	✓	✓	✓	
12	Toilet 2 C-T	✓	✓	✓	✓	✓	✓	-	✓	✓	✓	✓	
13	Toilet-3	-	-	-	-	-	-	-	-	-	-	✓	
14	Portico												
15	Other												
Remarks		Note: Don't stopper to be provided for Head room Door.											

**Quality Control Check Report. Stage: After Finishing Stage III (Villas)**

Miscellaneous check – after finishing stage III

Quality and workmanship of gate	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Quality and workmanship of railings	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Painting of gates & railings	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Cleaning/painting of external cladding/texture	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Quality and workmanship of lawn	<input checked="" type="checkbox"/> Good	<input type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Remarks:			