0.00	Quality
	Control
	Quality Control Check Repot.
ı	
	Stage: After Finishing Stage III (
	Stage III (VIII

Flat No	Other		Sl. No.	30387.
Company	Sevena Canada Merroject	Sezena fazina	Phase	
Prepared by	S. SUNCL XUMBS Sign	SIS	Date	30/5/18
Project Manager	Polomielí Krishna Sign	injues !	Date	30/5/18
Previous stage report no.	no. 29248	Report filed and signed by	PM	Yes No
Checked By MD on	MD Sign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work.	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.	eed only after recheck b	y QC.	
Stop further work Proceed with furth	Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR	QC report to QC team.  I out in the QC report. I	ATR not required.	
Proceed with furth	Proceed with further work. ATR not required.			25
Inspection should be done after:	after:			

- Completing stage II works.

  Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.

  In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

## Stage III check notes:

- Window grills must be fitted at the depth of ¼" from the wall. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided	THE COMMISSION CHECK
☐ Yes ☑ No	)	☐ Good ☐ Avg ☐ Poor	☐Yes ☐No	
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided	
□Yes □No —		Good Avg Poor	☐Yes ☐No	

N

S No

12

13

## Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Miscellaneous check – after finishing stage III	
Quality and workmanship of gate	☐Good ☐ Avg. ☐ Poor
Quality and workmanship of railings	Good Avg. Poor
Painting of gates & railings	☐Good ☐ Avg. ☐ Poor
Cleaning/painting of external cladding/texture	Good MAvg. Poor
Quality and workmanship of lawn	☐ Good ☐ Avg. ☐ Poor
Remarks:	
4	
	, income