

Quality Control Check Report. Stage: After Finishing Stage II (Villas)

Flat No	200	Other		Sl. No.	33016
Company	Nec CLP)	Project		Phase	-
Prepared by	V. Sanketh	Sign		Date	26/2/19
Project Manager	A. Suresh	Sign		Date	26/2/19
Previous stage report no.				Report filed and signed by PM	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Checked By MD on		MD Sign		For filling	<input type="checkbox"/> Yes <input type="checkbox"/> No

Recommendation:

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

Inspection should be done after:

- Completion of flooring, bathroom/utility tiles, doors & beading, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

Main door fixed with lock & stopper	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Granite soffit for main door required	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Granite soffit for main door provided	<input type="checkbox"/> Yes <input type="checkbox"/> No
Main door granite soffit workmanship	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor	Main door granite soffit edge polishing	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor

Tiling & granite work		Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA)												
S No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform
1	Toilet 1 G-Toi	✓	✓	✓	X	✓	X	✓	✓	✓	-	-	-	-
2	Toilet 2 M-Toi	✓	✓	✓	✓	✓	X	✓	✓	✓	-	-	-	-
3	Toilet 3 K-Toi	✓	✓	✓	✓	X	X	✓	✓	✓	-	-	-	-
4	Toilet 4	-	-	-	✓	X	X	-	✓	✓	-	-	-	-
5	Wash basin in dining area	-	-	-	-	-	-	-	-	-	-	-	-	-
6	Kitchen	✓	✓	✓	-	✓	X	-	-	✓	✓	✓	✓	-
7	Utility	✓	✓	✓	✓	✓	X	-	-	✓	✓	✓	✓	X
8	Portico													
9	Other													
Remarks														

Quality Control Check Report Stage: After Finishing Stage II (Villas)

S No	Room	Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA)												
		Color variation of floor tiles	Flooring workmanship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	General quality of painting & finishing	Door & frame painting quality	Door beading, luppam and painting quality.	Edge building	
1.	Bedroom 1 G.1B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
2.	Bedroom 2 M.1B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
3.	Bedroom 3 K.1B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
4.	Bedroom 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
5.	Drawing	✓	XX	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
6.	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
7.	Lobby 1 Lounge	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
8.	Lobby 2 <i>RuJa</i>	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
9.	Terrace/ balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
10.	Terrace-/balcony 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
11.	Head room	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
12.	Portico	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
13.	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
14.	Utility	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
15.	Other	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Remarks		<p>XXI Instead of full Tiles they laid cut-pieces Tiles in Drawing.</p> <p>XXII No. of skirting piece not provided in family lounge.</p>												

Quality Control Check Report Stage: After Finishing Stage II (Villas)

Miscellaneous check -- after finishing stage II

Quality and workmanship of portico tiles	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Quality and workmanship of flooring & setbacks	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Quality and workmanship of external cladding/ texture	<input type="checkbox"/> Good	<input checked="" type="checkbox"/> Avg.	<input type="checkbox"/> Poor
Remarks:	<i>note: Screws not fixed by villa external walls.</i>		