

Quality Control Check Report Stage: After Plumbing & Electrical (Villas)

Bungalow no.	87	Stage	I	SI. No.	34366
Company	AMM	Project	AVR Submohy	Phase	
Prepared by	S. JAMESH	Sign	[Signature]	Date	28/11/19
Project Manager	Zaki Hussain	Sign	[Signature]	Date	28/11/19
Previous stage report no.	34683	Report filed and signed by PM?			<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Additions & alterations sheet date	18/05/19	All pages signed by engineer & customer?			<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
Checked By MD on	[Signature]	MD Sign		For Filing	<input type="checkbox"/> Yes <input type="checkbox"/> No

Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
 Stop further work. Proceed with work after submitting ATR on QC report to QC team.
 Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
 Proceed with further work. ATR not required.
 Inspection should be done after:

- after clearing the bungalow,
- before starting painting, tiling & flooring.
- electrical conduit, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finished and signed. In case there are no additions and alterations prior to end, by PM to CR containing the same must be added.
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check

Notes:

1. Mark ✓ for correct or minor mistake which does not require correction
2. Mark X for minor mistake that requires minor correction.
3. Mark XXX for major mistake that requires correction by replacement or re-fixing.
4. Mark XXXX for major mistake that cannot be corrected.
5. Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance (+/-)
6. Location, height and spill level of electrical points must be checked as per measurements given in circular & plan. Tolerance (+/-)
7. Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
8. Water proofing must cover all pipes & check height above SHL.
9. Fasteners must be used as specified in circular. Specifically check fixing of PVC pipes.
10. Height of DB box must be 6" below false ceiling level or 12" below slab level.
11. In case of any changes in civil work, electrical work and plumbing work, a new drawing must be prepared at I/O and approved by MD.

Quality Control Check Report. Stage After Plumbing & Electrical (Villas)

S No	Room	Civil work near pipes in balcony & utility (✓ or X)	CPVC & PVC Check (✓ or X)	Electrical points check (✓ or X)	Water proofing check (✓ or X)	Proper use of fasteners check (✓ or X)	Placement of DB (✓ or X)	Placement of Generator chanceover (✓ or X)
1	Bedroom 1	M.B	✓	✓	✓	✓	✓	✓
2	Toilet 1	M.T	✓	✓	✓	✓	✓	✓
3	Bedroom 2	K.Q	✓	✓	✓	✓	✓	✓
4	Toilet 2	K.T	✓	✓	✓	✓	✓	✓
5	Bedroom 3		✓	✓	✓	✓	✓	✓
6	Toilet 3		✓	✓	✓	✓	✓	✓
7	Bedroom 4		✓	✓	✓	✓	✓	✓
8	Toilet 4		✓	✓	✓	✓	✓	✓
9	Drawing		✓	✓	✓	✓	✓	✓
10	Dining		✓	✓	✓	✓	✓	✓
11	Lobby 1		✓	✓	✓	✓	✓	✓
12	Lobby 2		✓	✓	✓	✓	✓	✓
13	Terrace-balcony-1		✓	✓	✓	✓	✓	✓
14	Terrace-balcony-2		✓	✓	✓	✓	✓	✓
15	Head room		✓	✓	✓	✓	✓	✓
16	Porcho		✓	✓	✓	✓	✓	✓
17	Kitchen		✓	✓	✓	✓	✓	✓
18	Utility	✓	✓	✓	✓	✓	✓	✓
19	Other		✓	✓	✓	✓	✓	✓

Remarks on additions & alteration sheet:

Signed by engineer:

Yes No

Signed by customer:

Yes No

Revised drawing required from HO

Yes No

Approved revised drawing attached

Yes No

Quality Control Check Report Stage: After Plumbing & Electrical (Villas)

Miscellaneous check

Depth of drainage line at compound wall specified : 16" Depth provided: 16"

Fasteners for external PVC/CPVC lines : or X Yes No

Setbacks properly leveled and compacted to 3" below proposed FFL? Yes No

Lawn area properly leveled and compacted to 9" below lawn FFL? Yes No

Electrical pipes for electric power supply & communication provided from compound wall? Yes No

Workmanship of drainage lines Good Avg. Poor

Painting provided? Yes No

Remarks: _____
