Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Flat No 91		Other		Sl. No.	27823
Company MNM)	Project	Mulgari how	Phase	} `
Prepared by P. Lo.,	P- Sai know	Sign	BC2,	Date	18/8/12
Project Manager	Kindonender Reddy	Sign	Kirkeni	Date	(8/8/12
Previous stage report no.		2742	Report filed and signed by PM	d by PM	MYes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	ATR on QC nd with work at only after mal	eport to QC team. Proces report to QC team. Processing ATR on cing corrections pointed ired.	eed only after recheck l QC report to QC team. I out in the QC report.	y QC. ATR not required.	

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

(polishing	1	
Good Avg Poor	Main door granite soffit edge	☐ Good ☐ Avg ☐ Poor	Main door granite soffit workmanship Good Avg Poor Main door granite so
□ Yes □ No _	Granite soffit for main door provided	☐ Yes ☐ No —	Granite soffit for main door required Yes No
		□Yes □No →	Main door fixed with lock & stopper Yes No

work

1

)

Finishing under granite

platform

S No

Room

Toilet 3 Toilet 2 Toilet 1

Toilet 4

Remarks

Other Portico

Utility

Kitchen

		_	-	2	Ī.		Т					-		1				
	Remarks	15.	14.	13.	12.	=	10.	9.	.∝	7.	6.	Ş	4.	\dot{n}	2.		S No	
	rks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony 2	Terrace/ balcony 1	Lolaby 2:	Lobby I Fill way	Dining	Drawing	Bedroom 4	Bedroom 3 GB	Bedroom 2 たら	Bedroom 1 MB	Room	Flooring & painting
			۲	7	1	l	1	<	ļ	<	<	<	1	<	<	<	Color variation of floor tiles	
			~	7	1	١	1	<	1	<	, <	<	9	<	5	7	Flooring workman ship & grouting	•
			۲	V		1)	_	1	<	5	5	1	<	<	7	Skirting size (3")	Rate
			V	7	1	١	1		1	<	5	5	1	<	<	<	Skirting workmanship	Rate the quality of (Good
			7	1	١	1	1	\ \	١	<	5	ς	1	<	<	5	Plastering above skirting	ty of (Go
			<	<	1	Ì	1	\ \		<	<	\	•	<	<	<	Plastering & finishing of walls	od ∨, Avg.
			<	7	\	1	1.	V	1	<	<	1	_	<	<	<	Crack filling	×
			1	\	1	1	•	١	ſ	>	1	}		1	1	1	Loft Finishing	Poor – nee
	-		·/:,	**	No.	1	ţ	1.	1	<	<	<	(7	<	<	General quality of painting & finishing	ds correct
			(1	1	1	1	<	1	}	`	<	١	<	ζ'	<	Door & frame painting quality	- needs correction XX, NA)
			١	1		1	1	<	1	١	١	<	١	/	\		Door beading, luppam and painting quality.	NA)
			X	4	K	1	١	3/7	١	<	/	<	-	<	<	<	Edge building	

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

Remarks:	Quality and workmanship of external cladding/ texture	Quality and workmanship of flooring & setbacks	Quality and workmanship of portico tiles	Miscellaneous check – after finishing stage ii
	Good Avg. Poor	Good Avg. Poor	Good Wavg. Poor	