

**Quality Control Check Report. Stage: After Finishing Stage II (Villas)**

Flat No	27	Other		Sl. No.	24627
Company	Agik	Project		Phase	
Prepared by	Shamshane	Sign	Shamshane	Date	20/08/19
Project Manager	Shamshane	Sign	Shamshane	Date	20/08/19
Previous stage report no.	229034	Report filed and signed by PM			<input type="checkbox"/> Yes <input type="checkbox"/> No
Checked By MD on		MD Sign		For filling	<input type="checkbox"/> Yes <input type="checkbox"/> No

**Recommendation:**

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

**Inspection should be done after:**

- Completion of flooring, bathroom, utility tiles, doors & bending, first coat of paint.
- Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

**Miscellaneous check:**

Main door fixed with lock & stopper	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
Granite soffit for main door required	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Granite soffit for main door provided	<input type="checkbox"/> Yes <input type="checkbox"/> No
Main door granite soffit workmanship	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor	Main door granite soffit edge polishing	<input type="checkbox"/> Good <input type="checkbox"/> Avg <input type="checkbox"/> Poor

**Quality Control Check Report**      **Stage: After Finish/In Stage II (Villa)**

Tiling & granite work		Rate the quality of (Good ✓, Avg. X, Poor - needs correction XX, NA)												
S No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform
1	Toilet 1 M.T.O.V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Toilet 2 C.T.O.V	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Toilet 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Toilet 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Wash basin/In dining area	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Porico	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	Other	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Remarks														

Quality Control Check Report      Stage After Finishing Stage II (Villas)

S No	Room	Rate the quality of (Good ✓, Avg X, Poor - needs correction XX, NA)										
		Color variation of floor tiles	Flooring workmanship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	General quality of painting & finishing	Door & frame painting quality	Door beading, luppam and painting quality.
1.	Bedroom 1 M. Bed	>	>	>	>	>	>	>	>	>	>	>
2.	Bedroom 2 G. Bed	>	>	>	X	>	>	>	>	>	>	>
3.	Bedroom-3.	-	-	-	-	-	-	-	-	-	-	>
4.	Bedroom-4.	-	-	-	-	-	-	-	-	-	-	>
5.	Drawing	>	>	>	>	>	>	>	>	>	>	>
6.	Dining	>	>	>	>	>	>	>	>	>	>	>
7.	Lobby 1.	>	>	>	>	>	>	>	>	>	>	>
8.	Lobby 2	>	>	>	>	>	>	>	>	>	>	>
9.	Terrace/balcony-1.	-	-	-	-	-	-	-	-	-	-	-
10.	Terrace/ balcony-2.	-	-	-	-	-	-	-	-	-	-	-
11.	Head room	>	>	>	>	>	>	>	>	>	>	>
12.	Porico	>	>	>	>	>	>	>	>	>	>	>
13.	Kitchen	>	>	>	>	>	>	>	>	>	>	>
14.	Utility	>	>	>	>	>	>	>	>	>	>	>
15.	Other	>	>	>	>	>	>	>	>	>	>	>
Remarks		In Bed etc of the tile underneath a hollow sound is coming.										

**Quality Control Check Report. Stage: After Finishing Stage II (Villas)**

Miscellaneous check ... after finishing stage II	
Quality and workmanship of portico ties	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor
Quality and workmanship of flooring & setbacks	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor
Quality and workmanship of external cladding: texture	<input type="checkbox"/> Good <input checked="" type="checkbox"/> Avg. <input type="checkbox"/> Poor
Remarks:	