Juality (
Control C	
Stage: After Finishing Stage II (V	
II (Villas)	

Flat No 28 Company Sovill Project Frepared by Company Sovill Sign Project Manager Report Manager Frequenced By MD on Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Stop further work. ATR not required.						
Seville Seville Seville Seville Tx Tx Tx Tx Tx Tx Tx T	Flat No	22	Other	The state of the s	SI. No.	34892
Corport Incorport to QC report to QC repor	Company	SOV LLP	Project	>0<	Phase	[X]
K. QUYShether. Sign Sign Date 11 12 Port no. 3 3 U. 11 Report filed and signed by PM Yes □ No. No	Prepared by		Sign	N. M.	Date	= 1 12 1 12
ort no. 3 3 14 Report filed and signed by PM Yes	Project Manager		Sign	Æ.	Date	11 12 119
MD Sign For filling ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report	no.	33411	Report filed and signe	ed by PM	√Yes □No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on		MD Sign		For filling	□Yes □No
menoring chould be done offer.	Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC re Proceed with work aft ner work only after mak ner work. ATR not requ	port to QC team. Proceser submitting ATR on ing corrections pointed ired.	eed only after recheck l QC report to QC team l out in the QC report.	by QC. ATR not required.	

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door in this stage.

Miscellaneous check:

	Main door granite soffit workmanship Good Avg Poor Main door granite so	Granite soffit for main door required Yes No	Main door fixed with lock & stopper ☐ Yes ☐ No
	Good Avg Poor	Yes No	Yes No
polishing	Main door granite soffit edge	in door provided	
	Good Avg Poor	√Yes □No	

	Tiling & granite work			Rate th	e quality	of (Goo	d , Aı	ge ×, P	oor – ne	eds corre	Rate the quality of (Good •, Avg. ×, Poor – needs correction ××, NA)	X, NA)		
S No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope		Granite platform height
		7	<	<	5	<	1	1		1		grant)
2	Toilet 2 C. T	<	<	<	<	1	<	, ,		/	ç- 			gravo
w	Foilet 3	1)		9	Carpon	-)	Ç.	-	(and)		Î
4	Toilet 4		J	1	\	1	1	١		9	1	1		Ì
5	Wash basin in dining area	Ì	Ì	١	1	1	N.	Ŷ	1	1	Ì	3		į
6	Kitchen	<	<	(<	<	<	1	*	<	<	<		<
7	Utility	<	<	<	<	<	1			<	١			S-4
8	Portico												T	
9	Other												T	
Rem	Remarks													
						v								

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

	Remarks:	Quality and workmanship of external cladding/texture	Onolity and an I is a mooning & Seluacks	Quality and workmanship of flooring & cothools	Quality and workmanship of portico tiles	Miscellaneous check – after finishing stage II
	[Good JAva Poor	Good VAvg. Poor	MANS: [] 1 001	Good Wave Door	