7	100000
	Quality (
	Control
	Control Check Repot.
	Repot.
	Stage:
	After
	ter Finishing Stage III (/
	Stage II
	Stage: After Finishing Stage III (Apartmen
2000	its)

Flat No	(5000)	Other	1	Sl. No.	29673
Company	VISTA HOMES	Project	VISTA HOMES	Phase	l
Prepared by	M Tga Svidher Sign	Sign	4	Date	81/20/91
Project Manager	TMadhu	Sign	Ten Ly	Date	16/03/18
Previous stage report no.	no.	29455	Report filed and signed by PM	d by PM	NYes □No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Procter submitting ATR on ing corrections pointedired.		by QC. ATR not required.	

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

Stage III check notes:

- Window grills must be fitted at the depth of ¼" from the wall. Switchboards must be fitted to plum.
- Cover junction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

Company of the control of the contro	Video door phone to be provided		Modular kitchen workman ship	Modular kitchen to be provided	Transcondition on one.
	No □No		☐ Good ☐ Avg ☐ Poor Modular kitchen granite	Nes □No	
	Video door phone provided	workman ship & finishing	Modular kitchen granite & dado	Modular kitchen provided	
	NYes No		Good Avg Poor	☐Yes ☑No	

Rem	15	14	13	12	1	10	9	∞	7	6	5	4	ယ	IJ	_	S No	
Remarks	Other	Other	Toilet 3	Toilet 2 (CT)	Toilet 1 (MT)	Kitchen	-Utility / balcony 3	Utility +balcomy-2-	Lility → balcony 1	Lebby-1-	Dining ·	Drawing	Bedroom-3	Bedroom 2 (以6)	Bedroom 1 (MB)	Room	
				<	-			(1	<		<	<	Door, door knob & door stopper fitting	
٥.			{	<				1	-	1	1	<	-	<	<	Door, door knob & door stopper cleaning	, -
			[<	<	<	1	ſ	1	-	\	<	Į	<	<	Window grills quality	Rate the quality of (Good
	0.000000		\	~	イ	<	-		-	ſ	1	<	1	く	<	Window grills fitting & finishing	quality of
			1	<	<	<			1		1	<		<	<	Windows quality	(Good ~
				<	<	<		\		1		<		V	<	Window fitting & finishing	, Avg. X,
			į		1	-	1	-	<	-	(1		-	J	Balcony railing quality & finishing	(, Poor –
				- [1	-	1	I	<	1	-	(1	French door quality & fitting	needs cc
				<	<	١		<	\		ĺ	Ţ		-		CP jali quality and fitting	needs correction XX, NA)
			1	<	<	<	1	<	<	1	<	<		<	<	Edge building	XX, I
			I	<	<	<		<	<		<	<		<u> </u>		Switch boards fitting & covering with plastic covers	VA)
			1	×	×	7	1	<	<		<	5]	<	<	Junction box covers painting	