

**Quality Control Check Report. Stage: After Finishing Stage II (Apartments)**

Flat No	D-602	Other		Sl. No.	28592
Company	BNC	Project	ME4	Phase	II
Prepared by	M. Tejaswini	Sign	AT	Date	06/12/17
Project Manager	Subba Reddy.	Sign		Date	06/12/17
Previous stage report no.	28195	Report filed and signed by PM		Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
Checked By MD on		MD Sign		For filling	Yes <input type="checkbox"/> No <input type="checkbox"/>

**Recommendation:**

- Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.
- Stop further work. Proceed with work after submitting ATR on QC report to QC team.
- Proceed with further work only after making corrections pointed out in the QC report. ATR not required.
- Proceed with further work. ATR not required.

**Inspection should be done after:**

- Completion of flooring, bathroom/utility tiles, first coat of paint.
- Completion of doors, windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

**Miscellaneous check:**

Main door fixed with lock & stopper	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Stopper not fixed.	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Granite soffit for balcony required	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Granite soffit for balcony provided	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
Balcony granite soffit workmanship	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>	Balcony granite soffit edge polishing	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>
Granite soffit for main door required	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	Granite soffit for main door provided	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Main door granite soffit workmanship	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>	Main door granite soffit edge polishing	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>
False ceiling to be provided ?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	False ceiling workmanship	Good <input type="checkbox"/> Avg <input checked="" type="checkbox"/> Poor <input type="checkbox"/>

Quality Control Check Report      Stage: After Finishing Stage II (Apartments)

Tiling & granite work		Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA)												
S No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform
1	Toilet 1 (MT)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Toilet 2 (CT)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Toilet 3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Toilet 4	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Wash basin in dining-area	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Other													
9	Other													
Remarks														

Quality Control Check Report      Stage: After Finishing Stage II (Apartments)

S No	Room	Rate the quality of (Good ✓, Avg. X, Poor – needs correction XX, NA)										
		Color variation of floor tiles	Flooring workmanship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	General quality of painting & finishing	Door & frame painting quality	Door beading, luppam and painting quality.
1	Bedroom 1 (MB)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Bedroom 2 (KB)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
3	Bedroom 3 (WB)	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
4	Drawing	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
5	Dining	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
6	Lobby 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
7	Utility / balcony 1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
8	Utility / balcony 2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
9	Utility / balcony-3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
10	Kitchen	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
11	Other											
12	Other											
Remarks												